Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 2001

**TO:** All Ford and Lincoln Mercury Dealers

**SUBJECT:** Special Field Action 01L06: All 2001 Model Year Explorer and Mountaineer Vehicles Equipped With 5.0L Engine – Warranty Guide Update

| | |
|---|---|
| OASIS: | No, a Warranty Guide Update will be mailed to owners/dealers. |
| OWNER LIST: | No |
| PROGRAM TERMS: | This program will be in effect until May 31, 2002, regardless of mileage. |

## VEHICLES COVERED BY THIS ACTION

All 2001 model year Explorer and Mountaineer vehicles equipped with a 5.0L engine built at Louisville and St. Louis Assembly Plants from the beginning of production to the end of production.

## REASON FOR PROGRAM

These vehicles were shipped with Warranty Guides that do not contain the California 7/70 emissions part warranty list for vehicles equipped with a 5.0L engine. California regulations require that each manufacturer furnish a list of the 7/70 warranted parts with each new vehicle.

## SERVICE ACTION

**In-stock units:**
Prior to delivery, dealers are to insert the Warranty Guide Update into the Warranty Guide, between pages 18 & 19 of all 2001 model year Explorer and Mountaineer vehicles, equipped with 5.0L engines.

**Sold units:**
Owners of 2001 model year Explorer and Mountaineer vehicles equipped with a 5.0L engine will be mailed a notification letter, which contains a Warranty Guide Update. They will be asked to place the update in their Warranty Guide, between pages 18 & 19, located in the glove compartment of their vehicle.

© Copyright 2001 Ford Motor Company

**ATTACHMENTS**

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter
Warranty Guide Update

**QUESTIONS?**

Claims Information: ……..1-800-423-8851

Other (Dealer Only) Program Questions: ……..1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

**Special Field Action 01L06**
All 2001 Model Year Explorer and Mountaineer Vehicles Equipped with 5.0L Engine
Warranty Guide Update

## OASIS

OASIS will not be activated for this program.

## PLEASE NOTE

Correct all vehicles in stock before delivery.

## DEALER-OWNER CONTACT

An owner list will not be provided for this program.

## CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

© Copyright 2001 Ford Motor Company

**Special Field Action 01L06**
All 2001 Model Year Explorer and Mountaineer Vehicles Equipped with 5.0L Engine
Warranty Guide Update

**LABOR ALLOWANCES**

| Description | Labor Operation | Labor Time |
|---|---|---|
| Install Warranty Guide Update<br>(Dealer Stock Units Only) | 01L06B | 0.2 Hours |

© Copyright 2001 Ford Motor Company

**Special Field Action 01L06**
All 2001 Model Year Explorer and Mountaineer Vehicles Equipped with 5.0L Engine
Warranty Guide Update

## WARRANTY GUIDE UPDATE AFFECTED VEHICLES

All 2001 model year Explorer and Mountaineer vehicles equipped with a 5.0L engine, built at Louisville and St. Louis Assembly Plants from beginning of production to the end of production.

## SERVICE PROCEDURE

1. Obtain a copy of the Warranty Guide Update.

2. Locate the vehicle Warranty Guide (located in the glove compartment).

3. Place a copy of the Warranty Guide update in the Warranty Guide between pages 18 & 19.

**PLEASE NOTE:**
This procedure is for dealer stock units only. Owners of vehicles previously delivered will receive a copy of the Warranty Guide Update with their notification letter.

© Copyright 2001 Ford Motor Company