Related Newsletter Articles

02T07 Hose Clamp Seed Stock

04/01/2002

Dealers with involved vehicles were allocated seed stock the week of 3/19. The shipments went out as an interim order under DOR/COR # 50277. The earlier published service part # N808860-S is obsolete, the new part # is N808860-S1. A bulletin supplement was issued on 3/25/02 to reflect the new part numbers.

Please alert your Parts Department to watch for the hose clamp(s).

Copyright © 2002 Ford Motor Company
Published By: **Recall/Service Programs Department**
Ford Customer Service Division