At Ford Motor Company, we work hard to build every inch of your vehicle with care. The engine, in particular, requires just the right combination of elements to keep it running smoothly, year after year.

Recently, it has come to our attention that the coolant in your engine may have been improperly mixed. If not corrected, an improper coolant mixture could do damage to the engine over a period of time.

An extremely limited number of vehicles are affected by this issue. However, if you are one of the owners to receive this letter, we have determined that *the coolant in your engine should be tested without delay.*

WHAT FORD WILL DO FOR YOU

Rest assured, Ford has you covered. At no cost to you, we are providing repair and inspection coverage to owners of affected vehicles. When you arrive for service, the dealership will test your coolant mixture and adjust its levels as necessary. Your engine will also be topped off with coolant and thoroughly inspected to ensure that it is in excellent condition.

Because time plays a key role in whether or not the mixture has an effect on your engine, we encourage you to contact your dealership as soon as possible. However, the program will be in place until February 28, 2002, regardless of mileage.

WHAT WE ARE ASKING YOU TO DO

Please call your dealership without delay to schedule a service appointment. The dealer will need your Vehicle Identification Number and the program number (both located at the top of this letter).

If you have trouble finding a service location, you can access **www.dealerconnection.com** to locate the dealership nearest you.

HOW LONG WILL REPAIRS TAKE?

The time needed for this repair is usually less than one half day. However, due to service scheduling issues, your dealership may need your vehicle for a longer period of time.

ANY QUESTIONS?

If you have any questions or concerns, please contact the Ford Motor Company Customer Relationship Center at 1-866-436-7332 or 1-800-232-5952 (TDD for persons with hearing impairments). Office hours are 8 a.m. to 11 p.m. Monday through Friday and 8 a.m. to 6 p.m. Saturday (Eastern Standard Time).

QUALITY CARE IS THERE FOR YOU

At Ford Motor Company, each vehicle is crafted with care. When a rare oversight occurs, we take equal care in providing you with superior service to ensure that your vehicle regains its peak performance level.

We apologize for any inconvenience caused by this program, and we would like to encourage you to contact your dealership right away. The ideal engine requires just the right mixture of elements, and Ford Motor Company is here to provide you with that dependable combination.

At Ford Motor Company, we work hard to build every inch of your vehicle with care. The engine, in particular, requires just the right combination of elements to keep it running smoothly, year after year.

Recently, it has come to our attention that the coolant in your engine may have been improperly mixed. If not corrected, an improper coolant mixture could do damage to the engine over a period of time.

An extremely limited number of vehicles are affected by this issue. However, if you are one of the owners to receive this letter, we have determined that *the coolant in your engine should be tested without delay.*

WHAT FORD WILL DO FOR YOU

Rest assured, Ford has you covered. At no cost to you, we are providing repair and inspection coverage to owners of affected vehicles. When you arrive for service, the dealership will test your coolant mixture and adjust its levels as necessary. Your engine will also be topped off with coolant and thoroughly inspected to ensure that it is in excellent condition.

Because time plays a key role in whether or not the mixture has an effect on your engine, we encourage you to contact your dealership as soon as possible. However, the program will be in place until February 28, 2002, regardless of mileage.

WHAT WE ARE ASKING YOU TO DO

Please call your dealership without delay to schedule a service appointment. The dealer will need your Vehicle Identification Number and the program number (both located at the top of this letter).

If you have trouble finding a service location, you can access **www.dealerconnection.com** to locate the dealership nearest you.

HOW LONG WILL REPAIRS TAKE?

The time needed for this repair is usually less than one half day. However, due to service scheduling issues, your dealership may need your vehicle for a longer period of time.

ANY QUESTIONS?

If you have any questions or concerns, please contact the Ford Motor Company Customer Relationship Center at 1-866-436-7332 or 1-800-232-5952 (TDD for persons with hearing impairments). Office hours are 8 a.m. to 11 p.m. Monday through Friday and 8 a.m. to 6 p.m. Saturday (Eastern Standard Time).

QUALITY CARE IS THERE FOR YOU

At Ford Motor Company, each vehicle is crafted with care. When a rare oversight occurs, we take equal care in providing you with superior service to ensure that your vehicle regains its peak performance level.

We apologize for any inconvenience caused by this program, and we would like to encourage you to contact your dealership right away. The ideal engine requires just the right mixture of elements, and Ford Motor Company is here to provide you with that dependable combination.

THE Park Concept, Design and Electronic Production

Ad No. N/A

Description:	Coolant Flyers - Taurus		
JWT Job No.:	FHB-GEN-313086	Art Director:	B. Smith
Park Job No.:	FCAR-04285	Writer:	K. Jones
Park Producer:	tb	Designer:	T. Briggs
Colors -	CMYK	Account:	D. Blomquist
Live -	N/A	Production:	B. Hart
Trim -	11.25" x 16.375"	Traffic:	J. Summers
Bleed -	11.5" x 16.625"	Art Admin:	N/A
DPI@Full Size -	N/A		
Photographer:	N/A	Engraver:	N/A
Retoucher:	N/A	Filed:	CRM/Job#/TaurusCoolant

Park Project Mgr.: A. Ayrault
8/23/01 REV.4

Proof 4 9/6/01
Galley #1

Output size - 85%

THE Park Concept, Design and Electronic Production

Ad No. N/A

Description: Coolant Flyers - Taurus
JWT Job No.: FHB-GEN-313086
Park Job No.: FCAR-04285
Park Producer: tb
Colors - CMYK
Live - N/A
Trim - 11.25" x 16.375"
Bleed - 11.5" x 16.625"
DPI@Full Size - N/A
Photographer: N/A
Retoucher: N/A

Art Director: B. Smith
Writer: K. Jones
Designer: T. Briggs
Account: D. Blomquist
Production: B. Hart
Traffic: J. Summers
Art Admin: N/A

Engraver: N/A
Filed: CRM/Job#/TaurusCoolant

Park Project Mgr.: A. Ayrault
8/23/01 REV.4

Proof 4 9/6/01
Galley #1

Output size - 85%

just the right mixture of elements.

Ford Motor Company
P.O. Box 1904
Dearborn, MI 48121-1904

PRESORTED
FIRST-CLASS MAIL
U.S. POSTAGE
PAID
SOUTHGATE, MI
PERMIT NO. 227

just the right mixture of elements.

Ford Motor Company
P.O. Box 1904
Dearborn, MI 48121-1904

PRESORTED
FIRST-CLASS MAIL
U.S. POSTAGE
PAID
SOUTHGATE, MI
PERMIT NO. 227

PLEASE READ CAREFULLY.

Important information about your Ford Taurus enclosed.

IMPORTANT VEHICLE NOTICE

Your engine requires ...

PLEASE READ CAREFULLY.
Important information about your Ford Taurus enclosed.

IMPORTANT VEHICLE NOTICE

Your engine requires ...