Ford Motor Company

A.R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: **Emission Recall 00E10-S1:** Certain 2000 Model Year Taurus Flex Fuel Vehicles – Fuel Delivery Module Replacement

Reference: Emission Recall 00E10: Certain 2000 Model Year Taurus Flex Fuel Vehicles – Fuel Delivery Module Replacement, dated August 2000

OASIS : Yes
OWNER LIST: Yes
OWNER LETTERS: Yes
PROGRAM TERMS: No Time or Mileage Limit

REASON FOR SUPPLEMENTAL INFORMATION

Attachment III (Technical Instructions) included with the original announcement of Emission Recall 00E10, did not contain specific instructions regarding the preparation and use of the Authorized Modifications Label (FPS-8262). Additionally, a statement that reminds dealers to provide the Emission Recall - Proof of Correction certificate to California and Massachusetts vehicle owners, was also omitted.

A revised and corrected copy of Attachment III (Technical Instructions), which incorporates the necessary information, is included in this announcement of Emission Recall 00E10-S1.

AFFECTED VEHICLES

Certain 2000 model year Taurus Flex Fuel vehicles built at the Atlanta Assembly plant from July 26, 1999 through July 20, 2000.

Certain 2000 model year Taurus Flex Fuel vehicles built at the Chicago Assembly plant from June 2, 1999 through July 20, 2000.

As 87% of the affected vehicles are fleet vehicles, we have worked with the major fleet accounts to determine the dealers that they will be directing these repairs to or purchasing the parts from to complete the repairs. This resulted in the identification of approximately 37,000 vehicles for which we will be shipping replacement pumps directly to dealers selected by the fleets. These major fleet accounts will be contacting these dealers directly regarding their pump replacement needs.

REASON FOR RECALL

Contamination and/or mechanical failure of internal components within the fuel delivery module may lead to a no-start or stall condition in affected vehicles.

SERVICE ACTION

Dealers are directed to replace the fuel delivery module.

ATTACHMENTS

Attachment I:	Administrative Information
Attachment II:	Labor Allowances and Parts Ordering Information
Attachment III:	Technical Information
Customer Notification Letter	Federal Locations
Customer Notification Letter	CA Certified Vehicles, Including MA Owners

QUESTIONS?

Claims Information:	1-800-423-8851
Other Recall (Dealers Only) Questions:	1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Emission Recall 00E10: Certain 2000 Model Year Taurus Flex Fuel Vehicles – Fuel Delivery Module Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on the VIN list in the Ford Dealer Consolidated Communicator (FDCC) and other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

- Immediately contact any affected owner whose name is not on the list.
- Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if:

- an owner cannot be contacted.
- an owner does not make a service date.

CLAIMS SUBMISSION

Enter claims using DWE. See ACESII manual.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for "Parts Retention and Return Procedures".

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the owner letter (or after the date of the owner letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Ford will pay for rental vehicle except for fuel, which will be at the owner's expense. Rentals should be provided only while the vehicle is at the dealership for the Fuel Delivery Module replacement. Follow Extended Service Plan (ESP) guidelines for rental dollar amounts. Enter the word "RENTAL" plus the number of days the vehicle was used in the Miscellaneous Expense area of the recall claim.

Emission Recall 00E10: Certain 2000 Model Year Taurus Flex Fuel Vehicles – Fuel Delivery Module Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Fuel Delivery Module	00E10B	1.1 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Parts are being direct shipped for those dealers identified by the North American Fleet Service Department.

As 87% of the affected vehicles are fleet vehicles, we have worked with the major fleet accounts to determine the dealers that they will be directing these repairs to or purchasing the parts from to complete the repairs. This resulted in the identification of approximately 37,000 vehicles for which we will be shipping replacement pumps directly to dealers selected by the fleets. These major fleet accounts will be contacting these dealers directly regarding their pump replacement needs.

These dealers will receive notification via DOES II and additional notifications for each weekly stock order shipped. Any dealer that requires a module to repair a FFV may obtain one by calling the recall hotline and supplying the appropriate vehicle identification number.

All order Types	First 90 days after launch	Call 1-800-325-5621

Part Number	Description	Quantity
YF1Z-9H307-EE	Kit, Fuel Delivery Module	1
FPS-8262	Authorized Modification Label	1

DOR/COR number 50171 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621).

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

October 2000

Emissions Recall 00E10 – Owners in Federal Locations

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and we also value our commitment to vehicle quality and the environment. We are therefore voluntarily recalling certain 2000 model year Taurus Flexible Fuel Vehicles (FFV) to replace a fuel delivery module.

What the emissions concern is…	Contamination and/or mechanical failure of internal components within the fuel delivery module may lead to a no-start or stall condition in affected vehicles.
What Ford and your Ford dealer will do to resolve the emissions concern…	At no cost to you, your dealer will replace the fuel delivery module according to the instructions provided by Ford.
How long will it take?	The time needed to repair your Taurus is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.
What we are asking you to do…	Call your dealer without delay. Ask for a service date for Emissions Recall 00E10 and if parts are in stock. If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within 7 days after the order is placed. When you bring your Taurus in, show your dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.
If you've already paid for this service…	If you paid to have this service done before the date of this letter, Ford Motor Company is offering a full refund. For the refund, please give your paid original receipt to your Ford dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

If you have changed your address or sold your Taurus, please fill out the enclosed prepaid postcard and mail it to us.

If the repair offered by this recall is not made promptly and without charge…

If you have trouble getting your vehicle repaired promptly and without charge, talk to the dealer service manager. You may also contact the Ford Customer Relationship Center by calling the following toll free phone number or by writing to the Ford Customer Relationship Center, P.O. Box 6248, Dearborn, Michigan 48121.

CALL: (800) 392-3673 or
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: 8:00 AM – 11:00 PM (Monday-Friday) ET
9:00 AM - 6:00 PM (Saturday) ET.

You may also contact us through the internet at www.ownerconnection.com. Our current response time to internet inquiries is approximately three business days.

Please have your vehicle serviced promptly to maintain full emission warranty coverage.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide Ford dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

Ford is conducting this action as part of our ongoing efforts to exceed owner expectations and maintain consumer confidence in our products. We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention in this important matter. And once again, we thank you for choosing the Ford Taurus.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

October 2000

Emissions Recall 00E10 – Owners of CA Certified Vehicles, Including MA Owners

Mr. John Sample
123 Main Street
Anywhere, CA or MA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and we also value our commitment to vehicle quality and the environment. We are therefore voluntarily recalling certain 2000 model year Taurus Flexible Fuel Vehicles (FFV) to replace a fuel delivery module. Your vehicle may be releasing air pollutants that exceed California Emissions Standards.

What the emissions concern is…	Contamination and/or mechanical failure of internal components within the fuel delivery module may lead to a no-start or stall condition in affected vehicles.
What Ford and your Ford dealer will do to resolve the emissions concern…	At no cost to you, your dealer will replace the fuel delivery module according to the instructions provided by Ford.
How long will it take?	The time needed to repair your Taurus is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.
What we are asking you to do…	Call your dealer without delay. Ask for a service date for Emissions Recall 00E10 and if parts are in stock. If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within 7 days after the order is placed. When you bring your Taurus in, show your dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.
If you've already paid for this service…	If you paid to have this service done before the date of this letter, Ford Motor Company is offering a full refund. For the refund, please give your paid original receipt to your Ford dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If the repair offered by this recall is not made promptly and without charge…

If you have trouble getting your vehicle repaired promptly and without charge, talk to the dealer service manager. You may also contact the Ford Customer Relationship Center by calling the following toll free phone number or by writing to the Ford Customer Relationship Center, P.O. Box 6248, Dearborn, Michigan 48121.

CALL: (800) 392-3673 or
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: 8:00 AM – 11:00 PM (Monday-Friday) ET
9:00 AM - 6:00 PM (Saturday) ET.

You may also contact us through the internet at www.ownerconnection.com. Our current response time to internet inquiries is approximately three business days.

Vehicles registered in California or Massachusetts…

The State of California and the Commonwealth of Massachusetts require the completion of emissions recall repairs prior to vehicle registration renewal. Your Taurus is subject to these requirements.

When your dealer completes this recall repair, you will receive a Vehicle Emission Recall Proof of Correction certificate. **Please make sure that you receive a certificate from your dealer and that you have it with you when you renew your vehicle registration.**

It is also important for you to know that the certificate should be returned to the Department of Motor Vehicles (DMV) only if it is requested by the DMV. Otherwise, this certificate is to be held by you for your records.

In order to ensure your full protection under emissions warranty provisions and to avoid any inconvenience when renewing your registration, it is recommended that you have your vehicle serviced as soon as possible. Failure to do so could be determined as lack of proper maintenance of your vehicle.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide Ford dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

Ford is conducting this action as part of our ongoing efforts to exceed owner expectations and maintain consumer confidence in our products. We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention in this important matter. And once again, we thank you for choosing the Ford Taurus.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs