Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

March 2001

TO: All Ford Dealers

SUBJECT: Owner Notification Program 01B65: Certain 2001 Model Year F-Super Duty Motorhome Chassis (Model F-53) – Front Wheel Bearing Inspection

OASIS : Yes
OWNER LIST: Yes
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until February 28, 2002.

AFFECTED VEHICLES

Certain 2001 model year F-Super Duty motorhome chassis (Model F-53) built at the Detroit Chassis Plant (DCP) from August 31, 2000 through October 27, 2000.

REASON FOR PROGRAM

In some of the affected vehicles, the inner front wheel bearing may not have been properly lubricated.

SERVICE ACTION

Dealers will remove the front wheels and front hubs in order to inspect both inner wheel bearings for proper lubrication. If there is not enough lubrication, both the inner and outer wheel bearings will be replaced and new seals installed in the hub assembly.

.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……..……..1-800-423-8851
Other Program Questions:……1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Owner Notification Program 01B65:
Certain 2001 Model Year Motorhome Chassis (Model F-53) –
Wheel Bearing Inspection

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

Promptly correct all affected vehicles on your dealer Recall/ONP Involved Unit Listings available on QCDealer.Com. Also, correct other eligible vehicles, which are brought to your dealership during the Program Term.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII manual for refund information.

Program Code:	01B65
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hr.

Refer to ACESII manual for refund information.

RENTAL VEHICLE

Rental vehicle coverage is not provided under this program.

Owner Notification Program 01B65:
Certain 2001 Model Year Motorhome Chassis (Model F-53) –
Wheel Bearing Inspection

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect both front wheel assemblies for proper lubrication of inner bearing.	01B65A	0.9 Hours
Replace wheel bearings and seals in one wheel assembly (Includes Inspection of both wheels.)	01B65B	1.4 Hours
Replace wheel bearings and seals in both wheel assemblies (Includes inspection of both wheels.)	01B65C	1.8 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this program. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
TGAA-1201-A	Inner Wheel Bearing	1 bearing required per wheel
C3TZ-1216-A	Outer Wheel Bearing	1 bearing required per wheel
C9HZ-1190-A	Inner Wheel Seal	1 seal required per wheel
DOTZ-1195-B	Outer Wheel Seal/Gasket (Comes in a package of 4)	1 gasket required per wheel

ORDER INFORMATION

DOR/COR number 50222 identifies parts ordered for this campaign.

DEALER PRICE

For latest prices, check DOES II or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2001

01B65

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is providing a no-charge service, Program Number 01B65, to owners of certain 2001 model year F-Super Duty motorhome chassis (Model F-53) for the inspection of both front inner wheel bearings.

Reason For This Program

During assembly, the front inner wheel bearings on some motorhome chassis were not adequately lubricated. The reason for this program is to inspect the front wheel bearings on your vehicle to make sure that they are properly lubricated.

What *Ford Motor Company* and your dealer will do…

At no charge to you (parts and labor) your dealer will inspect both front inner wheel bearings on your vehicle. If the wheel bearings do not have proper lubrication, new wheel bearings and seals will be installed.

This program will be in effect until February 28, 2002 regardless of miles.

What we are asking you to do…

Call your dealer without delay. Provide the dealer with your Vehicle Identification Number (located at the beginning of this letter). Ask for a service date and whether parts are in stock for Owner Notification Program 01B65.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

How long will it take….

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

Refund

If you paid to have this service done before the date of this letter, Ford Motor Company is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please call the Motorhome Customer Assistance Center toll free at 1-800-444-3311 and one of our representatives will be happy to assist you.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs