Ford Motor Company

A.R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: **DEMONSTRATION / DELIVERY HOLD:** Owner Notification Program 00B52: Certain 2000 Model Year E-Series Vehicles – Axle Pivot Bracket Attachment For Left Axle

OASIS : Yes
OWNER LIST: Yes
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until September 30, 2001, regardless of mileage.

AFFECTED VEHICLES

Certain 2000 model year E-Series vehicles built at the Lorain Assembly Plant from July 25, 2000 through July 31, 2000.

REASON FOR PROGRAM

1) In nineteen (19) of the affected vehicles, the bracket, which holds the pivot end of the left axle, may not be properly riveted to the frame crossmember. Over time, the bracket may loosen which could cause a noise and wheel alignment concern.
2) In the remainder of the affected vehicles, bolts were used to attach the pivot bracket for the left axle. However, the bolts have been installed with the threaded end pointed upward toward the oil pan. When the vehicle is driven, the end of the bolt could potentially make contact and cause damage to the oil pan.

SERVICE ACTION

Before demonstrating or delivering any of the vehicles involved in this program, the dealer must perform the following:

1) **Affected Vehicles With Suspect Rivets (19 Vehicles):** Drill out the four (4) attaching rivets, install bolts with the threads of the bolt pointing downward, and torque nuts to specifications. (No inspection necessary) These 19 vehicles are identified by VIN number in Attachment III.
2) **Affected Vehicles With Inverted Bolts:** Inspect the two upper bolts on the bracket for proper installation. If bolts are not installed correctly, remove and discard the bolts. Then, install new bolts with the threads of the bolt pointing downward and torque nuts to specifications.

ATTACHMENTS

Attachment I: ……Administrative Information
Attachment II: ……Labor Allowances and Parts Ordering Information
Attachment III:……Technical Information
Customer Letter

QUESTIONS?

Claims Information: 1-800-423-8851
Other Program Questions: 1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

DEMONSTRATION / DELIVERY HOLD:
Owner Notification Program 00B52
Certain 2000 Model Year E-Series Vehicles
Axle Pivot Bracket Attachment For Left Axle

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

Promptly correct all affected vehicles on the enclosed list and other eligible vehicles which are brought to your dealership.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII manual for refund information.

Program Code:	00B52
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hr.

Refer to ACESII manual for refund information.

RENTAL CARS

Rental vehicles are not approved for this program.

DEMONSTRATION / DELIVERY HOLD:
Owner Notification Program 00B52
Certain 2000 Model Year E-Series Vehicles
Axle Pivot Bracket Attachment For Left Axle

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
INSPECT: Bolts installed properly.	00B52A	0.2 Hour
REPAIR: Remove inverted bolts and install new bolts (Includes Inspection).	00B52B	0.5 Hour
REPAIR: Drill out four (4) rivets and install bolts (Includes Inspection)	00B52C* *Only applies to the 19 VIN numbers listed in Attachment III	1.1 Hours

PARTS REQUIREMENTS

Parts Order Information

PARTS WILL BE DIRECT SHIPPED:

- **Do not order any parts for this program because they will be direct shipped to the dealers that have involved vehicles.**
- Dealers can expect to receive parts within 2 weeks
- Questions regarding the vehicles involved should be directed to the Recall Hotline at 1-800-325-5621.

DOR/COR number 50178 identifies parts ordered for this campaign.

Repair Involved	Part Number	Quantity
For the replacement of inverted bolt and nut. **(432 vehicles involved)**	**Bolt**: N811530-S100 (1 per bag) **Nut**: N802074-S2 (5 per bag)	1 or 2 bolts and nuts will be needed for each vehicle.
For rivets that have been drilled out **(19 vehicles involved)**	**Bolt**: 58675-S2 (1 per bag) **Washer**: 44879-S2 (10 per bag) **Nut**: 34989-S2 (5 per bag)	4 bolts, nuts, and washers will be needed for each vehicle.

If additional parts are needed, call the Recall Hotline at 1-800-325-5621. This ordering process will remain in effect until October 31, 2000.

DEMONSTRATION / DELIVERY HOLD:
Owner Notification Program 00B52
Certain 2000 Model Year E-Series Vehicles
Axle Pivot Bracket Attachment For Left Axle

DEALER PRICE

For latest prices, check or call your:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673

September 2000

00B52 Kit Code AA

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is providing a no-charge service, Program Number 00B52, to owners of certain 2000 Model year E-Series vehicles.

Reason For This Program…

The bracket which holds the pivot end of the left front axle is secured to the frame with rivets and/or bolts. On some of the vehicles, the end of the bolt may be too close to the engine oil pan. In some cases, the end of the bolt may contact and damage the engine oil pan.

What *Ford Motor Company* and your dealer will do…

The existing bolts will be removed and new bolts will be installed so that the threaded end of the bolt(s) points away from the engine oil pan. This will provide the required clearance and prevent damage to the oil pan.

This program will be in effect until September 30, 2001, regardless of mileage.

What we are asking you to do…

Call your dealer without delay. Provide the dealer with your Vehicle Identification Number (located at the beginning of this letter). Ask for a service date and whether parts are in stock for Owner Notification Program 00B52.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

How long will it take….

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday - Friday: 8am-11pm and Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to internet inquiries is three business days.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673

September 2000

00B52 Kit Code BB

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is providing a no-charge service, Program Number 00B52, to owners of certain 2000 Model year E-Series vehicles.

Reason For This Program…

The bracket which holds the pivot end of the left front axle is secured to the frame with rivets. On some vehicles, the rivets may not have been installed correctly. Over time, the bracket may loosen and cause a noise when driven over rough roads. A loose bracket may also cause wheel alignment changes, which could accelerate tire wear.

What *Ford Motor Company* and your dealer will do…

The existing rivets will be removed and replaced with appropriate bolts. This will prevent the bracket from loosening.

This program will be in effect until September 30, 2001, regardless of mileage.

What we are asking you to do…

Call your dealer without delay. Provide the dealer with your Vehicle Identification Number (located at the beginning of this letter). Ask for a service date and whether parts are in stock for Owner Notification Program 00B52.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

How long will it take….

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday - Friday: 8am-11pm and Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to internet inquiries is three business days.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs