BODY—FRAME MOUNTED FRONT BUMPER BRACKETS SERVICE KIT

Article No. 02-23-2

FORD: 1998-2002 RANGER

ISSUE

During front end repair due to collision damage to the front end, the front frame horn or the entire frame is being replaced when only the front bumper bracket is damaged on some vehicles. A new Service Kit has been made available to replace front bumper brackets only.

ACTION

Replace front bumper brackets, if necessary, during front end repair. Order Left side 3L5Z-17N775-BA or right side 3L5Z-17N775-AA repair kits as necessary. Refer to the procedure outlined on the Instruction Sheet in the Front Bumper Bracket Service Kit.

NOTE

THIS KIT IS FOR FRONT BUMPER BRACKET REPLACEMENT ONLY. IT IS DESIGNED FOR UNDAMAGED FRONT FRAME RAILS.

PART NUMBER	PART NAME
3L5Z-17N775-AA	Front Bumper Bracket Service Kit - Right Side
3L5Z-17N775-BA	Front Bumper Bracket Service Kit - Left Side

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 108000, 111000, 305000

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company