Ford Motor Company

Frank M. Ligon
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

August 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Field Service Action 02L10: Certain 2000 Model Year 4x2 Expedition and Navigator Vehicles – Supplemental Tire Information Label

OASIS: Yes
OWNER LIST: Yes – In-stock vehicles only.
PROGRAM TERMS: This program will be in effect until January 31, 2003, regardless of mileage.

VEHICLES COVERED BY THIS ACTION

Certain 2000 model year 4x2 Expedition and Navigator vehicles built at Michigan Truck Assembly plant from Job 1 through Job last.

NON-COMPLIANCE

During production, incorrect tire pressure information for the rear tires was placed on the Certification Label on all affected vehicles. Federal Motor Vehicle Safety Standard (FMVSS) No. 120 requires the correct tire pressure be labeled on the vehicle. Correct tire pressure information for the front and rear tires is:

- Front Tire Pressure 26 PSI (179 kPa)
- Rear Tire Pressure 33 PSI (228 kPa)

A supplemental label with correct tire inflation pressures will be mailed to owners of all affected vehicles. A cleaning swab and instructions for attaching the label is included with each label mailed to owners.

NOTE: Expedition and Navigator 4x4 vehicles are not affected because they have different tire size.

© Copyright 2002 Ford Motor Company

SERVICE ACTION

In-stock units: Prior to selling any of the affected vehicles, dealers must affix the supplemental label according to the instructions in Attachment III on all in-stock vehicles.

Sold units: Owners of the affected vehicles will be mailed a supplemental label with revised tire inflation pressure specifications. An instruction sheet will also be included to show the owner where the label should be placed. At no charge, owners may choose to have the dealer install the label.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: ……..1-800-423-8851
Other (Dealer Only) Program Questions: ……1-800-325-5621

Sincerely,

Frank M. Ligon

Frank M. Ligon
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

Field Service Action 02L10
Certain 2000 Model Year 4x2 Expedition and Navigator Vehicles
Supplemental Tire Information Label

OASIS

You must use OASIS to determine if a vehicle is eligible for this Field Service Action.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

An owner list will not be provided.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

© Copyright 2002 Ford Motor Company

Field Service Action 02L10
Certain 2000 Model Year 4x2 Expedition and Navigator Vehicles
Supplemental Tire Information Label

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect: Supplemental Tire Information Label has been installed by customer.	02L10A	0.2 Hours
Install the supplemental Vehicle Tire Information Label.	02L10B	0.2 Hours

PARTS REQUIREMENTS

Ordering Instructions for Additional Labels

Supplemental Tire Information Labels for this program are being sent directly to owners of the affected vehicles.

Additionally, dealers will receive a seed stock of Supplemental Tire Information Labels for customers who may arrive at your dealership without the label.

Additional labels may be ordered at no charge by calling the Special Service Support Center at 1-800-325-5621. Inform the operator you are calling in regard to Field Service Action 02L10. Be prepared to provide your name, address, dealer P & A code, and the number of labels you need.

© Copyright 2002 Ford Motor Company