Ford Motor Company

March 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 01S08: Certain 2000 and 2001 Model Year Taurus and Sable Vehicles with Power Adjustable Foot Pedals – Brake Lamp Switch Replacement

AFFECTED VEHICLES

- 2000 through 2001 Model Year Taurus and Sable vehicles equipped with Power Adjustable Foot Pedals and built at the Atlanta Assembly Plant from May 3, 1999 through August 14, 2000
- 2000 Model Year Taurus vehicles equipped with Power Adjustable Foot Pedals and built at the Chicago Assembly Plant from June 2, 1999 through August 4, 2000

SAFETY CONCERN

Grease used on the Power Adjustable Foot Pedal assembly may enter the brake lamp switch and contaminate the contacts. Over time, this contamination may cause a build-up of carbon on the contacts, and in some cases, a short. This could result in one or more of the following symptoms:

- Brake lights remain illuminated
- Shift Interlock disabled
- Speed Control disabled
- ABS Warning light illuminates (if equipped with ABS)
- Battery discharged

A smaller number of switches may also fail in the open position. This type of failure will result in inoperative brake lights and the inability to shift the vehicle out of park. Loss of brake lamp function could potentially increase the risk of an accident.

SERVICE ACTION

On all affected vehicles, the dealer is to wipe excess grease from the Power Adjustable Foot Pedal assembly, and install a new brake lamp switch.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: 1-800-423-8851
Other (Dealer Only) Recall Questions: 1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Safety Recall 01S08
Certain 2000 and 2001 Model Year Taurus and Sable Vehicles with
Power Adjustable Foot Pedals – Brake Lamp Switch Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Recall/ONP Involved Unit Listings available on QCDealer.com. Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid brake lamp switch replacements made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental cars are not authorized for this program.

Safety Recall 01S08
Certain 2000 and 2001 Model Year Taurus and Sable Vehicles with
Power Adjustable Foot Pedals – Brake Lamp Switch Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Remove Excess Grease and Replace Brake Lamp Switch	01S08B	0.4 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock & Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
YF1Z-13480-AA	Brake Lamp Switch (Sedan)	1
YF1Z-13480-BA	Brake Lamp Switch (Wagon)	1

DOR/COR

DOR/COR number 50224 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621).

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2001

01S08

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2000 and 2001 model year Taurus and Sable vehicles built with Power Adjustable Foot Pedals.

What the safety issue is …

Grease used on the adjustable pedal assembly may enter the brake lamp switch and contaminate the contacts. This may cause one or more of the following symptoms to occur:

- Brake lights stay illuminated or are inoperative
- Shift Interlock disabled (will be able to shift out of "PARK" position without depressing the brakes)
- Speed Control will not activate
- Cannot shift the vehicle out of "PARK"
- ABS Warning light illuminates (on vehicles with ABS)
- Battery Discharged

Loss of brake light function could potentially increase the risk of an accident.

What Ford Motor Company and your dealer will do ...

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners affected by this recall are requested to return their vehicle to their dealer for replacement of the brake lamp switch and to have excess grease wiped off of the adjustable pedal assembly.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do …

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 01S08.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've already paid for this service …

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager. If you still need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.


You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.

Quality Care service is there for you all year round.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs