ELECTRICAL—REVISED MECHANICAL HOOD LAMP SWITCH TO REPLACE OLD STYLE MERCURY HOOD LAMP SWITCH	Article No. 01-19-4

FORD: 1990-1995 ESCORT
1990-2000 CROWN VICTORIA
1991 TAURUS
1992-1995 E SERIES
1994 F-150, F-250, F-350
2000-2001 F-150, SUPER DUTY F SERIES
2001 EXCURSION

LINCOLN: 1888-1989 MARK VII
2000-2001 TOWN CAR
2002 BLACKWOOD

MERCURY: 1990-1995 GRAND MARQUIS, TRACER
1993-1998 VILLAGER

ISSUE

This article is to provide information on replacement hood lamp switches. The 14 degree Mercury style hood switches will no longer be available. Replacement 14 degree Mechanical switches will be available as a service replacement.

ACTION

For vehicles requiring hood lamp switch replacement, replace the 14 degree Mercury switch with new 14 degree Mechanical switch. Replace hood lamp switch per the appropriate model year Workshop Manual as needed.

Old Service Part Number	New Service Part Number
F3XY-15702-A E8LY-15702-A	YW1Z-15702-BA YW1Z-15702-BA

PART NUMBER	PART NAME
YW1Z-15702-BA	14 degree Mechanical Hood Lamp Switch

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 201000, 201200

Copyright © 2001 Ford Motor Company