Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

March 2002

TO: Certain TH!NK Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD: Safety Recall 02S35:
Certain 2002 Model Year TH!NK Neighbor Vehicles –
Brake Master Cylinder Pushrod Replacement

REF: DEMONSTRATION / DELIVERY HOLD: Notice Dated February 27, 2002

REF: Dealer Announcement dated May 10, 1999, Low Volume Programs

AFFECTED VEHICLES

Certain 2002 model year TH!NK Neighbor electric vehicles built prior to February 22, 2002.

SAFETY CONCERN

In some of the affected vehicles, contact between the brake pedal arm and the threaded portion of the brake master cylinder pushrod may cause the pushrod to bend or break during engagement of the brakes. If this condition occurs, the vehicle could experience a degradation or loss of brake function, potentially resulting in an accident. Parking brake function is not affected.

SERVICE ACTION

Before demonstrating or delivering any of the vehicles involved in this recall, the dealer must install a revised brake master cylinder pushrod. This must be done on all of the affected vehicles in dealer inventory, as well as vehicles that have been delivered to customers.

Until repairs are performed the following should be done on all affected vehicles: 1) shut off the service disconnect switch and 2) fully charge the batteries. Refer to Attachment III for proper service procedures.

Note: Do not, under any circumstances, allow the batteries to fully discharge. A completely discharged battery may require replacement.

Note: The vehicle should be fully charged when returned to the customer.

Note: Obtain the vehicle's GFCI charging cable when picking-up the vehicle. Return the charging cable when delivering the repaired vehicle to the customer.

© Copyright 2002 Ford Motor Company

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

TRANSPORTATION OF TH!NK NEIGHBOR

To perform this recall, pick-up and return of a customer's vehicle will be required. This is necessary due to operating parameters of the TH!NK Neighbor vehicle, and the nature of this service concern.

Under this program, Ford Motor Company will reimburse dealers a fee to pick-up and deliver a customer's vehicle. This is in addition to normal repair allowance stated in this bulletin (reference Attachment II).

If you choose not to provide repair service for your customer due to distance from your TH!NK dealership, you may arrange to have a Ford or Lincoln Mercury dealer more convenient to the customer perform the repair. You will be paid an allowance to locate a suitable repairing Ford or Lincoln Mercury dealer (reference Attachment II).

TH!NK Mobility is asking for your support and the cooperation of your sales and service teams to make this a positive experience for our TH!NK Neighbor customers, all of whom are new to the TH!NK Mobility family.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter(s)

QUESTIONS?

Claims Information:……..……..1-800-423-8851
Other (Dealer Only) Recall Questions:……..……..……1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

DEMONSTRATION / DELIVERY HOLD: Safety Recall 02S35
Certain 2002 TH!NK Neighbor Vehicles
Brake Master Cylinder Pushrod Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your attached Involved Unit Listing (list received by TH!NK dealers only). Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

A full allotment of parts, based on your TH!NK Neighbor inventory, will be direct shipped to your dealership the week of 03/11/02.

DEALER-OWNER CONTACT

Immediately contact any of your affected owners whose names are not on your attached Involved Unit Listing (list received by TH!NK dealers only) but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

Note: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

Note: If you are a TH!NK Mobility dealer, be sure to submit claims using the secondary P&A code established for you as a TH!NK Mobility dealer.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs applicable to this recall which were made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

The use of rental vehicles is not authorized for this program.

© Copyright 2002 Ford Motor Company

DEMONSTRATION / DELIVERY HOLD: Safety Recall 02S35
Certain 2002 TH!NK Neighbor Vehicles
Brake Master Cylinder Pushrod Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Repair (TH!NK and non-TH!NK Dealers)	02S35B	0.4 Hour
TH!NK Transportation (TH!NK and non-TH!NK Dealers)	Misc. Expense Code "TTRANS"	1.0 Hour
*Administrative Allowance for TH!NK Dealer to Locate Servicing Dealer (TH!NK Dealer Only)	*02S35E	*0.3 Hour
Administrative Allowance for Repair Claim Processing (Repairing Dealer Only)	Misc. Expense Code "ADMIN"	0.1 Hour

***Note**: The dealer must input the labor time (0.3 Hours) for this labor allowance.

- Under no circumstances will claiming of "02S35E" and "ADMIN" be allowed on the same claim.
- Only a TH!NK dealer may claim labor allowance "02S35E". Use of labor allowance "02S35E" does not close out the recall.
- Only the repairing dealer can claim labor operation "ADMIN".
- Labor operation "TTRANS" cannot be claimed with repair of a dealer in-stock unit.
- ACES II edits are in place to ensure claims comply with the conditions listed above.

Refer to the following Claiming Matrix for a listing of acceptable labor operation / miscellaneous expense combinations:

CLAIMING MATRIX

Description	TH!NK Dealer	Non-TH!NK Dealer
Repair In-Stock Unit	02S35B, ADMIN	N/A
Pick-Up, Repair and Return Customer (Delivered) Vehicle	02S35B, TTRANS, ADMIN	02S35B, TTRANS, ADMIN
Locate Non-TH!NK Dealer to Perform Repair	02S35E	N/A

© Copyright 2002 Ford Motor Company

PARTS REQUIREMENTS

STOCK VEHICLES:

Correct all vehicles in stock before delivery. **A full allotment of parts, based on your TH!NK Neighbor inventory, will be direct shipped to your dealership the week of 03/11/02.** If you require additional parts, contact the Low Volume Coordination Center at 1-800-248-0186. When calling this number, identify Safety Recall 02S35 and have the VIN of the dealer stock vehicle to be serviced.

CUSTOMER VEHICLES:

Parts will be direct shipped for this recall. To order parts, contact the Low Volume Coordination Center at 1-800-248-0186. When calling this number, identify Safety Recall 02S35 and have the VIN of the customer vehicle to be serviced.

Part Number	Description	Quantity
2E3Z-2143-AA	Brake Pushrod Asy	1 per Vehicle

ORDER INFORMATION

The DOR/COR for this program is **50276**. This number identifies parts ordered for this recall through the Low Volume Coordination Center at 1-800-248-0186.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”.

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2002 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2002

Safety Recall 02S35

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2002 TH!NK Neighbor electric vehicles.

We apologize for this situation and want to assure you, that with your assistance, we will correct this condition. Our commitment, together with TH!NK Mobility dealers, is to provide you with the highest level of service and support possible.

What the issue is …

In some of the affected vehicles, contact between the brake pedal arm and the threaded portion of the brake master cylinder pushrod may cause the pushrod to bend or break during engagement of the brakes. If this condition occurs, the vehicle could experience a degradation or loss of brake function, potentially resulting in an accident. Parking brake function is not affected.

What Ford Motor Company and your dealer will do ...

Ford Motor Company has instructed dealers to arrange to pick up your TH!NK Neighbor, repair your vehicle by installing a revised brake master cylinder pushrod and return it to you free of charge (vehicle transportation, parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What we are asking you to do …

If you do not already have a servicing dealer, please access www.thinkmobility.com for TH!NK dealer addresses and contact information. From the TH!NK Mobility homepage, choose "United States" from the drop down menu. Next, click on the "TH!NK neighbor" icon. Call your TH!NK Mobility dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 02S35. If your TH!NK dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

© Copyright 2002 Ford Motor Company

If your vehicle is a distance from your TH!NK dealer, where scheduling a repair is impractical, your TH!NK dealer can arrange for repairs to be performed at a suitable Ford or Lincoln Mercury dealer more convenient to you.

If you have already paid for this service …

If you paid to have this service done before the date of this letter, Ford is offering a refund. To receive the refund, please give your paid original receipt to your TH!NK dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this safety recall.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your TH!NK dealership's Service Manager for assistance. If you still have concerns, please contact TH!NK Mobility and one of our representatives will be happy to assist you:

Call (800) 252-4221

Office Hours (Eastern Time Zone)
Monday through Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Hearing impaired call (800) 232-5952 TDD for the hearing impaired.

If you are still having trouble getting your vehicle repaired and without charge, you may write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.

We pride ourselves on becoming the world's leading consumer company providing automotive products and services. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company