Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

February 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Emissions Recall 02E19: Certain 2001 Bi-Fuel CNG/LPG F-Series Vehicles Catalytic Converter Replacement

AFFECTED VEHICLES

Certain 2001 Bi-Fuel CNG/LPG F-Series Vehicles built at the Ontario Truck Plant from November 1, 2000 through February 5, 2001.

REASON FOR FIELD SERVICE ACTION

Certain 2001 5.4L Ford F-Series Bi-Fuel (CNG/LPG) Conversion vehicles were built with incorrect catalytic converter assemblies in four of the five locations in the exhaust system. **The total number of affected units is 46 trucks.**

SERVICE ACTION

For vehicles involved in this Emissions Recall, the dealer must replace the front four catalytic converters to resolve the issue. This must be done on all of the affected vehicles in your inventory as well as vehicles that have been delivered to customers.

PLEASE NOTE

Correct all vehicles in stock before delivery. Vehicles with incorrect catalytic converters may exceed exhaust emission standards. Sale of uncorrected vehicles to customers could lead to penalties under the Clean Air Act.

© Copyright 2002 Ford Motor Company

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Letter(s)

QUESTIONS?

Claims Information: ……1-800-423-8851
Other Field Service Action (Dealers Only) Questions: ……1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

EMISSIONS RECALL 02E19:
Certain 2001 Bi-Fuel CNG/LPG F-Series Vehicles
Catalytic Converter Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this Emissions Recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

DEALER-OWNER CONTACT

Note: There are only 46 units affected by this issue; most dealers will not have any involved units.

Immediately contact any affected owner whose name is not on the list but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

NOTE: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this field service action is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the owner letter (or after the date of the owner letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII manual for refund information.

RENTAL CARS

The use of rental vehicles is not authorized for this program.

© Copyright 2002 Ford Motor Company

EMISSIONS RECALL 02E19:
Certain 2001 Bi-Fuel CNG/LPG F-Series Vehicles
Catalytic Converter Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Catalytic Converter Assemblies	02E19B	2.0 hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS / ORDERING INFORMATION

Parts will not be direct shipped for this Field Service Action. Order your parts requirement through normal order processing channels as noted below:

All Order Types Effective immediately Normal order process

This program only involves 46 vehicles. Only order parts after confirming your dealership has an involved vehicle.

Part Number	Description	Quantity
YL3Z-5E212-GA	Engine Catalytic Converter Assembly, LH 4x2 units	1
YL3Z-5E212-GB	Engine Catalytic Converter Assembly, RH 4x2 units	1
YL3Z-5E212-HA	Engine Catalytic Converter Assembly, LH 4x4 units	1
YL3Z-5E212-HB	Engine Catalytic Converter Assembly, RH 4x4 units	1
FPS-8262	Authorized Modifications Label*	1

***** Label orders come in packages of 25.

© Copyright 2002 Ford Motor Company

EMISSIONS RECALL 02E19:
Certain 2001 Bi-Fuel CNG/LPG F-Series Vehicles
Catalytic Converter Replacement

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

REMOVED PARTS RETURN

Removed catalysts must be returned. Hold the removed catalysts until the claim is paid and the Parts Department receives WPRC "parts disposition instructions" on your daily Parts Advice Register (Overnight Messages). An FPS-700 Parts Disposition Tag will be issued to recall the removed catalysts. Return of removed catalysts with the FPS-700 tag attached must be shipped prepaid freight via United Parcel Service (UPS) to the address on the reverse side of the tag. Refer to the part return shipping procedure in Section 1 .0 of the Warranty and Policy manual. Direct questions on warranty parts returns to the WPRC at 1-800-416-9772.

ANY QUESTIONS ON THE HANDLING OF SPECIAL SITUATIONS REGARDING REMOVED CATALYSTS SHOULD BE RESOLVED WITH YOUR SERVICE ZONE MANAGER.

© Copyright 2002 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

February 2002

Emissions Recall 02E19

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and is committed to vehicle quality and the environment. Therefore, we are voluntarily recalling certain 2001 Bi-Fuel CNG/LPG F-Series trucks to correct an emission concern.

What is the emission concern?…

Some 2001 5.4L Ford F-Series Bi-Fuel (CNG/LPG) Conversion vehicles were built with incorrect catalytic converter assemblies.

What Ford Motor Company and your dealer will do...

Ford Motor Company will replace the four exhaust y-pipe mounted catalytic converter assemblies in your vehicle free of charge (parts and labor). A fifth catalytic converter on your vehicle is correct, therefore, it will not be replaced. Owners who are affected by this Emissions Recall are requested to return their vehicle to their dealer for this important service.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do…

Call your dealer without delay. Provide the dealer with your Vehicle Identification Number (located at the beginning of this letter). Ask for a service date and whether parts are in stock for Emission Recall 02E19. If you do not have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions. If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

© Copyright 2002 Ford Motor Company

If you've already paid for this service…

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this program.

If you have concerns….

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you.

CALL: (866) 436-7332 or
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday-Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Or you may contact us through the Internet …

www.ownerconnection.com

Please have your vehicle serviced promptly to maintain full emission warranty coverage.

Quality Care service is there for you all year round.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company