Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

March 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Emissions Recall 02E17: Supplement #1: Certain 1997 through 2000 Model Year Dedicated Compressed Natural Gas F-Series Trucks - Heater Hose to Fuel Rail Flex Line Inspection.

REFERENCE: Emissions Recall 02E17: Certain 1997 through 2000 Model Year Dedicated Compressed Natural Gas F-Series Trucks - Heater Hose to Fuel Rail Flex Line Inspection.

REF: Dealer Announcement dated May 10, 1999, Low Volume Programs

REASON FOR THIS SUPPLEMENT

The original Dealer letter had an incorrect part number listed in Attachment II. This Supplement corrects the kit part number in Attachment II for the 2000 MY application vehicles.

AFFECTED VEHICLES

Certain 1997 model year F-250 vehicles built at the Kansas City Assembly Plant from November 19, 1996 through November 17, 1997, and retrofitted at TDM Manhattan Modification Center.

Certain 1998 model year F-250 vehicles built at the Kansas City Assembly Plant from September 11, 1996 through August 25, 1998, and retrofitted at TDM Manhattan Modification Center.

Certain 1999 model year F-250 vehicles built at the Kansas City Assembly Plant from April 16, 1998 through August 18, 1999, and retrofitted at TDM Manhattan Modification Center.

Certain 2000 model year F-150 vehicles built at the Kansas City Assembly Plant from October 5, 1999 through August 1, 2000, and retrofitted at TDM Manhattan Modification Center.

REASON FOR THIS RECALL

In some of the affected vehicles the fuel rail flex line may have chafed against the supply heater hose which runs from the engine to the heater core, and against the return heater hose which runs from the heater core to the engine. This contact by the heater hose on the fuel rail flex line has the potential to cause a small abrasion on the fuel rail that could eventually result in a gaseous fuel leak.

© Copyright 2002 Ford Motor Company

SERVICE ACTION

Before demonstrating or delivering any of the vehicles involved in this Emissions Recall, the dealer must inspect the fuel rail flex line for evidence of chafing and, if necessary, replace the fuel rail and related components. This must be done on all of the affected vehicles in your inventory as well as vehicles that have been delivered to customers.

NOTE: The State of California requires the completion of emission recall repairs prior to vehicle registration renewal. For vehicles registered in California, please provide the owner with a Vehicle Emission Recall Proof of Correction certificate after the repair has been performed. (These certificates may be obtained by contacting your regional office.)

LOW VOLUME PROGRAM

This recall is being processed as a Low Volume Program. This type of field action was announced in an All-Dealer letter dated May 10, 1999.

Owners will be contacting the Low Volume Coordination Center to arrange for this service. We will advise you via CuDL (Customer Data Link) of the owners that chose your dealership to perform the service provided by this recall. The parts will be ordered for you by the Program Coordination Center.

You are requested to contact the owner and arrange for this service. (Note that our Coordination Center will advise owners that they will hear from you within the next two business days.)

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Letter(s)

QUESTIONS?

Claims Information: ……1-800-423-8851
Other Recall (Dealers Only) Questions: ……1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

Emissions Recall 02E17
Certain 1997 through 2000 Model Year Dedicated Compressed Natural Gas F-Series trucks
Heater Hose to Fuel Rail Flex Line Inspection

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

You must contact the Low Volume Coordination Center at 1-800-248-0186 to arrange for parts if you have an involved vehicle in stock. When calling this number, identify Emissions Recall 02E17 and have the VIN of the dealer stock vehicle to be serviced.

DEALER-OWNER CONTACT

When you receive notification through CuDL (Customer Data Link), you should contact the owner and arrange for this service. Please note that our Coordination Center will advise owners that they will hear from you within the next two business days. For more information, see "Low Volume Announcement Letter" dated May 10,1999.

Immediately contact any affected owner whose name is not on the list but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

NOTE: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the owner letter (or after the date of the owner letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII manual for refund information.

RENTAL CARS

The use of rental vehicles is not authorized for this program.

© Copyright 2002 Ford Motor Company

Emissions Recall 02E17
Certain 1997 through 2000 Model Year Dedicated Compressed Natural Gas F-Series trucks
Heater Hose to Fuel Rail Flex Line Inspection

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
2000 MY Inspect Fuel Rail Flex Line and replace Heater hoses (Most 2000 MY units will require this labor operation)	02E17B	0.9 hours
2000 MY Inspect Fuel Rail Flex Line and Replace Heater hoses, Fuel Rail, and Injector O-rings	02E17C	2.1 Hours
1997 - 1999 MY Inspect Fuel Rail Flex Line and replace Heater Hoses (Most 1997-99 MY units will require this labor operation)	02E17D	1.0 hours
1997 - 1999 MY Inspect Fuel Rail Flex Line and Replace Heater Hoses, Fuel Rail, and injector O-rings	02E17E	2.2 hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS / ORDERING INFORMATION

CUSTOMER VEHICLES:

Parts will be shipped to your dealership according to the procedures established for "Low Volume Programs". DO NOT order parts, except for dealer stock units (Refer to "Low Volume Programs").

Note: When the customer calls the Coordination Center, the correct parts will be automatically sent to the Dealer. This will avoid having the customer return to the dealer if the vehicle fails the inspection. A DOES II message will be sent to the Dealer confirming part shipment. Parts not used may be returned for credit. (See "Excess Stock Return" below).

Unless otherwise requested, parts will be shipped stock order. For stock units, follow process shown below:

All Order Types	First 60 days after launch	Call 1-800-248-0186
All Order Types	61 days after launch	Normal order process

© Copyright 2002 Ford Motor Company

Emissions Recall 02E17
Certain 1997 through 2000 Model Year Dedicated Compressed Natural Gas F-Series trucks
Heater Hose to Fuel Rail Flex Line Inspection

Part Number	Description	Quantity
F75Z-18472-AG	Heater Hose Kit (1997–1999 MY)	1
2L3Z-18472-AC	Heater Hose Kit (2000 MY)	1
VC-4-A	Engine Coolant allowance - 1 Gallon (Ford Specification ESE-M97B44-A) – Sold in unit of issue of 6	1
FPS-8262	Authorized Modifications Label*	1

The following additional parts are only required if inspection reveals that the Fuel Rail assembly must be replaced.

2L3Z-9F792-AA	Fuel Delivery, Rail Assembly (1997-2000 MY)	1
F3DZ-9229-AAFFV	O-Ring Kit (Sold in unit issue of 10), Qty Needed is 16 per repair, two O-rings per injector (1997-2000 MY)	2

* Label orders come in packages of 25.

ORDER INFORMATION

The DOR/COR for this program is 50270. This number identifies parts ordered for this recall through the Low Volume Coordination Center (1-800-248-0186).

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2002 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2002

For Owners in CA only: Emissions Recall 02E17

Mr. John Sample
123 Main Street
Anywhere, CA, 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and is committed to vehicle quality and the environment. Therefore, we are voluntarily recalling certain 1997 - 2000 Model Year Dedicated Compressed Natural Gas F-Series Trucks. Your vehicle may be releasing air pollutants that exceed California emission standards. We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What is the concern?…

In some of the affected vehicles the fuel rail flex line may have chafed against the supply heater hose which runs from the engine to the heater core, and against the return heater hose which runs from the heater core to the engine. This contact by the heater hose has the potential to cause a small abrasion on the fuel rail that could eventually result in a gaseous fuel leak.

If you do not have this service done:

- Your emissions warranty may be reduced
- Your vehicle may not pass emissions or smog tests that may be required in your area
- Your state department of motor vehicles may not renew your vehicle registration

What Ford Motor Company and your dealer will do...

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners who are affected by this recall are requested to return their vehicle to their dealer for an inspection, replacement of the cooling system heater hoses and, if necessary, replacement of the fuel rail.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do…

Call toll-free 1-800-248-0186 and inform the Ford representative that you wish to have your vehicle serviced under Emission Recall 02E17.

© Copyright 2002 Ford Motor Company

Representatives are available 7:30AM to 7:30PM Monday through Friday, and 7:45AM to 5:00PM on Saturday (times are Eastern Time).

Please have this letter with you when you call. The Ford representative will ask for the Vehicle Identification Number (VIN) of your vehicle. The VIN is printed on the top of this letter.

Arrangements will be made with the dealership of your choice to have parts available. The dealership will call you to schedule an appointment. If you have not heard from your dealer within two working days, call your dealer to request a service appointment. You need do nothing else except bring your vehicle to the dealership on the service date.

If you have already paid for this service…

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this recall.

If you have concerns….

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you.

CALL: (866) 436-7332 or
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday-Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Or you may contact us through the Internet …

www.ownerconnection.com

© Copyright 2002 Ford Motor Company

Vehicles registered in California…

The State of California requires the completion of emissions recall repairs prior to vehicle registration renewal. If your F-Series Truck is registered in California, it is subject to these requirements.

When your dealer completes this emissions recall repair, you will receive a Vehicle Emission Recall Proof of Correction certificate. **Please make sure that you receive a certificate from your dealer and that you have it with you when you renew your vehicle registration.**

It is also important for you to know that the certificate should be returned to the Department of Motor Vehicles (DMV) only if it is requested by the DMV. Otherwise, this certificate is to be held by you for your records.

In order to ensure your full protection under emissions warranty provisions and to avoid any inconvenience when renewing your registration, it is recommended that you have your vehicle serviced as soon as possible. Failure to do so could be determined as lack of proper maintenance of your vehicle.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2002

Emissions Recall 02E17

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567
Ford Motor Company values you as a customer and is committed to vehicle quality and the environment. Therefore, we are voluntarily recalling certain 1997 - 2000 Model Year Dedicated Compressed Natural Gas F-Series Trucks that might be exceeding Federal emission standards. We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What is the concern?…

In some of the affected vehicles the fuel rail flex line may have chafed against the supply heater hose, which runs from the engine to the heater core, and against the return heater hose, which runs from the heater core to the engine. This contact by the heater hose on the fuel rail has the potential to cause a small abrasion on the fuel rail that could eventually result in a gaseous fuel leak.

What Ford Motor Company and your dealer will do...

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners who are affected by this recall are requested to return their vehicle to their dealer for an inspection, replacement of the cooling system heater hoses and, if necessary, replacement of the fuel rail.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do…

Call toll-free 1-800-248-0186 and inform the Ford representative that you wish to have your vehicle serviced under Emission Recall 02E17. Representatives are available 7:30AM to 7:30PM Monday through Friday, and 7:45AM to 5:00PM on Saturday (times are Eastern Time). Please have this letter with you when you call. The Ford representative will ask for the VIN of your vehicle. The VIN is printed on the top of this letter. Arrangements will be made with the dealership of your choice to have parts available. The dealership will call you to schedule an appointment. If you have not heard from your dealer within two working days, call your dealer to request a service appointment. You need do nothing else except bring your vehicle to the dealership on the service date.

© Copyright 2002 Ford Motor Company

If you've already paid for this service…

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this program.

If you have concerns….

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you.

CALL: (866) 436-7332 or
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday-Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Or you may contact us through the Internet …

www.ownerconnection.com

Please have your vehicle serviced promptly to maintain full emission warranty coverage.

Quality Care service is there for you all year round.

QualityCare at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company