Ford Motor Company

Frank M. Ligon
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

August 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 02S39: Certain 2002 Model Year Crown Victoria Natural Gas Vehicles (NGV) - "T" Fitting Replacement

AFFECTED VEHICLES

Certain 2002 model year Crown Victoria NGV vehicles built at the St. Thomas Assembly Plant from Job One to Job Last.

SAFETY CONCERN

On some of the affected vehicles, a "T" fitting that connects fuel tanks three and four may develop a leak when solenoid valves are energized, such as when the ignition switch is in the ON position or during refueling. The leak can be easily heard and will stop leaking when the ignition key is turned to the OFF position or the refueling process is terminated. A gas leak of sufficient quantity concentrated in an area to create a combustible mixture and in the presence of an ignition source could result in a fire.

SERVICE ACTION

The Ford Certified NGV dealer will replace the "T" fitting on number 4 fuel tank with a redesigned "T" fitting, tighten the "T" fitting jam nut to 43 Nm (32 lb-ft), test the fitting for leakage and clear diagnostic codes.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

© Copyright 2002 Ford Motor Company


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter(s)

QUESTIONS?

Claims Information:……..……..……....1-800-423-8851
Online Involved Unit Listings ……1-800-555-9601
Other (Dealer Only) Recall Questions:…….……...1-800-325-5621

Sincerely,



Frank M. Ligon

© Copyright 2002 Ford Motor Company

Safety Recall 02S39
Certain 2002 Model Year Crown Victoria Natural Gas Vehicles (NGV)
"T" Fitting Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any of your affected owners whose names are not on your VIN list but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

Note: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs applicable to this recall which were made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

The use of rental vehicles is not authorized for this program.

© Copyright 2002 Ford Motor Company

Safety Recall 02S39
Certain 2002 Model Year Crown Victoria Vehicles Natural Gas Vehicles (NGV)
"T" Fitting Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Remove #4 fuel tank "T" fitting, install and Torque new "T" fitting, check fitting for leakage, and clear diagnostic codes.	02S39B	1.6 Hrs.
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts will be direct shipped to Ford Certified NGV dealers for this recall. Only Ford Certified NGV dealers will be seed stocked and should receive their individual seed stock allocations one week after launch. Only Ford Certified NGV dealers should order this part.

All orders until October 13, 2002 — Call 1-800-325-5621

All orders after October 14, 2002 — Normal Order Process

Part Number	Description	Quantity
2W7Z-9C116-BA	Valve Assembly	1

ORDER INFORMATION

The DOR/COR for this program is **50285**. This number identifies parts ordered for this recall through the Special Service Support Center (1-800-325-5621).

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”.

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2002 Ford Motor Company