Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Owner Notification Program 00B53: Certain 2000 and 2001 Model Year F-250 and F-350 4X4 Vehicles Equipped with Single Rear Wheels, Gas Engines, and 5-Speed Manual Transmissions – Front Driveshaft Replacement

REF: Dealer Announcement dated May 10, 1999, Low Volume Recalls and Owner Notification Programs (Attachment IV)

OASIS : Yes
OWNER LIST: Yes
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until October 31, 2001, regardless of mileage.

AFFECTED VEHICLES

Certain 2000 and 2001 model year F-250 and F-350 4X4 vehicles equipped with single rear wheels, gas engines, 5-speed manual transmissions, and built at the Kentucky Truck Plant from July 20, 2000 through August 3, 2000.

REASON FOR PROGRAM

In some of the affected vehicles, the front driveshaft may be one inch too long, which could potentially result in severe vehicle vibration.

SERVICE ACTION

The dealer must inspect all of the affected vehicles for the correct length driveshaft and replace any driveshaft that fails the inspection.

LOW VOLUME RECALL

NOTE: There are only 272 total vehicles affected in this program.

This recall is being processed as a Low Volume Recall. This type of field action was announced in an All-Dealer letter dated May 10, 1999. (See Attachment IV)

Owners will be contacting the Low Volume Recall Coordination Center to arrange for this service. We will advise you via MORS III of the owners that chose your dealership to perform the service provided by this Recall program. The parts will be ordered for you by the Program Coordination Center.

You are requested to contact the owner and arrange for this service. (Note that our Coordination Center will advise owners that they will hear from you within the next two business days.)

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Attachment IV: Low Volume Dealer Announcement Letter
Customer Notification Letter

QUESTIONS?

Claims Information:……..1-800-423-8851
Other Program Questions:……..1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Owner Notification Program 00B53
Certain 2000 and 2001 Model Year F-250 and F-350 4X4 Vehicles
Front Driveshaft Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

Promptly correct all affected vehicles on the enclosed list and other eligible vehicles that are brought to your dealership.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

Program Code:	00B53
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hr.

RENTAL CARS

Rental cars are not provided for this program.

Owner Notification Program 00B53
Certain 2000 and 2001 Model Year F-250 and F-350 4X4 Vehicles
Front Driveshaft Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect Front Driveshaft Length	00B53A	0.2 Hours
Inspect and Replace Front Driveshaft	00B53B	0.6 Hours

PARTS REQUIREMENTS

Parts Ordering Information

CUSTOMER VEHICLES:

Parts will be shipped to your dealership according to the procedures established for "Low Volume Recalls". DO NOT order parts, except for dealer stock units (Refer to Attachment IV).

Note: When the customer calls the Coordination Center, the correct parts will be automatically sent to the dealer. This will avoid having the customer return to the dealer if the vehicle fails the inspection. Parts not used may be returned for credit. (See "Excess Stock Return" below).

STOCK VEHICLES:

Correct all vehicles in stock before delivery. First, inspect all affected stock vehicles to determine parts requirements. Then, contact the Low Volume Recall Coordination Center at 1-800-248-0186 to arrange for parts. When calling this number, identify Owner Notification Program 00B53 and have the VIN of the dealer stock vehicle to be serviced.

Parts will not be direct shipped for this program. Parts will be shipped Priority Next Day delivery.

Stock, Interim, and Emergency Orders	First 30 days after launch	Call 1-800-248-0186
All Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
F81Z-4A376-JA	Front driveshaft	1

ORDER INFORMATION DOR/COR

DOR/COR number 50181 identifies parts ordered for this campaign through the Recall Hotline (1-800-248-0186).

DEALER PRICE

For latest prices, check or call your:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

ATTACHMENT IV

All Dealer Letter
Part Procurement Process for Low Volume Programs

Ford Customer Service Division

Ford Motor Company
P.O. Box 1904
Dearborn, Michigan 48121

May 10, 1999

To: All Ford and Lincoln Mercury Dealers

cc: All Parts Managers
All Service Managers

Subject: Updated Part Procurement Process For Low Volume Recalls

The purpose of this communication is to update the process for dealer acquisition of service parts for certain Recalls/Owner Notification Programs with a small number of involved vehicles.

Background:

- Situations where Recalls/Owner Notification Programs have a small number of involved units require special handling.
- There are no controls in the parts system to prevent the over-ordering of parts in low volume situations.
- Many dealers order one or more parts even if they do not have an involved unit to insure customer satisfaction. This can result in parts in the inventory of dealers who do not need them and exhausted supply for dealers who do need them.
- With existing procedures, there is a cost to the Company and the Dealers (handling, returning, scrapping, etc.).

What's "Small Volume"?

- Generally, recalls, or ONP's involving 5,000 or fewer vehicles.

What We Propose

- Procedure to better manage "Parts-To-Affected-Vehicle" process.
- Vehicle owner (retail customer/fleet/dealer) requested to contact a "process facilitator" via a special 1-800 toll-free line or with a special postcard provided with the owner letter.
- Process facilitator verifies VIN/Owner information and works with owner (or dealer) to identify repairing dealer.
- Process facilitator inputs part order and sends a MORS III message with Customer/VIN/part shipping information to the identified repairing dealer.
- Dealer would be charged for the part at the lowest acquisition cost.

What's Different:

- Owner asked to call special toll-free line or send back special postcard.
- Parts would not be available through the normal parts ordering system.
- Owners would need to have an appointment.

Dealer Benefits:

- Eliminates back-orders—guarantees part availability.
- Increases customer satisfaction with your "Service Experience"
- New process will enable dealers to initiate pro-active service scheduling—with the information we will provide on the MORS III message, you call the customers to arrange a service appointment knowing that the part will be there and the customer's vehicle needs service.

Additional details will be provided as specific Recalls/Owner Notification Programs suitable for this process are launched.

We ask that you share this procedure with your parts and service personnel to insure they are aware of this process.

Ann O'Neill
Director
Vehicle Service and Programs

R. E. Turecki
Director
Global Parts Supply and Logistics

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673

October 2000

00B53

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is providing a Service Program, Number 00B53, free of charge to owners of certain 2000 and 2001 F-250 and F-350 4X4 vehicles built with single rear wheels, gas engines, and 5-speed manual transmissions.

Reason For This Program…

In some of the affected vehicles, a driveshaft that is one inch too long may have been installed. This driveshaft may cause your vehicle to develop a vibration.

What *Ford Motor Company* and your dealer will do…

Your dealer will inspect and if necessary replace your vehicle's driveshaft to avoid a vibration condition.

This program will be in effect until October 31, 2001, regardless of mileage.

What we are asking you to do…

Call toll-free 1-800-248-0186 and inform the Ford representative that you wish to have your vehicle serviced under Owner Notification Program 00B53. Representatives are available 7:30AM to 7:30PM Monday through Friday, and 8:00AM to 3:00PM on Saturday (times are Eastern Time).

Please have this letter with you when you call. The Ford representative will ask for the serial number of your vehicle. The serial number is printed on the top of this letter.

Arrangements will be made with the dealership of your choice to have parts available. The dealership will call you to schedule an appointment. If you have not heard from your dealer within two working days, call your dealer to request a service appointment. You need do nothing else except bring your vehicle to the dealership on the service date.

If you misplace this letter, your dealer will still do the work, free of charge.

How long will it take…

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

Refunds…

If you paid to have this service done before the date of this letter, Ford Motor Company is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm

Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com

Our current response time to Internet inquiries is three business days.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs