Ford Motor Company

March 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD: Safety Recall 01S10: Certain 2001 Model Year F-Series, F-Series Super Duty, Excursion, and Expedition Vehicles Built Through February 28, 2001– Driver's Airbag Replacement

AFFECTED VEHICLES

- Certain 2001 model year F-Series, F-Series Super Duty, and Excursion vehicles built at the Kentucky Truck Plant and the Kansas City Assembly Plant from February 26, 2001 through February 28, 2001

- Certain 2001 model year Expedition vehicles built at the Michigan Truck Plant from February 26, 2001 through February 27, 2001

Please Note: Only the VINs identified in OASIS are included in this action. Only 288 vehicles in this time frame have suspect driver airbags. See your affected units list on QCDealer.com to determine if you have an involved unit. Most dealerships will not have any affected units.

SAFETY CONCERN

In the affected vehicles the driver's airbag may have insufficient welds that could prevent proper inflation of the airbag. In the event of an accident, the driver's airbag may not properly deploy which could potentially result in reduced occupant protection and/or a burn injury.

SERVICE ACTION

Before demonstrating or delivering any of the vehicles involved in this recall, the dealer must replace the driver's airbag. Call the Recall Hotline at 1-800-325-5621 for directions prior to replacing. This must be done on all of the affected vehicles.

WARNING: Do not deploy the suspect airbag module. Package the suspect airbag in the replacement airbag shipping box and use the return tag to ship to the supplier.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……..……....1-800-423-8851
Other (Dealer Only) Recall Questions:…….……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

DEMONSTRATION / DELIVERY HOLD: Safety Recall 01S10
Certain 2001 Model Year F-Series, F-Series Super Duty, Excursion, and Expedition Vehicles
Driver's Airbag Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Recall/ONP Involved Unit Listings available on QCDealer.com. Also, correct other eligible vehicles that are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Refer to ACESII manual for refund information.

RENTAL CARS

If a replacement airbag must be ordered for a sold unit, Ford will pay for a rental vehicle except for fuel, which will be at the owner's expense. Follow Extended Service Plan (ESP) guidelines for rental dollar amounts. Enter the word "RENTAL" plus the number of days the vehicle was used in the Miscellaneous Expense area of the recall claim.

DEMONSTRATION / DELIVERY HOLD: Safety Recall 01S10
Certain 2001 Model Year F-Series, F-Series Super Duty, Excursion, and Expedition Vehicles
Driver's Airbag Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
F-150 and Expedition Vehicles: Replace the driver's airbag	01S10B	1.4 Hour
F-Series Super Duty and Excursion Vehicles: Replace the driver's airbag	01S10C	1.8 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Since there are only 288 vehicles involved, dealers must call the Recall Hotline at 1-800-325-5621 to order parts. When calling, be prepared to provide the affected VIN to ensure the correct airbag will be shipped to you (via any order type you choose). This process will remain in effect for the first 30 days after launch. After 30 days, dealers will be able to order parts through normal order processing channels.

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

ORDER INFORMATION DOR/COR

DOR/COR number 50225 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621).

DRIVER AIR BAG MODULE REPLACEMENT

SERVICE PROCEDURE

WARNING: DO NOT DEPLOY THE SUSPECT AIR BAG MODULE. PACKAGE THE SUSPECT AIR BAG IN THE REPLACEMENT AIR BAG SHIPPING BOX AND USE THE RETURN TAG TO SHIP TO THE SUPPLIER.

The airbag module will be replaced in all the affected vehicles.

CALL THE RECALL HOTLINE AT 1-800-325-5621 FOR INSTRUCTIONS BEFORE REPLACING THE AIR BAG.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2001

01S10

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect that relates to motor vehicle safety exists in certain 2001 F-Series, Super Duty, Excursion, and Expedition vehicles.

What the safety issue is …

In the affected vehicles the driver's airbag may have insufficient welds that could affect proper inflation of the airbag during a vehicle crash. This could potentially result in reduced occupant protection or a burn injury.

What Ford Motor Company and your dealer will do...

Ford Motor Company will replace the driver's side airbag in your vehicle free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do …

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 01S10.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

Rental vehicle…

If a replacement airbag must be ordered, Ford will pay for a rental vehicle except for fuel, which will be at the owner's expense until repairs can be completed.

If you have already paid for this service …

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager. If you still need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.


Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs