TRIM—SEATS—LACK OF COMFORT FROM FRONT SEATS	Article No. 01-1-8

LINCOLN: 2000-2001 LS

ISSUE

Some vehicles may exhibit a lack of comfort of the front seats. The condition may be described as a lack of seat padding on the lower seat cushion and/or being able to feel the seat frame through the padding. This may be caused by the density of the front seat lower cushion foam.

ACTION

Replace the front seat lower cushion with a revised cushion which is of a higher density foam (firmer).

Replace per appropriate year LS Workshop Manual procedure, Section 501-10.

PART NUMBER	PART NAME
YW4Z-54632A23-BA	Seat Cushion - LH
YW4Z-54632A22-BA	Seat Cushion - RH

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 101000, 107000

Copyright © 2001 Ford Motor Company