Ford Motor Company

Frank M. Ligon
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

December 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Customer Satisfaction Program 02M01: Certain vehicles equipped with a tube-mounted EGR Pressure Sensor - Additional EGR Pressure Sensor Warranty Coverage

OASIS: Yes
OWNER LIST: No
PROGRAM TERMS: This additional coverage program will add 2 years or 24,000 miles whichever occurs first, to the base warranty coverage for the tube mounted EGR Pressure Sensor. This coverage will automatically transfer to subsequent owners.

VEHICLES COVERED BY THIS PROGRAM

Certain 2000 and 2001 model year vehicles equipped with a tube-mounted EGR Pressure Sensor (9J460). Refer to OASIS for specific vehicle eligibility.

TIME AND MILEAGE LIMITS

Warranty Type	Current Warranty Coverage	Total Warranty Coverage
Federal	3 Years/36,000 Miles	5 years/60,000 Miles
California Emissions*	3 Years/50,000 Miles	5 Years/74,000 Miles
Lincoln	4 Years/50,000 Miles	6 Years/74,000 Miles

* California emissions include vehicles certified for sale in California and registered in California, Maine, Massachusetts, New York or Vermont.

REASON FOR PROVIDING ADDITIONAL COVERAGE

Vehicles experiencing a problem with the tube mounted EGR Pressure Sensor may exhibit a Malfunction Indicator Light (MIL) along with one or more of Diagnostic Trouble Codes (DTC) P0401, P0402, P1400, or P1401.

A very small percentage of vehicles may also exhibit a MIL with the following symptoms:

- Hesitation/Surge
- Stall with restart

Any of these conditions will not cause engine damage or failure, but may decrease the customer's satisfaction with their vehicle.

© Copyright 2002 Ford Motor Company

SERVICE ACTION

It is recommended for vehicles exhibiting any of the conditions listed above and equipped with a tube mounted EGR Pressure Sensor, that the dealer retrieve continuous DTC prior to any other diagnostics.

Dealers are to install a new tube mounted EGR Pressure Sensor at no charge to the owner of the vehicle, ONLY if one or more of these continuous DTC are present:

- P1400 – DPF EGR Sensor Circuit Low Voltage Detected
- P1401 – DPF EGR Sensor Circuit High Voltage Detected
- P0401 – EGR Flow Insufficient Detected
- P0402 – EGR Flow Excessive Detected

A failed DPFE will only exhibit one or more of the DTC listed above. This program will not cover any other continuous DTC present.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letters

QUESTIONS?

Claims Information: ……..1-800-423-8851
Other (Dealer Only) Program Questions: ……1-800-325-5621

Sincerely,

Frank M. Ligon

Frank M. Ligon

© Copyright 2002 Ford Motor Company

Customer Satisfaction Program 02M01
Certain Vehicles Equipped with a Tube-Mounted EGR Pressure Sensor
Additional EGR Pressure Sensor Warranty Coverage

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

Note: Submission of an "M" program claim will not remove the vehicle from OASIS because the affected vehicles are eligible for multiple repairs if the affected condition reoccurs during the extended warranty time/mileage period.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

EXTENDED WARRANTY PROGRAMS AND MEASURED WARRANTY

This program, and others may involve repairs that fall within the mileage/time coverage period of the New Vehicle Limited Warranty (NVLW). For that reason, Ford Motor Company is investigating the integration of warranty extension programs into the dealer measured warranty report for vehicles still within the NVLW.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made on or before the last day of the month of the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Failure of the EGR Pressure Sensor (9J460) will not have an impact on any other component of the vehicle. Therefore, refunds will only be granted for the replacement of the EGR Pressure Sensor (9J460).

All supporting documentation must be retained in accordance with the Warranty and Policy Manual.

Program Code:	02M01
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hr.

Refer to ACESII manual for refund information.

RENTAL CARS

The use of rental vehicles is not authorized for this program.

© Copyright 2002 Ford Motor Company

Customer Satisfaction Program 02M01
Certain Vehicles Equipped with a Tube-Mounted EGR Pressure Sensor
Additional EGR Pressure Sensor Warranty Coverage

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Retrieve one or more of the following Continuous DTC, P1400, P1401, P0401 or P0402, clear codes and replace tube mounted EGR Pressure Sensor, perform KOEO self test NOTE: 0.5 hrs labor time will be paid for Econoline and Town Car. 0.4 hrs labor time will be paid for Crown Vic/Grand Marquis and Expedition.	02M01B	0.3 hrs

Special Notes:

- Diagnostics preformed beyond retrieving continuous DTC will not be paid for under this program.
- Pinpoint diagnostics is not required to identify a failed EGR Pressure Sensor; therefore labor time has been adjusted accordingly.
- Due to the specific DTC to identify a failed EGR Pressure Sensor, this program will not cover any other continuous DTC; normal vehicle warranty would apply for any other DTC.
- There will be no related damage claims allowed for this program.

PARTS REQUIREMENTS

Parts will not be direct shipped for this program. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
2F1Z-9J460-AA	Tube Mounted EGR Pressure Sensor	1

DOR/COR NUMBER

The DOR/COR for this program is 50291. This number identifies parts ordered for this Customer Satisfaction Program through the Special Service Support Center (1-800-325-5621).

DEALER PRICE

For latest prices, check DOES II or updated price book.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2002 Ford Motor Company