Ford Motor Company

January 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 00S42: Certain 1999 and 2000 Model Year Windstar Vehicles – Front Electronic Module (FEM) Reconfiguration To Modify The Delayed Accessory Relay Operation – FMVSS 118 Non-Compliance

AFFECTED VEHICLES

Certain 1999 and 2000 model year Windstar vehicles built at the Oakville Assembly Plant from February 18, 1999 through February 1, 2000.

NON-COMPLIANCE

In the affected vehicles there is the potential that the power windows may be operable after the ignition has been turned to the "off" position and the front doors are opened. FMVSS 118 prohibits the operation of the power windows under these conditions.

SERVICE ACTION

The dealer must reconfigure the front electronic module (FEM) using NGS or WDS.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……..1-800-423-8851
Other (Dealer Only) Recall Questions:……..1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Safety Recall 00S42
Certain 1999 and 2000 Model Year Windstar Vehicles
Front Electronic Module (FEM) Reconfiguration To Modify The Delayed Accessory Relay Operation – FMVSS 118 Non-Compliance

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer VIN list which you will receive in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles that are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental cars are not provided for this program.

Safety Recall 00S42
Certain 1999 and 2000 Model Year Windstar Vehicles
Front Electronic Module (FEM) Reconfiguration To Modify The Delayed Accessory Relay Operation – FMVSS 118 Non-Compliance

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Reconfigure FEM module with WDS	00S42B	0.3 Hours
Reconfigure FEM module with NGS	00S42C	0.2 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

There are no parts required for this program.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673

January 2001

00S42

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that certain 1999 and 2000 model year Windstar vehicles fail to conform to the requirements specified in the Federal Motor Vehicle Safety Standard (FMVSS) No. 118, Power Operated Window, Partition, and Roof Panel Assemblies.

We apologize for this situation and want to assure you that with your assistance we will correct this condition. Our commitment, together with Ford dealers, is to provide you with the highest level of service and support possible.

What the non-compliance issue is…	In the affected vehicles there is the potential that the power windows may be operable after the ignition has been turned to the "off" position and the front doors are opened. FMVSS 118 prohibits the operation of the power windows under these conditions.
What Ford Motor Company and your dealer will do...	Ford Motor Company will reconfigure an electronic module in your vehicle to correct this condition. Owners who are affected by this recall are requested to return their vehicle to their dealer for this reconfiguration.
How long will it take?	The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.
What we are asking you to do…	Call your dealer without delay. Ask for a service date. When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.
If you've changed address or sold the vehicle…	Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you experience trouble having your vehicle repaired, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-800-424-9393 or 1-888-327-4863.


Quality Care service is there for you all year round.

QualityCare℠ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs