Ford Motor Company

September 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 00S30: Certain 2000 Model Year Focus Vehicles with 2.0L Zetec Engine, Automatic Transaxle and Speed Control – Speed Control Cable Inspection

AFFECTED VEHICLES

Certain 2000 model year Focus vehicles equipped with Speed Control, 2.0L Zetec engine and automatic transaxle, which were built at the Wayne Assembly Plant from Job #1 through October 31, 1999 and from December 1, 1999 through February 25, 2000.

SAFETY CONCERN

In some of the affected vehicles the speed control cable may have been built too long and the cable end slug may catch on the protective plastic slider at wide open throttle. This could potentially prevent the throttle cable from returning to idle when the accelerator pedal is released. A throttle that does not return to idle could result in reduced vehicle control and, potentially, a vehicle crash.

SERVICE ACTION

Dealers will inspect the speed control cable attachment and, if necessary, replace the speed control cable assembly.


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……...1-800-423-8851
Other (Dealer Only) Recall Questions:……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Safety Recall 00S30

Certain 2000 Model Year Focus with 2.0L Engine, Automatic Transaxle and Speed Control
Speed Control Cable Inspection

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer VIN list which you will receive in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid speed control cable repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Ford Motor Company will pay for a rental vehicle, except for fuel which will be at owner's expense. Enter the word "RENTAL" plus the number of days the vehicle was used in the Miscellaneous Expense area. Follow ESP cost guidelines.

Safety Recall 00S30
Certain 2000 Model Year Focus with 2.0L Engine, Automatic Transaxle and Speed Control
Speed Control Cable Inspection

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect Speed Control Cable	00S30A	0.2 Hours
Inspect and Replace Speed Control Cable	00S30B	0.3 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
YS4Z-9A825-DA	Speed Control Cable – 2.0L Zetec – Automatic	1

DOR/COR

DOR/COR Number 50185 identifies parts ordered for this campaign through the Recall Hotline (1-800-325-5621).

DEALER PRICE

For latest prices, refer to DOES II or your updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673

October 2000

00S30

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2000 model year Focus vehicles equipped with speed control (cruise control).

We apologize for this situation, and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What the safety issue is …

In some of the affected vehicles, the speed control cable may be too long, which could potentially prevent the throttle from returning to idle from wide-open throttle. A throttle that does not return to idle could result in reduced vehicle control and, potentially, a vehicle crash.

What Ford Motor Company and your dealer will do ...

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners who are affected by this recall are requested to return their vehicle to their dealer for inspection and, if necessary, replacement of the speed control cable.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do …

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 00S30.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've already paid for this service …

If you paid to have the speed control cable replaced before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager. If you still need assistance, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 1-202-366-0123).

Quality Care service is there for you all year round.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs