- **TRIM—MANUAL SHIFT LEVER OUTER BOOT DETACHMENT—FX4 MODELS EQUIPPED WITH MANUAL TRANSMISSION ONLY—VEHICLES BUILT BEFORE 4/30/2002**
- **TRANSMISSION—MANUAL SHIFT LEVER OUTER BOOT DETACHMENT—FX4 MODELS EQUIPPED WITH MANUAL TRANSMISSION ONLY—VEHICLES BUILT BEFORE 4/30/2002**

Article No. 02-21-10

FORD: 2002 RANGER

ISSUE

On some vehicles, the manual shifter boot (transfer case or transmission) may unseat from the shifter. This may be caused by insufficient retention of the boot.

ACTION

Remove and replace appropriate shifter boot(s) with new service boot(s). Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Verify that either or both transmission or transfer case shifter leather boot(s), colored black, have become loose or not seated.
2. If either boot is not seated or loose, replace per the parts list.
3. Remove the knobs.
4. Unsnap the fasteners and pull up on the boot to remove.
5. Reinstall the new boot.
6. Reinstall the knobs and tighten.

PART NUMBER	PART NAME
2L5Z-7277-AC	Transmission Shifter Boot
2L5Z-7277-AD	Transfer Case Shifter Boot

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
022110A	Replace Transmission Shift Boot	0.2 Hr.
022110B	Replace Transfer Case Shift Boot	0.2 Hr.
022110C	Replace Both Transmission And Transfer Case Shift Boots	0.2 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
7277	07

OASIS CODES: 107000, 505000, 505200, 508000

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle.

Copyright © 2002 Ford Motor Company