Ford Motor Company

June 2000

TO: All Lincoln Mercury Dealers

SUBJECT: **Owner Notification Program 00B39, Revision # 1:** Certain 2000 Model Year Lincoln LS Vehicles – Wood and Leather Steering Wheel and Wood Shifter Knob Retrofit

OASIS: Yes

OWNER LIST: No

PARTS RETURN: Follow the provisions of the Warranty and Policy Manual for "Parts Retention and Return Procedures".

PROGRAM TERMS: This program will be in effect until December 31, 2000, regardless of mileage.

REFERENCE: **Owner Notification Program 00B39, posted on qcdealer.com May 26, 2000**

REASON FOR REVISION

Owner Notification Program 00B39 has been revised to update the Attachment III. Step # 10 on Page 5 inadvertently listed the torque specification for the steering wheel retaining nut as 30 lb – in. The correct specification is **30 lb – ft**. This correction has been incorporated in Attachment III.

AFFECTED VEHICLES

Certain 2000 model year Lincoln LS vehicles, equipped with non-sport packages, built at the Wixom Assembly plant from August 8, 1998 through August 8, 1999.

REASON FOR PROGRAM

Lincoln is committed to ensuring that the owner's luxury experience is uncompromised and meeting their product expectations. However, when the affected vehicles were manufactured, these particular Lincoln LS vehicles were not equipped with a wood steering wheel and wood shifter knob.

The functionality of the steering wheel and shifter knob are not affected by the substitution.

Accordingly, at the owner's discretion, Lincoln will retrofit the vehicle's current leather steering wheel and leather shifter knob with a wood and leather steering wheel and wood shifter knob.

SERVICE ACTION

Dealers are directed to replace the vehicle's leather steering wheel and leather shifter knob with a wood and leather steering wheel and wood shifter knob.

MODIFIED LOW VOLUME OWNER NOTIFICATION PROGRAM

This action is being processed as a modified "Low Volume Owner Notification Program". This type of action was announced in the revised All-Dealer letter dated May 10, 1999. A copy of that letter is attached. Parts will be shipped to your dealership based on **dealer personnel** contacting the special 1-800-number provided.

Once the parts are available, dealers are to call the customer to confirm the service appointment.


ATTACHMENTS

Attachment I:	Administrative Information
Attachment II:	Labor Allowances and Parts Ordering Information
Attachment III:	Technical Information
Attachment IV:	All Dealer Letter - Part Procurement Process for Low Volume Programs

QUESTIONS?

Claims Information:	1-800-423-8851
Other Program Questions:	1-800-325-5621

Sincerely,



Mark Hutchins
President
Lincoln Mercury

Owner Notification Program 00B39, Revision # 1
Certain 2000 Model Year Lincoln LS Vehicles –
Wood and Leather Steering Wheel and Wood Shifter Knob Retrofit

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII Manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor will only refund owner-paid wood and leather steering wheel and wood shifter knob replacements made before the date of the Owner Letter.

- Program Code: 00B39
- Misc. Expense: REFUND
- Misc. Expense: ADMIN
- Misc. Expense: 0.2 Hr.

Refer to Section 3 of the ACESII manual for refund information.

RENTAL CARS

Rental cars are not authorized for this program.

Owner Notification Program 00B39, Revision # 1
Certain 2000 Model Year Lincoln LS Vehicles –
Wood and Leather Steering Wheel and Wood Shifter Knob Retrofit

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Steering Wheel and Shifter Knob	00B39B	0.5 Hours

PARTS REQUIREMENTS

Parts Ordering Information

Parts will be direct shipped to your dealership Parts Manager under a modified "Low Volume Recall Programs" procedure. Dealers are to order parts for affected in stock units AND at the request of a customer with a verified affected unit. Dealers are to call the Ford Program Assistance Center at **1-800-248-0186** to place an order. Refer to the attached All-Dealer letter (Attachment IV).

All Orders	**Through August 31, 2000**	**Call 1-800-248-0186**
All Orders	**After September 1, 2000**	**Normal Process**

DOR/COR number 50163 identifies parts ordered for this campaign through the:

- **Low Volume Recall program (1-800-248-0186)**

Part Number	Description	Quantity
XW4Z-3600-CAA	Wood and Leather Steering Wheel, Parchment	1
XW4Z-3600-CAB	Wood and Leather Steering Wheel, Truffle	1
XW4Z-3600-CAC	Wood and Leather Steering Wheel, Graphite	1
XW4Z-3600-CAD	Wood and Leather Steering Wheel, Black	1
YW4Z-7213-DA	Wood Shifter Knob	1

Owner Notification Program 00B39, Revision # 1
Certain 2000 Model Year Lincoln LS Vehicles –
Wood and Leather Steering Wheel and Wood Shifter Knob Retrofit

DEALER PRICE

For latest prices, check or call your:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Original All Dealer Letter

Part Procurement Process for Low Volume Programs

Ford Customer Service Division

Ford Motor Company
P.O. Box 1904
Dearborn, Michigan 48121

May 10, 1999

To: All Ford and Lincoln Mercury Dealers

cc: All Parts Managers
All Service Managers

Subject: Updated Part Procurement Process For Low Volume Recalls

The purpose of this communication is to update the process for dealer acquisition of service parts for certain Recalls/Owner Notification Programs with a small number of involved vehicles.

Background:

- Situations where Recalls/Owner Notification Programs have a small number of involved units require special handling.
- There are no controls in the parts system to prevent the over-ordering of parts in low volume situations.
- Many dealers order one or more parts even if they do not have an involved unit to insure customer satisfaction. This can result in parts in the inventory of dealers who do not need them and exhausted supply for dealers who do need them.
- With existing procedures, there is a cost to the Company and the Dealers (handling, returning, scrapping, etc.).

What's "Small Volume"?

- Generally, recalls, or ONP's involving 5,000 or fewer vehicles.

What We Propose

- Procedure to better manage "Parts-To-Affected-Vehicle" process.
- Vehicle owner (retail customer/fleet/dealer) requested to contact a "process facilitator" via a special 1-800 toll-free line or with a special postcard provided with the owner letter.
- Process facilitator verifies VIN/Owner information and works with owner (or dealer) to identify repairing dealer.
- Process facilitator inputs part order and sends a MORS III message with Customer/VIN/part shipping information to the identified repairing dealer.
- Dealer would be charged for the part at the lowest acquisition cost.

What's Different:

- Owner asked to call special toll-free line or send back special postcard.
- Parts would not be available through the normal parts ordering system.
- Owners would need to have an appointment.

Dealer Benefits:

- Eliminates back-orders—guarantees part availability.
- Increases customer satisfaction with your "Service Experience"
- New process will enable dealers to initiate pro-active service scheduling—with the information we will provide on the MORS III message, you call the customers to arrange a service appointment knowing that the part will be there and the customer's vehicle needs service.

Additional details will be provided as specific Recalls/Owner Notification Programs suitable for this process are launched.

We ask that you share this procedure with your parts and service personnel to insure they are aware of this process.

A. R. O'Neill
Director
Vehicle Service and Programs

R. E. Turecki
Director
Global Parts Supply and Logistics

LINCOLN

June 2000

Mr. John Sample
123 Main Street
Anywhere, USA 12345
Vehicle Identification Number: 12345678901234567

We hope you are enjoying your new 2000 Lincoln LS. Lincoln takes great pride in designing a luxury sport sedan, which has received immediate recognition as a *true driver's car* and the prestigious ***Motor Trend*** **Car of the Year Award** for 2000. We appreciate the opportunity to be an integral part of your driving experience.

Lincoln is committed to ensuring that your luxury experience is uncompromised and meeting your product expectations. In meeting that commitment, you are being notified of a campaign action, included with this letter.

Additionally, when your vehicle was manufactured, your Lincoln LS was not equipped with a wood steering wheel and wood shifter knob. The functionality of your steering wheel and shifter knob were not affected by the substitution. Accordingly, at your discretion, Lincoln will retrofit your current leather steering wheel and leather shifter knob with a wood and leather steering wheel and wood shifter knob.

If you choose to have your vehicle retrofitted, please contact your Lincoln dealer to advise the dealer of your intent to have the wood and leather steering wheel and wood shifter knob installed at no charge and to schedule an appointment. Once your selected dealer is in receipt of the wood and leather steering wheel and wood shifter knob, the dealer will contact you to confirm your appointment to install the components and complete the additional service campaign.


The time needed to retrofit your LS is approximately one-half day, but your dealer may need your vehicle for a longer period of time. The opportunity to retrofit your current leather steering wheel and leather shifter knob with a wood and leather steering wheel and wood shifter knob expires December 31, 2000.

If you have already purchased and installed the wood and leather steering wheel and wood shifter knob before the date of this letter, Ford Motor Company is offering a full refund. For the refund, please provide your paid original receipt to your Lincoln dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have changed your address or sold the vehicle please fill out the enclosed prepaid postcard and mail it to us. This action is part of our ongoing efforts to exceed owner expectations and maintain confidence in our products.

Once again, we thank you for choosing the Lincoln LS.

Sincerely,



Mark Hutchins
President
Lincoln Mercury