Electrical Work Request

Targeted Repair & Circuit Restoration

ACTION REQUIRED

ISSUE OVERVIEW (SUMMARY)

An auxiliary junction/terminal block previously spliced into the dedicated electric water heater line has severe thermal damage (burned/melted). This block was added to supply power to a washing machine in the same room. Under sustained load (overcurrent/high current draw), the junction connection failed.

Job Details & Location Information

Primary Appliance:	Electric Water Heater (Sauter 100L)
Secondary Equipment:	Washing Machine (to be disconnected from this circuit)
Nature of Damage:	Overheated/burned junction box and wiring trunking
Target Outcome:	Restore line back to single dedicated water heater feed

Requested Scope of Work

- **Isolate & Safe Off:** Ensure power to the dedicated water heater circuit is fully isolated at the main consumer unit/breaker board.
- **Remove Non-Standard Junction:** Completely remove the damaged/burned added connection block and affected surface trunking section.
- **Inspect Cable Integrity:** Check the incoming supply wires and the water heater feed line for heat degradation or compromised insulation.
- **Restore Dedicated Power Line:** Re-establish a direct, safe, and code-compliant connection dedicated solely to the water heater (reverting to original specification).
- **Test System:** Test circuit continuity, grounding, and operational load to ensure safe operation.

Site Photos & Visual Evidence



Figure 1: Close-up of Burned Junction Block
Showing severe thermal damage, soot marks, and degraded wire insulation resulting from overcurrent on the shared branch line.



Figure 2: Water Heater & Installation Context
Sauter 100L water heater tank relative to the damaged connection point and plumbing setup.