Work Order ID : 14044218
Please have on site contact sign this copy and keep this for your record.

General Information

Service Title
POS replacement

Service Schedule
On Wednesday September 20th 2023
At 3:00 pm EDT

Manager of Work Order
NCR HSR

+18665062979

Assigned Provider
Sadiqa Thornton (user id: 24217)

Service Location (type: Commercial)
338701 DUNKIN

SOMERVILLE, NJ, 08876

On Site Contact

Additional Fields

Client Work Order #
Tip: Give this number to the Help Desk
3188693//86402784

Customer Ticket #
3188693//86402784

Data to Note

MOD First and Last name [required]

Name of RDC Remote Engineer [required]
Tip: Who from RDC released you or approved your extra time onsite?

Out of Scope Hours Explanation [required]
Tip: If job required time outside of maximum hours allowed, provide details of what additional work was completed and who approved additional work. If none, put N/A.

Return Tracking # [required]
Tip: Tracking # for return shipment

Serial Number Old Part [required]

Serial Number New Part [required]

Where you able to reach RDC [required]
Tip: Please log how many times it took to reach RDC and how long the wait.

Necessary Equipment

Full Work Description

Scope of Work:

Subject: POS replacement

Part Number: 7761-3100-0067

Part Description: P1535 PCAP 120GB 8GB RAM WIN10E-64BIT 2016 MSR Int2x20

Re-package the Old Device:

- Peel off the shipping label to reveal the return label.
- Write the RMA number on the box – found on the attached sign-off sheet.
- Take a photo of the label and upload it to the work order
- Drop the package off at any FedEx location.

Review attached client work order for equipment details and client work order #. Remember to print the client work order for the POC sign-off.

Do not log multiple site visits on this work order.

Each site visit will require its own work order.

If a revisit is needed or requested by support, close out this work order and contact Pivital ASAP to notify that a revisit will be required.

Device installs may also include troubleshooting, configuration, or working with support to confirm device is on the customer's network.

Terminals may have peripheral devices, such as printers or pin pads . These may also need troubleshooting and/or configuration to complete the installation scope.

Tool Requirement:

- WIN10 Laptop – with Charger
- Cellphone – with Charger
- Black Ink Pens – for Documentation
- Hot Spot or Internet Dongle
- Regular, Phillips, & Micro screwdrivers (various sizes)
- USB Keyboard & Mouse
- USB Thumb Drive (4Gb or 16Gb)
- Side cutters
- Nut drivers
- Crescent wrench
- Allen wrench set
- Black electrical tape
- 7" Ty-wraps
- RJ11/45 6ft patch cables
- Digital camera
- Labels
- Permanent marker
- Grounding strap (to prevent ESD)
- Flashlight

Applicable for Cabling/Wiring call only:

- Network cable
- Cat5 Network tester

Site Requirements:

- Part(s) must be dropped off at the FedEx Location – DO NOT leave the part on the site.
- If MOD or Support request part to be left onsite. Call **HSR Help Desk (RDC)** and confirm before leaving site. RDC representative's name will be required.
- Duration of the site visit should not be more than 1.5 hours – If additional time required onsite, call for extended duration approval: **HSR Help Desk 800-348-8937**.
- Record the client employee's First name of who provided approval for an extended time frame.
- Approval must be documented in the work order's correct Custom Field or payment will be denied.

Site Security Requirements:

- Government-issued photo ID required
- Names of all technicians attending the site must be provided in advance
- Check-in with site contacts representing **NCR**
- The job requires workers to be fully equipped to complete all work without the need for any customer tools or equipment
- Professional environment expects professional conduct and clean business casual attire

Tasks

Some tasks below may be eligible for completion by calling 1-877-573-6330

Pre Visit

1. Provider must set start time

2. Provider must **Print work order out - the work order MUST be completed (including start and complete time) and signed by the manager on duty prior to leaving site (see attachments for PDF)**
   (Code 185 108 734 455 75#)

On Site

1. Provider must check in
   (Code 180 104 522 455 75#)
2. Provider must call phone number **+1 800-348-8937** **check in with HSR Help Desk (RDC). Reference Client Work Order # (also shown on work order details header this is not your FN wo#)**

3. Provider must **HSR Help Desk will provided a customer specific support number. Call support as directed by the HSR Help Desk.**
   (Code 154 109 542 455 75#)
4. Provider must upload or take a picture of **Old equipment before install**

5. Provider must upload or take a picture of **Serial Number of Old Part**

6. Provider must upload or take a picture of **Serial Number of New Part**

7. Provider must upload or take a picture of **New Equipment after install**

8. Provider must upload or take a picture of **Return tracking label**

9. Provider must enter shipment tracking for **Return Part**

10. Provider must **Box up the return part to ship back as instructed. Remember to peel off the shipping label as there will be a return label.**
    (Code 160 106 313 455 75#)
11. Provider must **Write the RMA number on the return box**
    (Code 105 108 623 455 75#)
12. Provider must upload or take a picture of **Completed and signed client work order**

13. Provider must **Provide the name of the MOD**
    (Code 138 105 953 455 75#)
14. Provider must **Confirm with the customer support work is completed and record the name of the person you are working with.**
    (Code 140 108 663 455 75#)
15. Provider must call phone number **+1 800-348-8937 Call HSR Help Desk (RDC) after work is completed with support. Tech MUST check out with HSR Help Desk prior to leaving site.**

16. Provider must enter close out notes

17. Provider must check out
    (Code 159 105 993 455 75#)

Post Visit

1. Provider must upload or take a picture of **FedEx Tracking Receipt**

Shipments

1. Pos is being shipped from site location

Approval of Work

I acknowledge that the work has been satisfactorily completed.

Name	Arrival Time AM / PM
Signature	Departure Time AM / PM
Date	

CONFIDENTIAL!

The following information is confidential and should not be seen by anyone but you, the assigned provider.

Confidential Information

Description of Problem:

Hi NCR Team,

HDD SWAP RTS has been triggered for PC338701 with N@YS Case: INC000027793898

Details:

• POS2 Is Offline (ETH Port Issue)

• Reseat network cable

• Change network cable (used from POS1 that is online)

• Check Meraki > PT is online but POS is offline

• Bypass Verifone Switch

• Reboot POS2

• POS2 still offline

USD Findings: POS2 Is Offline (ETH Port Issue)

Note for the tech: Need to have the RTS Tech Guide. Call store when on way going to the location and call USD Support at 1-800-700-1225 Option 2 before leaving the store. Bring Mouse and Keyboard.

Simphony Version: 18.2.9.6

Contact Details:

• Name: Samar Amin | Store Manager

• Store Phone: (908)704-1819

• Alternate Contact: 908-346-0405

• Preferred date and time to install the POS: ASAP

• Store Hours: 05:00AM - 8:00PM

POS Information:

• Model No: 7761-3100-0258

• Serial No: 20-55295192

Note from Client: null

Upon arrival and prior to leaving site: Call 800-348-8937 HSR Help Desk to check in/out. Reference the NCR WO#3188693.

Deliverable Uploads

Make sure you collect and upload any required deliverables into the following deliverable categories:
[ ] Old equipment before install
[ ] Serial Number of Old Part
[ ] Serial Number of New Part
[ ] New Equipment after install
[ ] Return tracking label
[ ] Completed and signed client work order
[ ] FedEx Tracking Receipt
[ ] Misc

Customer Standard Instructions

-Deliverables are due within 6 hours of tech leaving site.

Customer Policies & Procedures

PIVITAL Policies & Procedures

*****ATTENTION: ALL ITEMS ARE REQUIRED FOR PAYMENT****

-IMPORTANT: Present yourself as an representative of PIVITAL unless otherwise instructed in the work order. Do not promote any other company other than PIVITAL on this Work Order.

-All travel expenses (Excluding parking and tolls) must be accepted/approved via counter offer, no exceptions.

-The requesting provider must be the provider who performs the actual service work onsite. You are expected to arrive onsite by yourself (no helpers, or assistants). Exceptions may be given but only upon prior approval by PIVITAL on this Work Order. Failure to comply with the above statements will result in loss of compensation on this work order.

-Dress Code: Business casual is required. No denim; t-shirts; logos or tennis shoes are allowed (work boots are acceptable).

-Print this work order and all additional documentation. Read the complete work order prior to arrival. Direct all questions to PIVITAL on this Work Order contact-NOT THE END CLIENT.

Failure to return parts, when requested, may result in the cancelation of this work order at no pay.

-Work performed outside the original Service Information detailed on this work order will not be compensated to the provider by PIVITAL on this Work Order unless it has been pre-approved by PIVITAL's Work Order manager. Requests by the provider for any payment increase must be documented in the messages tab of this work order, for any payment increase to be considered for approval. Additionally, pre-approval is required in work order messages for any expenses not in the work order when assignment occurs.

-By requesting this work order you agree to warranty all work performed on this work order to PIVITAL on this Work Order for a minimum period of 15-business days. Warranty period will begin from the date that PIVITAL on this Work Order has approved the work order electronically on the Field Nation platform. You will be required to repair all failed work, at no additional costs to PIVITAL on this Work Order within 3-business days of being notified of the warranty issue.

-You agree to provide PIVITAL on this Work Order with a 100% satisfaction guarantee. If you fail to fully complete the Services requested, then PIVITAL on this Work Order will not consider the work order complete.

-By accepting a work order you are stating that you have the expertise, tools and equipment required to perform the services in accordance with industry standards and practices.

-Acceptance of work order enters you into a legally binding contract to perform the services. By accepting this work order you agree not to solicit any business directly with PIVITAL's client that you are performing work for on this work order.

-The Spend Limit set on this work order is inclusive of all costs.

-If upon arrival you find that the work site is not ready for services you must contact the specified contact listed by PIVITAL on this Work Order prior to leaving the premises for further instructions. Failure to do so will be considered a 'No-Show' on your part.

-Deliverables are required within 12-hours of the completion of this work order. After the 12-hour threshold, a Late Closeout Penalty will be applied: 25% of labor

-Do not cancel appointments. In case of emergency contact PIVITAL on this Work Order directly. DO NOT CONTACT the End-User.

-Upon final project approval by PIVITAL on this Work Order, you will be paid by PIVITAL on this Work Order via Field Nation.