

Power Supply



File: psu.kicad\_sch

CM4 Connector 1



File: cm-conn1.kicad\_sch

CM4 Connector 2



File: cm-conn2.kicad\_sch

SATA Bridge





File: sata.kicad\_sch



Peripherals



File: peripherals.kicad\_sch




# /CM4 Connector 1












# /CM4 Connector 2



# /Peripherals







# /Power Supply



RP2040 power



+5v @ 3A PSU ( 7.5v-28v Input )



/SATA Bridge

