

Power Supply



File: psu.kicad_sch

CM4 Connector 1



File: cm-conn1.kicad_sch

CM4 Connector 2



File: cm-conn2.kicad_sch

SATA Bridge





File: sata.kicad_sch



Peripherals




File: peripherals.kicad_sch









/CM4 Connector 1




/CM4 Connector 2




/Peripherals




/Power Supply



RP2040 power



+5v @ 3A PSU (7.5v-28v Input)



/SATA Bridge

