Tabla A.1b Metales sólidos: variación de la conductividad térmica k [W/m K] con la temperatura (para la composición de los metales véase la tabla A.1a)

			A variation of the			Temperatura K			1000000		
9681	Metal	0001	200	300	400	500	600	800	1000	1200	1500
Aceros	al carbón						0.0	300	1000	1200	- FEET -
AISI	1010	8911	58è	64	59	54	49	**			
AISI	1042			52	50	48	45	39	31	10.10	I IA
A ICI	4130			43	42	41	40	37	29	26	30
Aceros	inoxidable	S		-1			40	37	31	27	31
AISI	302			15	17	19	20	22		GEDTAUL	20000
AISI	304		13	15	17	18	20	23	25		HILA
AISI	316		576	13	15	17	18	23	25		PULA
AISI	410		25	25	26	27	27	21	24	are.	1214
Alumin	io			-	100		21	29			TEA
Puro			237	237	240	236	231	210		4	u muta
Dura	luminio		138	174	187	188	231	218			0383
Alea	ción 195 n	noldeada		168	174	180	185		46.45	Commun	HIND A
Circoni						.00	103		moldeada	A STATE	
Puro			25	23	22	21	21	21	23	26	29
	aloy-4		13.3	14.2	15.2	16.2	17.2	19.2	21.2	23.2	29
Cobre	,						17.2	17.2	21.2	23.2	ing select
Puro			413	401	393	386	379	366	352	339	City 1
	ce comerci	ial	42	52	52	55	OC.	300	332	mornuo y	200
Lató			74	111	134	143	146	150			
_	alemana			116	135	145	147				MAP.
Estaño	alcination		73	67	62	60	Per	210			oftchi
			,,,	0.							COME!
Hierro	20		81	73	66	59	53	42	32	29	31
	deado		0.	51	44	39	36	27	23		Meto
				1				100			ishoust
Magnes			199	156	153	151	149	146			2010
Puro			199	150	84	0001				BANG	
	ción A8				04						
Níquel			106	91	80	72	66	68	72	76	83
Puro			105		13.5	15.1	17.0	20.5	24.0	27.6	
	nel-X-750		10.3	11.7	14	16	17	21			Nictor
Nicro	omo		319	13		304	298	284	270	255	· ·
Oro			323	317	311	419	412	396	379	361	Ela
Plata			420	429	425	72	73	76	79	83	90
Platino			73	72	72	33	31	77.75			Winds of
Plomo			37	35	34		59	59	60	61	62
Tantali	0	: 52	58	58	58	59	39	3,	00		arout
Titanio					200	20	19	19	21	22	25
Puro	080		25	22	20	20	010	17			(Aug)
	A1-4V			5.8				125	118	112	100
Tungste			185	174	159	146	137	125	110	112	2000