



FireDoor Nation LLC • (765) 480-4394 • firedoornation.com

Annual Fire Door Inspection Report

Redding Endoscopy Center

2179 Court St, Redding, CA 96001

Inspection Dates:
9/18/2026

Job ID: 980005



FireDoor Nation LLC • (765) 480-4394 • firedoornation.com

NFPA Code Reference

Fire door assemblies are visually inspected and functionally tested by qualified personnel. Inspection includes operation of the opening protective, closing and latching, clearances, labels, hardware, glazing, gasketing, auxiliary hardware and other observable conditions within the documented scope.

Note 1: This report records conditions observed at the time of inspection. Required ratings and final code interpretation remain subject to construction documents, the adopted code edition and the Authority Having Jurisdiction.

Reference standards:

NFPA 80 — Standard for Fire Doors and Other Opening Protectives

NFPA 101 — Life Safety Code, where applicable

NFPA 105 — Smoke Door Assemblies and Other Opening Protectives,
where applicable



FireDoor Nation LLC • (765) 480-4394 • firedoornation.com

Fire Door Report Summary

Total number of Doors	8
Passing Doors	8
Repaired/Passed Doors	0
Not Repaired Doors	0

Inspection Details

Total number of Doors	8
Passed Doors	8
Failed Doors	0

Client: Jamie Whitmoor-Pryer | Facility: Redding Endoscopy Center | Job ID: 980005
Single doors: 8 | Double doors: 0 | Door leaves: 8 | Compliance rate: 100%

980420						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	IT Room	Door Rating:	20 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							

980421						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	Bio-Hazard	Door Rating:	20 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							

980422						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	Soiled Linen	Door Rating:	20 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							

980423						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	Exit Route	Door Rating:	20 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							

980424						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	Clean Work Room	Door Rating:	45 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							

980425						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	Soiled Work Room	Door Rating:	45 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							

980426						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	Enviromental Services	Door Rating:	45 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							

980427						PASS	
No photo	Inspector:	Kelton Landrum	Building:	Main	Wall Rating:	Not Recorded	
	Inspection Date:	9/18/2026	Location:	General Storage	Door Rating:	45 Minutes	
			Floor:	1	Frame Rating:	Not Recorded	
Deficiency Detail							
Door passed inspection							



FireDoor Nation LLC • (765) 480-4394 • firedoornation.com

Inspection Report Certification

Prepared By:

Authorized for and on behalf of FireDoor
Nation LLC:

Kelton Landrum

Life Safety Inspector
FireDoor Nation LLC

Kelton Landrum

President
FireDoor Nation LLC

Customer Complaints or Report Corrections

Questions, complaints, or requests to correct inspection information may be submitted to kl@firedoornation.com. Include the facility name, Job ID, applicable Door ID and the specific item being questioned so the record can be reviewed against the inspection documentation.

This report is prepared for the client identified in the report and documents conditions observed during inspection of the listed openings. Results pertain only to the specific items evaluated and conditions reasonably observable at the time of inspection. This report does not establish the required fire-resistance rating of an opening where that determination depends on construction documents, adopted code provisions or an Authority Having Jurisdiction. Repairs, alterations and final acceptance remain subject to applicable listings, manufacturer requirements, adopted codes and standards and AHJ requirements.

Certification statement: The preparer certifies that this report is a true representation of the inspection information recorded for the listed openings.