


Pilotage incident review

This review covers the grounding of a pilot launch near buoy seven in November.

1. Sequence of events

The launch left the pilot station at dusk and grounded on a shoal outside the marked channel.



2. Findings

The signed witness statement on the previous page is a scan and has no text layer.

The review recommends a second lookout on every launch after sunset.