

# TCPIP stack and MRF24WB0MA/B and MRF24WG0MA/B Errata Detail

## **Applicability**

Products MRF24WB0MA/B and MRF24WG0MA/B Stack version v2012-08-22 and older PIC24 SSL Client only

## Problem

Current MLA releases only support 1024 SSL RSA key sizes. There is a requirement to be able to support 2048 SSL RSA key sizes

### Fix

Code changes are needed in 2 files (SSLClientSize.h and Mac.h).

#### Details (FW Code change)

Related file and function prototypes:

SSLClientSize.h
 Comment out the following line
 // #error "SSL Key sizes greater than 1024 only supported on the PIC32"

## 2. Mac.h

Modification is highlighted in red.

```
#elif defined(WF_CS_TRIS)

#define RAMSIZE 14170ul

#define TXSTART (RAMSIZE - ((4ul + MAX_PACKET_SIZE + 4ul)*1) - TCP_ETH_RAM_SIZE -

RESERVED_HTTP_MEMORY - RESERVED_SSL_MEMORY)

#define RXSTART (0ul)

#define RXSTOP ((TXSTART-2ul) | 0x0001ul)

#define RXSIZE (RXSTOP-RXSTART+1ul)

#define BASE_TX_ADDR (TXSTART + 4ul)

#define BASE_TCB_ADDR (BASE_TX_ADDR + ((MAX_PACKET_SIZE + 4ul)*1))

#define BASE_HTTPB_ADDR (BASE_TCB_ADDR + TCP_ETH_RAM_SIZE)
```