TAC AB / Schneider Vista-Xenta Firmware Attack Surface & Detection Brief

TAC AB / Schneider Vista-Xenta Firmware Attack Surface & Detection Brief

Scope: Access-verification pass only (2026-10-22). **No firmware was acquired and no CVE research pass was performed.** The legacy TAC Vista product-range page (`se.com/us/en/product-range/577-tac-vista/`) returns HTTP 200 with 1,416,739 bytes of product content plus authentication prompts, and the Schneider firmware download facet (`se.com/.../doc-group-type/...?docType=1555773-Firmware`) returns **HTTP 404** - the documented legacy facet path no longer resolves. **Access verdict: NOT PUBLICLY DOWNLOADABLE at the paths tested.** That is deliberately weaker than "confirmed login wall": it is a dead path on a live site, so a different, currently-valid Schneider route may exist and was not found this pass. No filename, byte count or SHA256 to report.

php2shell context: this brief's PHP determination was driven by CVE-2026-109618 / CVE-2026-109619 ("php2shell", CVSS 9.2, PHP 5.4+, emergency-patched 2026-10-21). Those two IDs are carried here **as supplied by the requester** - they were not independently corroborated against NVD/MITRE in this pass, and no vendor-specific CVE was invented to pair with them.

PHP finding: UNDETERMINED. TAC Vista/Xenta is a late-1990s-to-2000s LonWorks-era platform; Xenta 500/700/900 controllers expose an embedded web UI and the Xenta 911/913 gateways historically served HTML templates. Whether any of that used PHP cannot be established without a rootfs, and the era makes PHP and a bespoke CGI about equally plausible. **Not recorded as in-scope or out-of-scope for php2shell.**

Fleet exposure

252 devices in the ARNG OT census, function class *Building Automation/BMS*. Vendor-lineage complication: TAC AB was acquired by Schneider Electric and the line is discontinued in favour of EcoStruxure Building Operation - so current Schneider portals are unlikely to carry Xenta firmware at all, making an archive or dealer channel the realistic source.

What would close the PHP question

1. A live-device HTTP check against one of the 252 units - `X-Powered-By` header and `.php` handling. Fastest route, no vendor dependency.
2. Schneider's legacy/discontinued-product archive, if a valid path can be found - the one recorded in this project is now HTTP 404.
3. A third-party licence manifest, the technique that definitively answered Axis without its gated binary.

Status

Item	State
Public firmware download	**No** at paths tested - product page HTTP 200, firmware facet HTTP 404
Firmware acquired	No
Extraction run	N/A
PHP determination	**Undetermined**
CVE research pass	**Not performed** - no CVE IDs asserted here