

JOEL BOX 5" BASE 31/7/11 12:22 Page 1

KEY:

- PERFORATION RULE
 - CUT RULE
 - CREASE RULE



JOEL BOX 5" LID 02/08/11 16:22 Page 1

KEY:

- The diagram illustrates three types of fold lines used in paper engineering:

 - PERFORATION RULE**: Indicated by a dashed red horizontal line.
 - CUT RULE**: Indicated by a solid green horizontal line.
 - CREASE RULE**: Indicated by a dotted blue horizontal line.

