

PHASE 03

DP-DBBA Evaporation

QUICK OPERATOR GUIDE
Release 0.9.36 · Build 2026.08.11-r15

PURPOSE

Use the Phase 01 thickness ratio to calculate the DP-DBBA target, evaporate under controlled conditions and prepare the Keysight handoff to Phase 04.

WORKFLOW AT A GLANCE

1 · QUALIFY Oven stable near 200 C	2 · READY CK-1 T and average rate at target	3 · OPEN Open shutter physically and confirm	4 · EVAPORATE Reach ratio-derived CK-1 thickness	5 · HANDOFF Close shutter; 0.640 A, output ON
---------------------------------------	--	---	---	--

BEFORE STARTING ✓ Confirm or replace the Phase 01 thickness ratio shown by the launcher. ✓ Verify the physical shutter is closed and the external oven is ready. ✓ Check the temperature, rate and ratio-derived thickness targets.	KEY FACTS <table><tr><td>Shutter gate</td><td>Stable external oven + CK-1 temperature and average rate at target.</td></tr><tr><td>Automatic current cap</td><td>0.660 A default</td></tr><tr><td>Software hard stop</td><td>0.680 A</td></tr><tr><td>Temperature watchdog</td><td>255 C default</td></tr></table>	Shutter gate	Stable external oven + CK-1 temperature and average rate at target.	Automatic current cap	0.660 A default	Software hard stop	0.680 A	Temperature watchdog	255 C default
Shutter gate	Stable external oven + CK-1 temperature and average rate at target.								
Automatic current cap	0.660 A default								
Software hard stop	0.680 A								
Temperature watchdog	255 C default								
CONTROLS AND END STATES <table><tr><td>Finish Phase</td><td>Enabled at shutter-close stage: normal 0.640 A / OUTPUT ON handoff to Phase 04.</td></tr><tr><td>Abort / Safe Stop</td><td>Immediate CURR 0.000 and OUTPUT OFF; PID 0 C is requested afterwards.</td></tr></table>	Finish Phase	Enabled at shutter-close stage: normal 0.640 A / OUTPUT ON handoff to Phase 04.	Abort / Safe Stop	Immediate CURR 0.000 and OUTPUT OFF; PID 0 C is requested afterwards.	RUN DATA Saved under: Data Samples/DP-DBBA Evaporation Data/				
Finish Phase	Enabled at shutter-close stage: normal 0.640 A / OUTPUT ON handoff to Phase 04.								
Abort / Safe Stop	Immediate CURR 0.000 and OUTPUT OFF; PID 0 C is requested afterwards.								

SAFETY - VERIFY THE REAL HARDWARE

Finish is a live electrical handoff, not a shutdown. Before Phase 04, verify the shutter is closed and the Keysight reads approximately 0.640 A with OUTPUT ON.