



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Campbell Ridge SF (NC)(RAL)
Lot	00.0022
Street Address	113 Alden Way
Field Manager	Thomas Crews
	Eric Morphy
Reviewer	Tony Walldroff
Date	5/15/2026
Type	New Review
Product Type	Detached

Score	93.26%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	15
# of Items	26
Customer Exceptions	2
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Notes

NOTE: DO NOT SCORE mark CUSTOMER REQUESTS fireplace, cooktop, email Alex Lawson

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	3		0.25
Minor Paint	6		0.5
Minor Clean	6		0.5

Items


Room	Trade	Item	Description	Points	Initials	
Bath - 1st Floor Full	Drywall	1400 - Miscellaneous	Bow in drywall at ceiling above showerhead	0.25		
Bath - 1st Floor Full	Plumbing	700D - Damage	Drain cover tarnished	0.25		
Bath - Hall	Drywall	1400 - Miscellaneous	At top floor hall bath Bow in drywall at wall with shower next to toilet	0.25		
Bath - Hall	Framing	1030 - Out of Square/Level	At hall bath top floor trim is out of square at floor right of toilet	0.25		
Bath - Hall	Plumbing	700D - Damage	At top floor hall bath, scuffs and scratches at edge of tub across from toilet	0.25		
Bath - Owner's	Cabinets	1600D - Damage	Chip in left vanity cabinet right door	0.25		
Bath - Owner's	Interior_Trim	1510 - Not Pieced Together Well	Inconsistent gap between jamb/casing and floor between left and right side	0.25		
Bath - Owner's	Plumbing	700D - Damage	Scuffs,scratches on front of tub next to vanity	0.25		
Bedroom - Owner's	Interior_Trim	1500D - Damage	Baseboard damaged next to hinges outside owners bedroom	0.25		
Bedroom 2	Drywall	1410 - Major Drywal Issue	Bow in drywall at bedroom across from loft at top of stairs	0.25		
Bedroom 2	Interior_Trim	1510 - Not Pieced Together Well	Inconsistent gap between jamb/casing and floor between left and right side at BR at top of stairs	0.25		
Bedroom 3	Doors	50000D - Damage	FR bedroom closet door damaged , right door at bottom	0.25		
Exterior	Concrete_Flatwork	520 - Stain	Paint stains on right side of driveway	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Chip in garage slab outside of overhead door left side	0.25		
Exterior	Roofing	2000 - Miscellaneous	Lifted shingle at front of right dormer	0.25		
Exterior	Stairs_and_Rails	21005 - Missing Pieces	Railings not present at front porch, inconsistent with the rest of community	0.25		
Garage	Exterior_Trim	20000 - Miscellaneous	Gap between foundation and garage door, trim, exterior visible from inside garage	0.25		
Kitchen/Dinette	Appliances	1800D - Damage	Bend in rear corner, inconsistent gap between hood vent and wood surround right side	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Middle drawer face right of cooktop scratched	0.25		
Kitchen/Dinette	Cabinets	1630 - Drawer/Door Issue	Pull out shelves left of fridge, left cabinet binding, inconsistent operation with adjacent set	0.25		
Kitchen/Dinette	Cabinets	1620 - Missing Bumps	Missing bump for drawer across from pantry at Island	0.25		
Kitchen/Dinette	Doors	50040 - Door Rubs	Metal rubbing at strike plate for pantry door in kitchen	0.25		
Living	Framing	1020 - Out of Plumb	Wall at Cased opening to owners BR next to thermostat crooked	0.25		
Stairs/Hall	Framing	1050 - Bowed Wall	Bow in wall between front door and stairs , midway between	0.25		
Stairs/Hall	Framing	1050 - Bowed Wall	Bow in wall across from front door, next to entry to first floor bedrooms	0.25		

Stairs/Hall	Stairs_and_Rails	21040 - Rough Finish	Chip , rough edge in bottom of handrail at top of stairs	0.25		
-------------	------------------	----------------------	--	------	--	--

Customer Exceptions

Room	Trade	Item	Description	Adjustment	Initials	
Kitchen/Dinette	Appliances	1835 - Inoperable Appliance	DNS per Doug: customer provides propane for gas appliances			
Living	HVAC	600 - Miscellaneous	DNS per Doug: customer provides propane for gas appliances, fireplace not operating			

Scored Photos



Bath - 1st Floor Full
1400 - Miscellaneous
Bow in drywall at ceiling above showerhead



Bath - 1st Floor Full
700D - Damage
Drain cover tarnished



Bath - Hall
1030 - Out of Square/Level
At hall bath top floor trim is out of square at floor right of toilet



Bath - Hall
1400 - Miscellaneous
At top floor hall bath Bow in drywall at wall with shower next to toilet



Bath - Hall
700D - Damage
At top floor hall bath, scuffs and scratches at edge of tub across from toilet




Bath - Owner's
1510 - Not Pieced Together Well
Inconsistent gap between jamb/casing and floor between left and right side



Bath - Owner's
1600D - Damage
Chip in left vanity cabinet right door



Bath - Owner's
700D - Damage
Scuffs, scratches on front of tub next to vanity



Bedroom - Owner's
1500D - Damage
Baseboard damaged next to hinges outside owners bedroom



Bedroom 2
1410 - Major Drywal Issue
Bow in drywall at bedroom across from loft at top of stairs



Bedroom 2
1510 - Not Pieced Together Well
Inconsistent gap between jamb/casing and floor between left and right side at BR at top of stairs



Bedroom 3
50000D - Damage
FR bedroom closet door damaged , right door at bottom



Exterior
2000 - Miscellaneous
Lifted shingle at front of right dormer



Exterior
21005 - Missing Pieces
Railings not present at front porch, inconsistent with the rest of community



Exterior
500D - Damage
Chip in garage slab outside of overhead door left side



Exterior
520 - Stain
Paint stains on right side of driveway



Garage
20000 - Miscellaneous
Gap between foundation and garage door, trim, exterior visible from inside garage



Kitchen/Dinette
1600D - Damage
Middle drawer face right of cooktop scratched




Kitchen/Dinette
1620 - Missing Bumps
Missing bump for drawer across from pantry at Island




Kitchen/Dinette
1630 - Drawer/Door Issue
Pull out shelves left of fridge, left cabinet binding, inconsistent operation with adjacent set



Kitchen/Dinette
1800D - Damage
Bend in rear corner, inconsistent gap between hood vent and wood surround right side



Kitchen/Dinette
50040 - Door Rubs
Metal rubbing at strike plate for pantry door in kitchen




Living
1020 - Out of Plumb
Wall at Cased opening to owners BR next to thermostat crooked



Stairs/Hall
1050 - Bowed Wall
Bow in wall across from front door, next to entry to first floor bedrooms



Stairs/Hall
1050 - Bowed Wall
Bow in wall between front door and stairs , midway between



Stairs/Hall
21040 - Rough Finish
Chip , rough edge in bottom of handrail at top of stairs

Customer Exceptions



Kitchen/Dinette
1835 - Inoperable Appliance
DNS per Doug: customer provides propane for gas appliances



Living
600 - Miscellaneous
DNS per Doug: customer provides propane for gas appliances, fireplace not operating

Check List Item and Other Photos





