



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Essex Village SF (NC)(RAL)
Lot	00.0011
Street Address	30 Gerrard St
Field Manager	McLean Warren
	Matthew Wing
Reviewer	Joshua Chapman
Date	6/9/2026
Type	New Review
Product Type	Detached

Score	92.39%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	24
# of Items	25
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

4 to 5 to 9

Reschedules


Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	5		0.5
Minor Paint	14		1.5
Minor Clean	5		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Bath_Accessories	18050D - Damage	Scratches in right edge of mirror	0.25		
Bath - Hall	Plumbing	700D - Damage	Black marks on side of toilet tank cover	0.25		
Bath - Owner's	Flooring	1300 - Miscellaneous	Inconsistent gap at bottom left of shower door, grout is used for half	0.25		
Bath - Owner's	Plumbing	740 - Hot/Cold Reversed	Hot and cold reversed at right sink	0.25		
Bath - Powder	Drywall	1400D -Damage	Damage to drywall under sink	0.25		
Bath - Powder	Interior_Trim	1500D - Damage	Damage to baseboard to right of sink	0.25		
Bedroom 2	Interior_Trim	1500D - Damage	Damage to door trim at bottom strike side of entry door, middle left bedroom	0.25		
Exterior	Concrete_Flatwork	520 - Stain	Stains on back patio	0.25		
Exterior	Electric	852 - Exterior Penetrations Not Sealed	Outlet not sealed at left side of house at back	0.25		
Exterior	Landscaping	330 - Dying Sod/Seed/Shrubs/Tree	Dying sod in left and back yard	0.25		
Exterior	Landscaping	330 - Dying Sod/Seed/Shrubs/Tree	Dying sod in right and back yard	0.25		
Exterior	Plumbing	770 - House Penetrations Not Sealed	Penetration not sealed at soffit pipe on left side of house	0.25		
Exterior	Roofing	2020 - Plastic Wrappers Left On	Tape visible on flashing at right side of house at front porch roof	0.25		
Exterior	Siding	4000D - Damage	Stains on siding at gas line, left side of house	0.25		
Exterior	Siding	4030 - Soffit/Fascia Issues	Gap in soffit above middle columns at back porch	0.25		
Exterior	Siding	4030 - Soffit/Fascia Issues	Gap in soffit above SGD at back porch	0.25		
Foyer	Doors	50000D - Damage	Scratches in threshold at front door	0.25		
Foyer	Framing	1050 - Bowed Wall	Wall bows under outlet	0.25		
Foyer	Interior_Trim	1500D - Damage	Damage to door trim above front door	0.25		
Garage	Doors	50000D - Damage	Scratches in threshold at garage door	0.25		
Garage	Exterior_Trim	20060 - Ext. Trim Out of Plumb/Square	Kickboard not plumb under garage door	0.25		
Kitchen/Dinette	Appliances	1800D - Damage	Scratch in top of dishwasher	0.25		
Kitchen/Dinette	Interior_Trim	1560 - Out of plumb/square	Trim not square at bottom right of garage door	0.25		
Living	Framing	1050 - Bowed Wall	Wall bows, left of font hall way	0.25		
Stairs/Hall	Interior_Trim	1560 - Out of plumb/square	Out of square at top of stairs at knee wall	0.25		

Scored Photos



Bath - Hall
18050D - Damage
Scratches in right edge of mirror



Bath - Hall
700D - Damage
Black marks on side of toilet tank cover



Bath - Owner's
1300 - Miscellaneous
Inconsistent gap at bottom left of shower door, grout is used for half



Bath - Owner's
740 - Hot/Cold Reversed
Hot and cold reversed at right sink




Bath - Powder
1400D -Damage
Damage to drywall under sink



Bath - Powder
1500D - Damage
Damage to baseboard to right of sink



Bedroom 2
1500D - Damage
Damage to door trim at bottom strike side of entry door, middle left bedroom



Exterior
2020 - Plastic Wrappers Left On
Tape visible on flashing at right side of house at front porch roof



Exterior
330 - Dying Sod/Seed/Shrubs/Tree
Dying sod in left and back yard



Exterior
330 - Dying Sod/Seed/Shrubs/Tree
Dying sod in right and back yard



Exterior
4000D - Damage
Stains on siding at gas line, left side of house



Exterior
4030 - Soffit/Fascia Issues
Gap in soffit above middle columns at back porch



Exterior
4030 - Soffit/Fascia Issues
Gap in soffit above SGD at back porch



Exterior
520 - Stain
Stains on back patio



Exterior
770 - House Penetrations Not Sealed
Penetration not sealed at soffit pipe on left side of house



Exterior
852 - Exterior Penetrations Not Sealed
Outlet not sealed at left side of house at back



Foyer
1050 - Bowed Wall
Wall bows under outlet



Foyer
1500D - Damage
Damage to door trim above front door



Foyer
50000D - Damage
Scratches in threshold at front door



Garage
20060 - Ext. Trim Out of Plumb/Square
Kickboard not plumb under garage door



Garage
50000D - Damage
Scratches in threshold at garage door



Kitchen/Dinette
1560 - Out of plumb/square
Trim not square at bottom right of garage door



Kitchen/Dinette
1800D - Damage
Scratch in top of dishwasher



Living
1050 - Bowed Wall
Wall bows, left of front hall way



Stairs/Hall
1560 - Out of plumb/square
Out of square at top of stairs at knee wall

Check List Item and Other Photos



