



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Essex Village SF (NC)(RAL)
Lot	00.0070
Street Address	27 Gerrard St
Field Manager	Anthony Turner Jr
	Matthew Wing
Reviewer	Jason Weaver
Date	7/2/2026
Type	New Review
Product Type	Detached

Score	92.83%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	24
# of Items	21
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

7/3 to TBD, closed 7/3, sent email 6/26 to 7/2 email Anthony Turner

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	2		0.25
Minor Paint	11		1.5
Minor Clean	11		1.5


Items

Room	Trade	Item	Description	Points	Initials	
Attic	Doors	5000D - Damage	Weatherstripping on attic door is partially painted on left side and fully painted on right side	0.25		
Bath - Owner's	Cabinets	1600D - Damage	Top edge lower rail of cabinet under right sink is scratched near the right side	0.25		
Bath - Owner's	Ceramic	1210 - Grout Touchup	Hole in grout around bottom of beauty plate for shower head	0.25		
Bath - Owner's	Plumbing	701 - Fixture Improperly Installed	Drain cover is set crooked in shower	0.25		
Bath - Owner's	Plumbing	740 - Hot/Cold Reversed	Hot and cold are reversed on the shower	0.25		
Bath - Powder	Interior_Trim	1560 - Out of plumb/square	The baseboard on the right side of the toilet is bowed	0.25		
Bath - Powder	Plumbing	700D - Damage	Marks or scratches on the front edge of the sink in the middle	0.25		
Bedroom 1	Windows	13000D - Damage	Lower rail is gouged on right window in the middle in front right bedroom	0.25		
Exterior	Cleaning	1915 - Exterior Presentation	Tape left over weep holes of transom window on the right side of home	0.25		
Exterior	Roofing	2000D - Damage	Bent drip edge on right side of home left of the apex of the roof line	0.25		
Exterior	Siding	4000 - Miscellaneous	J channel over cut on top left corner of patio door	0.25		
Exterior	Siding	4000D - Damage	Metal wrap has sharp edge at top right corner over the front door	0.25		
Foyer	Doors	50020 - Weather Stripping Torn	Top piece of weatherstripping at front door is torn in the middle	0.25		
Garage	Doors	50000D - Damage	Door sweep for fire door entry is partially painted	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	The top corner edges of the false front under the sink and the top left corner of the the drawer to the right has the finish rubbed off	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	The top right corner of the drawer left of stove. The finish is rubbed off.		JW	7/2/2026
Kitchen/Dinette	Cabinets	1600D - Damage	The hole cut through the shelf in cabinet above microwave has rough edges around the hole	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	The front edge of shelf in lower cabinet right of stove is damaged	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	The top edge of the drawer, right of the stove is scratched above handle	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Scratch on cabinet door of upper cabinet over refrigerator right door, scratch on left side over handle	0.25		
Laundry Room	HVAC	660 - Ragged Drywall Visible Through Grate	Visible damaged drywall can be seen behind vent over laundry door on the laundry room side	0.25		


Scored Photos



Attic
50000D - Damage
Weatherstripping on attic door is partially painted on left side and fully painted on right side



Bath - Owner's
1210 - Grout Touchup
Hole in grout around bottom of beauty plate for shower head



Bath - Owner's
1600D - Damage
Top edge lower rail of cabinet under right sink is scratched near the right side




Bath - Owner's
701 - Fixture Improperly Installed
Drain cover is set crooked in shower



Bath - Owner's
740 - Hot/Cold Reversed
Hot and cold are reversed on the shower



Bath - Powder
1560 - Out of plumb/square
The baseboard on the right side of the toilet is bowed



Bath - Powder
700D - Damage
Marks or scratches on the front edge of the sink in the middle




Bedroom 1
13000D - Damage
Lower rail is gouged on right window in the middle in front right bedroom




Exterior
1915 - Exterior Presentation
Tape left over weep holes of transom window on the right side of home



Exterior
2000D - Damage
Bent drip edge on right side of home left of the apex of the roof line




Exterior
4000 - Miscellaneous
J channel over cut on top left corner of patio door



Exterior
4000D - Damage
Metal wrap has sharp edge at top right corner over the front door



Foyer
50020 - Weather Stripping Torn
Top piece of weatherstripping at front door is torn in the middle



Garage
50000D - Damage
Door sweep for fire door entry is partially painted



Kitchen/Dinette
1600D - Damage
Scratch on cabinet door of upper cabinet over refrigerator right door, scratch on left side over handle



Kitchen/Dinette
1600D - Damage
The top right corner of the drawer left of stove. The finish is rubbed off.



Kitchen/Dinette
1600D - Damage
The front edge of shelf in lower cabinet right of stove is damaged



Kitchen/Dinette
1600D - Damage
The hole cut through the shelf in cabinet above microwave has rough edges around the hole



Kitchen/Dinette
1600D - Damage
The top left corner of the false front under the sink and the top left corner of the drawer to the right has the finish rubbed off



Kitchen/Dinette
1600D - Damage
The top edge of the drawer, right of the stove is scratched above handle



Laundry Room
660 - Ragged Drywall Visible Through Grate
Visible damaged drywall can be seen behind vent over laundry door on the laundry room side

Check List Item and Other Photos





