



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Kensley Grove TH (NC)(RAL)
Lot	00.0049
Street Address	959 Kensley Grove Ln
Field Manager	Cameron McCarthy
	Eric Morphy
Reviewer	Diana Vedock
Date	5/29/2026
Type	New Review
Product Type	Townhouse

Score	90.00%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	12
# of Items	35
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	3	several areas patched, not painted	0.25
Minor Paint	5	cracking in corners, drips, scuffs	0.5
Minor Clean	4	several supply registers with debris in them, kitchen counter edges are scuffed	0.5

Items

Room	Trade	Item	Description	Points	Initials	
Attic	Cleaning	1910 - Construction Items Left Behind	on attic platform, left behind 2X4	0.25		
Bath - Hall	Bath_Accessories	18020 - Towel Bar Loose	at right wall connection, towel bar loose	0.25		
Bath - Hall	Plumbing	700D - Damage	top of toilet tank cover porcelain is scuffed	0.25		
Bath - Owner's	Bath_Accessories	18060 - Shower Enclosure Not Operating Properly	exterior door-with horizontal handle- is hard to operate in track	0.25		
Bath - Owner's	Cabinets	1670 - Overcut Hole for Pipes	at right vanity, overcut for drain line	0.25		
Bath - Owner's	Electric	810 - Crooked Outlet/Switch	GFCI right of mirror is not square/ level with mirror or splash block	0.25		
Bath - Owner's	Plumbing	701 - Fixture Improperly Installed (ex: not square)	in water closet, toilet seat is not secured	0.25		
Bath - Powder	Drywall	1400D -Damage	damage to drywall at supply line behind toilet	0.25		
Bedroom 2	Doors	50000D - Damage	front right bedroom, closet door damaged and repair effort made which is noticeable at top panel, interior hinge side	0.25		
Bedroom 2	Flooring	1350 - Carpet Installation	front right bedroom entry, hinges side jamb, carpet comes short and visible subfloor	0.25		
Exterior	Concrete_Flatwork	520 - Stain	front porch of home has staining present- foot prints, mud, other materials	0.25		
Exterior	Gutters_and_Downspout	3000D - Damage	right of front porch, gutter is damaged near bottom 3 ft	0.25		
Exterior	HVAC	600 - Miscellaneous	at rear, condenser unit lot level	0.25		
Exterior	Landscaping	300 - Miscellaneous	at rear, negative grade/ sinkage mid yard just off the nose of rear patio	0.25		
Exterior	Landscaping	300 - Miscellaneous	whole back of unit building, sod is not terminated where neighboring units have termination of sod	0.25		
Exterior	Landscaping	300D - Damage	front mulch disturbed at flower bed with cleanout	0.25		
Exterior	Roofing	2000 - Miscellaneous	left side of home, upper gable, raised shingles at overhang	0.25		
Exterior	Roofing	2000 - Miscellaneous	at garage detail roof, shingles at right side come short of starter strip	0.25		
Exterior	Siding	4040 - Drip Edge	at front of home, top gable drip edge right side is bent out of placement at gutter junction	0.25		
Exterior	Siding	4000D - Damage	at front, lower roof, the drip edge on front and right of garage roof detail has poor joints and is dented/ bent	0.25		
Exterior	Siding	4040 - Drip Edge	left side of garge roof detail drip edge is bent and has poor joint at front corner	0.25		
Exterior	Siding	4000D - Damage	over front porch portal, flashing mid run of header is damaged	0.25		
Exterior	Windows	13005 - Missing Pieces	whole home is missing screen install- is the only unit in whole building with no screens- not consistent for neighborhood	0.25		
Foyer	Doors	50010 - Hinge Screw/Pin Issues	at front door, noisy hinges	0.25		
Foyer	Interior_Trim	1560 - Out of plumb/square	at foyer coat closet, short wall, right side, trim and wall noticeably not square with flooring	0.25		

Garage	Interior_Trim	1510 - Not Pieced Together Well	at entry from garage, casing nails in top corner hinge side of door	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	left side of microwave, cabinet box is damaged	0.25		
Kitchen/Dinette	Cleaning	1920 - Trash and Debris	inside pantry closet, both plumbing boxes are not clean	0.25		
Kitchen/Dinette	Doors	50030 - Daylight Through Exterior Door Edge	at rear entry to home, water from sprinklers got into home under door sweep	0.25		
Kitchen/Dinette	Electric	855 - Other Installation Issue	prewire caps have differing screws each cap	0.25		
Kitchen/Dinette	Plumbing	701 - Fixture Improperly Installed (ex: not square)	fridge line trim box not square with base board/ crooked	0.25		
Laundry Room	Appliances	1830 - Installed Incorrectly	dryer is not leveled- rocks when operating	0.25		
Laundry Room	HVAC	660 - Ragged Drywall Visible Through Grate	visible drywall in transfer grill over doors	0.25		
Stairs/Hall	Closet_Shelving	17010 - Installation	linen closet in hall by front bedrooms, all shelves cut short- not full weight bearing of 1	0.25		
Stairs/Hall	Stairs_and_Rails	21000 - Miscellaneous	at second floor landing, the single step to second floor has a negative slope in towards riser	0.25		

Scored Photos



Attic
1910 - Construction Items Left Behind
on attic platform, left behind 2X4



Bath - Hall
18020 - Towel Bar Loose
at right wall connection, towel bar loose



Bath - Hall
700D - Damage
top of toilet tank cover porcelain is scuffed



Bath - Owner's
1670 - Overcut Hole for Pipes
at right vanity, overcut for drain line




Bath - Owner's
18060 - Shower Enclosure Not Operating Properly
exterior door- with horizontal handle- is hard to operate
in track




Bath - Owner's
701 - Fixture Improperly Installed (ex: not square)
in water closet, toilet seat is not secured




Bath - Owner's
810 - Crooked Outlet/Switch
GFCI right of mirror is not square/ level with mirror or
splash block



Bath - Powder
1400D - Damage
damage to drywall at supply line behind toilet



Bedroom 2
1350 - Carpet Installation
front right bedroom entry, hinges side jamb, carpet comes
short and visible subfloor



Bedroom 2
50000D - Damage
front right bedroom, closet door damaged and repair
effort made which is noticeable at top panel, interior
hinge side



Exterior
13005 - Missing Pieces
whole home is missing screen install- is the only unit in whole building with no screens- not consistent for neighborhood



Exterior
2000 - Miscellaneous
at garage detail roof, shingles at right side come short of starter strip




Exterior
2000 - Miscellaneous
left side of home, upper gable, raised shingles at overhang



Exterior
300 - Miscellaneous
at rear, negative grade/ sinkage mid yard just off the nose of rear patio



Exterior
300 - Miscellaneous
whole back of unit building, sod is not terminated where neighboring units have termination of sod



Exterior
3000D - Damage
right of front porch, gutter is damaged near bottom 3 ft



Exterior
300D - Damage
front mulch disturbed at flower bed with cleanout



Exterior
4000D - Damage
at front, lower roof, the drip edge on front and right of garage roof detail has poor joints and is dented/ bent



Exterior
4000D - Damage
over front porch portal, flashing mid run of header is damaged



Exterior
4040 - Drip Edge
at front of home, top gable drip edge right side is bent out of placement at gutter junction



Exterior
4040 - Drip Edge
left side of garge roof detail drip edge is bent and has poor joint at front corner



Exterior
520 - Stain
front porch of home has staining present- foot prints, mud, other materials



Exterior
600 - Miscellaneous
at rear, condenser unit lot level



Foyer
1560 - Out of plumb/square
at foyer coat closet, short wall, right side, trim and wall noticeably not square with flooring



Foyer
50010 - Hinge Screw/Pin Issues
at front door, noisy hinges



Garage
1510 - Not Pieced Together Well
at entry from garage, casing nails in top corner hinge side of door




Kitchen/Dinette
1600D - Damage
left side of microwave, cabinet box is damaged




Kitchen/Dinette
1920 - Trash and Debris
inside pantry closet, both plumbing boxes are not clean




Kitchen/Dinette
50030 - Daylight Through Exterior Door Edge
at rear entry to home, water from sprinklers got into home under door sweep



Kitchen/Dinette
701 - Fixture Improperly Installed (ex: not square)
fridge line trim box not square with base board/ crooked




Kitchen/Dinette
855 - Other Installation Issue
prewire caps have differing screws each cap



Laundry Room
1830 - Installed Incorrectly
dryer is not leveled- rocks when operating



Laundry Room
660 - Ragged Drywall Visible Through Grate
visible drywall in transfer grill over doors



Stairs/Hall
17010 - Installation
linen closet in hall by front bedrooms, all shelves cut
short- not full weight bearing of 1



Stairs/Hall
21000 - Miscellaneous
at second floor landing, the single step to second floor
has a negative slope in towards riser

Check List Item and Other Photos



