



New Review - Home Quality Review

Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Kensley Grove TH (NC)(RAL)
Lot	00.0053
Street Address	950 Kensley Grove Ln
Field Manager	Cameron McCarthy
	Eric Morphy
Reviewer	Terry Cureton
Date	5/15/2026
Type	New Review
Product Type	Townhouse

Score	93.50%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	13
# of Items	20
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	3		0.25
Minor Paint	7		1
Minor Clean	3		0.25

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Bath_Accessories	18050D - Damage	Hall bath mirror bracket is rusty, bottom left of mirror	0.25		
Bath - Hall	Plumbing	700D - Damage	Front edge of hall bath tub is scratched	0.25		
Bath - Owner's	Cabinets	1600D - Damage	Master bath vanity cabinet is chipped, front edge, left side	0.25		
Bath - Owner's	Cabinets	1600D - Damage	Chip in master bath vanity cabinet, front edge right side	0.25		
Bath - Owner's	Cabinets	1600D - Damage	Right rail of middle drawer is chipped, master vanity cabinet	0.25		
Bath - Owner's	Doors	50000D - Damage	Bottom right of master bath linen closet door jamb is chipped	0.25		
Bath - Owner's	Flooring	1300D - Damage	Scratch on flooring front of master vanity cabinet	0.25		
Bedroom - Owner's	Interior_Trim	1500D - Damage	Master bedroom closet door has nail protruding out, left middle side, closet side	0.25		
Bedroom 2	Interior_Trim	1500D - Damage	Top right of front left bedroom door casing is chipped, hallway side	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Mortar residue on front porch slab	0.25		
Exterior	Doors	50020 - Weather Stripping Torn	Weatherstripping is torn, bottom middle of back entry door, hinge side	0.25		
Exterior	Electric	855 - Other Installation Issue	Grounding wire anchor not engaged, at back meter base	0.25		
Exterior	Siding	4000D - Damage	Siding miscut, wavy line above back entry door and screw hole visible	0.25		
Family Room	Interior_Trim	1500D - Damage	Baseboard damaged, family room, right of stair landing	0.25		
Foyer	Doors	50020 - Weather Stripping Torn	Weatherstripping torn, top center of front entry door	0.25		
Garage	Foundation	420 - Exposed Ties/Clips	Sill foam visible garage wall, right side	0.25		
Kitchen/Dinette	Cabinets	1640 - Knob Installation	Lower cabinet left of range, handle is loose	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Upper cabinet right of corner cabinet is damaged, top front edge	0.25		
Kitchen/Dinette	Plumbing	790 - Minor Leak	Dishwasher leaks	0.25		
Stairs/Hall	Interior_Trim	1560 - Out of plumb/square	Baseboard out of square, front edge of stair kneewall, top of stairs	0.25		

Scored Photos



Bath - Hall
18050D - Damage
Hall bath mirror bracket is rusty, bottom left of mirror



Bath - Hall
700D - Damage
Front edge of hall bath tub is scratched



Bath - Owner's
1300D - Damage
Scratch on flooring front of master vanity cabinet



Bath - Owner's
1600D - Damage
Chip in master bath vanity cabinet, front edge right side




Bath - Owner's
1600D - Damage
Master bath vanity cabinet is chipped, front edge, left side




Bath - Owner's
1600D - Damage
Right rail of middle drawer is chipped, master vanity cabinet



Bath - Owner's
50000D - Damage
Bottom right of master bath linen closet door jamb is chipped



Bedroom - Owner's
1500D - Damage
Master bedroom closet door has nail protruding out, left middle side, closet side




Bedroom 2
1500D - Damage
Top right of front left bedroom door casing is chipped, hallway side



Exterior
4000D - Damage
Siding miscut, wavy line above back entry door and screw hole visible



Exterior
50020 - Weather Stripping Torn
Weatherstripping is torn, bottom middle of back entry door, hinge side



Exterior
855 - Other Installation Issue
Grounding wire anchor not engaged, at back meter base




Family Room
1500D - Damage
Baseboard damaged, family room, right of stair landing




Foyer
50020 - Weather Stripping Torn
Weatherstripping torn, top center of front entry door



Garage
420 - Exposed Ties/Clips
Sill foam visible garage wall, right side




Kitchen/Dinette
1600D - Damage
Upper cabinet right of corner cabinet is damaged, top front edge



Kitchen/Dinette
1640 - Knob Installation
Lower cabinet left of range, handle is loose



Kitchen/Dinette
790 - Minor Leak
Dishwasher leaks



Stairs/Hall
1560 - Out of plumb/square
Baseboard out of square, front edge of stair kneewall, top of stairs

Check List Item and Other Photos



