



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Mason Glenn SF (NC)(RAL)
Lot	00.0006
Street Address	101 Millview Way
Field Manager	McLean Warren
	Matthew Wing
Reviewer	Jason Weaver
Date	5/29/2026
Type	New Review
Product Type	Detached

Score	92.80%
Second Look, Paint & Drywall?	No
Possible Points	125.00
Adj. Possible Points	125.00
Tic Marks	27
# of Items	20
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	8
Builder Items	0
No Action Items	0

Notes

NOTE: DO NOT SCORE mark DIVISION EXCEPTIONS irrigation sprinkler heads, water, gas, generator power, hot water, brick under electric meter base, fireplace, cooktop, email Alex Lawson

Rescheduling Notes

27 to 29

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	2		0.25
Minor Paint	12		1.5
Minor Clean	13		1.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Plumbing	701 - Fixture Improperly Installed	Shower handle knot square to spout when turned off	0.25		
Bath - Owner's	Plumbing	761 - Missing Pieces	Shower enclosure missing glass panel left of shower door	0.25		
Bedroom 1	Interior_Trim	1500D - Damage	Damaged vinyl trim on exterior of lower sash at bottom left corner of left window in the middle left bedroom	0.25		
Bedroom 1	Windows	13000D - Damage	Damaged vinyl trim on exterior of lower sash at bottom left corner of left window in the middle left bedroom	0.25		
Dining Room	Doors	50020 - Weather Stripping Torn	Weatherstripping is torn on the hinge side of patio door slab above middle hinge	0.25		
Dining Room	Interior_Trim	1500 - Miscellaneous	Gap between floor and shoe mold on left wall under the right window near the single slab patio door	0.25		
Exterior	Cleaning	1920 - Trash and Debris	Debris on roof over garage, next to second story deck on front of home	0.25		
Exterior	Doors	50005 - Missing Pieces	Exterior trim around glass on second story deck door is partially caulked to door	0.25		
Exterior	Doors	50030 - Daylight Through Exterior Door Edge	Daylight comes through second story patio door at the top corner over the strike plate	0.25		
Exterior	Siding	4000 - Miscellaneous	Gap between metal wrap and beam above left column on second story deck	0.25		
Family Room	Doors	50000D - Damage	Center rail where sliding glass doors come together is scratched in the middle	0.25		
Family Room	Framing	1030 - Out of Square/Level	Small wall left of entry to primary bedroom is not square	0.25		
Foyer	Doors	50000D - Damage	Interior door sweep on front door is partially painted	0.25		
Garage	Exterior_Trim	20000D - Damage	Threshold to home entry is dented	0.25		
Kitchen/Dinette	Appliances	1835 - Inoperable Appliance	Cannot test dishwasher due to no water	1		
Kitchen/Dinette	Cabinets	1630 - Drawer/Door Issue	Cabinet doors over the refrigerator are not lined up on the bottom	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Gouge on front edge of range hood trim near the right side	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Top edge of drawer front is chipped on drawer left of sink	0.25		
Kitchen/Dinette	Framing	1030 - Out of Square/Level	Small wall right of pantry closet next to refrigerator is not square	0.25		
Loft	Electric	807 - Bulb Burned Out or Missing	Lightbulb burned out in light fixture of loft	0.25		

Division Exceptions

Room	Trade	Item	Description	Adjustment	Initials	
Exterior	Major_Item	Fireplace Inoperable	Fireplace is not working			
Exterior	Foundation	405 - Missing Parts and Pieces	Brick missing under electrical meter on left side of home			
Exterior	Plumbing	760 - Missing Fixture	Sprinkler system missing heads			
Exterior	Electric	800 - Miscellaneous	House running off generator			
Exterior	Exterior_Appointments	12000 - Miscellaneous	No gas meter for home on right side of house			
Kitchen/Dinette	Appliances	1835 - Inoperable Appliance	Cooktop is not operating			
Kitchen/Dinette	Major_Item	No Water to 1 Location	No water in entire home			
Kitchen/Dinette	Major_Item	No Hotwater	No hot water in entire home		JW	5/29/2026

Scored Photos



Bath - Hall
701 - Fixture Improperly Installed
Shower handle knot square to spout when turned off



Bath - Owner's
761 - Missing Pieces
Shower enclosure missing glass panel left of shower door



Bedroom 1
13000D - Damage
Damaged vinyl trim on exterior of lower sash at bottom left corner of left window in the middle left bedroom



Bedroom 1
1500D - Damage
Damaged vinyl trim on exterior of lower sash at bottom left corner of left window in the middle left bedroom



Dining Room
1500 - Miscellaneous
Gap between floor and shoe mold on left wall under the right window near the single slab patio door



Dining Room
50020 - Weather Stripping Torn
Weatherstripping is torn on the hinge side of patio door slab above middle hinge



Exterior
1920 - Trash and Debris
Debris on roof over garage, next to second story deck on front of home



Exterior
4000 - Miscellaneous
Gap between metal wrap and beam above left column on second story deck



Exterior
50005 - Missing Pieces
Exterior trim around glass on second story deck door is partially caulked to door



Exterior
50030 - Daylight Through Exterior Door Edge
Daylight comes through second story patio door at the top corner over the strike plate



Family Room
1030 - Out of Square/Level
Small wall left of entry to primary bedroom is not square



Family Room
50000D - Damage
Center rail where sliding glass doors come together is scratched in the middle



Foyer
50000D - Damage
Interior door sweep on front door is partially painted



Garage
20000D - Damage
Threshold to home entry is dented



Kitchen/Dinette
1030 - Out of Square/Level
Small wall right of pantry closet next to refrigerator is not square




Kitchen/Dinette
1600D - Damage
Gouge on front edge of range hood trim near the right side




Kitchen/Dinette
1600D - Damage
Top edge of drawer front is chipped on drawer left of the sink



Kitchen/Dinette
1630 - Drawer/Door Issue
Cabinet doors over the refrigerator are not lined up on the bottom



Kitchen/Dinette
1835 - Inoperable Appliance
Cannot test dishwasher due to no water



Loft
807 - Bulb Burned Out or Missing
Lightbulb burned out in light fixture of loft

Division Exceptions Photos



Exterior
12000 - Miscellaneous
No gas meter for home on right side of house



Exterior
405 - Missing Parts and Pieces
Brick missing under electrical meter on left side of home



Exterior
760 - Missing Fixture
Sprinkler system missing heads



Exterior
800 - Miscellaneous
House running off generator



Exterior
Fireplace Inoperable
Fireplace is not working



Kitchen/Dinette
1835 - Inoperable Appliance
Cooktop is not operating



Kitchen/Dinette
No Hotwater
No hot water in entire home



Kitchen/Dinette
No Water to 1 Location
No water in entire home

Check List Item and Other Photos



