



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Neill's Pointe (NC)(RAL)
Lot	00.0018
Street Address	177 Steel Springs Ln
Field Manager	Dustin Howard
	Eric Morphy
Reviewer	Joshua Chapman
Date	5/20/2026
Type	New Review
Product Type	Detached

Score	92.83%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	22
# of Items	23
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

14 to 18 to 19 no email to 20 no email

Reschedules


Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	5		0.5
Minor Paint	12		1.5
Minor Clean	5		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Owner's	Ceramic	1220 - Tile Installation Issue	Inconsistent gap at schluter strip at left side of shower tile, bathroom side	0.25		
Bath - Owner's	Ceramic	1220 - Tile Installation Issue	Inconsistent reveal at top of tile edge at top of shower wall , shower side	0.25		
Bath - Owner's	Plumbing	710 - Escutcheon Issue	Gap at escutcheon under left sink	0.25		
Bath - Powder	Interior_Trim	1500D - Damage	Damage to door trim at top of door	0.25		
Bath - Shared	Plumbing	700D - Damage	Black marks on edge of tub	0.25		
Bedroom 2	Framing	1030 - Out of Square/Level	Out of square at strike side of entry door, FR bedroom	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Damage to sidewalk at left of driveway	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Damage to back patio on back edge	0.25		
Exterior	Concrete_Flatwork	500 - Miscellaneous	Inconsistent finish on front porch under front door	0.25		
Exterior	Electric	860 - Damage	Ceiling light is stained at back porch	0.25		
Exterior	Exterior_Trim	20060 - Ext. Trim Out of Plumb/Square	Kickboard not square under SGD	0.25		
Exterior	Roofing	2020 - Plastic Wrappers Left On	Tape visible on flashing at left side of house, at back porch roof	0.25		
Exterior	Siding	4000D - Damage	Stains on siding at gas line at right side of house	0.25		
Garage	Electric	855 - Other Installation Issue	Gaps visible around ceiling lights in garage	0.25		
Kitchen/Dinette	Appliances	1800D - Damage	Damage to microwave bracket on right side	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Damage at left side of island	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Scratch in island drawer to left of sink	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Damage to bottom of upper cabinet, right of fridge	0.25		
Kitchen/Dinette	Ceramic	1220 - Tile Installation Issue	Gap in tile visible behind range	0.25		
Kitchen/Dinette	Framing	1050 - Bowed Wall	Wall bows at corner to right of SGD	0.25		
Kitchen/Dinette	Interior_Trim	1500D - Damage	Damage to baseboard, between windows in corner of dining area	0.25		
Kitchen/Dinette	Plumbing	700D - Damage	Scratches in sink	0.25		
Stairs/Hall	Framing	1030 - Out of Square/Level	Out of square at bottom left of powder room door	0.25		

Scored Photos



Bath - Owner's
1220 - Tile Installation Issue
Inconsistent gap at schluter strip at left side of shower tile, bathroom side



Bath - Owner's
1220 - Tile Installation Issue
Inconsistent reveal at top of tile edge at top of shower wall , shower side



Bath - Owner's
710 - Escutcheon Issue
Gap at escutcheon under left sink



Bath - Powder
1500D - Damage
Damage to door trim at top of door



Bath - Shared
700D - Damage
Black marks on edge of tub



Bedroom 2
1030 - Out of Square/Level
Out of square at strike side of entry door, FR bedroom



Exterior
20060 - Ext. Trim Out of Plumb/Square
Kickboard not square under SGD



Exterior
2020 - Plastic Wrappers Left On
Tape visible on flashing at left side of house, at back porch roof



Exterior
4000D - Damage
Stains on siding at gas line at right side of house




Exterior
500 - Miscellaneous
Inconsistent finish on front porch under front door



Exterior
500D - Damage
Damage to back patio on back edge



Exterior
500D - Damage
Damage to sidewalk at left of driveway



Exterior
860 - Damage
Ceiling light is stained at back porch



Garage
855 - Other Installation Issue
Gaps visible around ceiling lights in garage



Kitchen/Dinette
1050 - Bowed Wall
Wall bows at corner to right of SGD




Kitchen/Dinette
1220 - Tile Installation Issue
Gap in tile visible behind range



Kitchen/Dinette
1500D - Damage
Damage to baseboard, between windows in corner of dining area



Kitchen/Dinette
1600D - Damage
Damage at left side of island




Kitchen/Dinette
1600D - Damage
Damage to bottom of upper cabinet, right of fridge



Kitchen/Dinette
1600D - Damage
Scratch in island drawer to left of sink



Kitchen/Dinette
1800D - Damage
Damage to microwave bracket on right side



Kitchen/Dinette
700D - Damage
Scratches in sink



Stairs/Hall
1030 - Out of Square/Level
Out of square at bottom left of powder room door

Check List Item and Other Photos



