



New Review - Home Quality Review

Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	North First Street TH (NC)(RAL)
Lot	00.0015
Street Address	1274 Hammond Drive
Field Manager	Nickolas Cooke
	Matthew Wing
Reviewer	Heath Roach
Date	5/21/2026
Type	New Review
Product Type	Detached

Score	92.00%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	31
# of Items	18
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules


Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	10		1
Minor Paint	16		2
Minor Clean	5		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Drywall	1400 - Miscellaneous	Comer above hinge side of door not plumb.	0.25		
Bath - Owner's	Interior_Trim	1510 - Not Pieced Together Well	Right door jamb when in toilet room is cut short and filled with caulk.	0.25		
Bath - Powder	Plumbing	720 - Sink/Tub Not Holding Water	Sink does not hold water.	0.25		
Exterior	Cleaning	1915 - Exterior Presentation	House wrap visible above lower left window at rear patio.	0.25		
Exterior	Landscaping	300 - Miscellaneous	Sod is displaced at right side of driveway.	0.25		
Family Room	Doors	50030 - Daylight Through Exterior Door Edge	Daylight visible at top left comer of rear entry door.	0.25		
Family Room	Paint	1730 - Item Not Painted	Base shoe not finished painted at rear entry door.	0.25		
Foyer	Framing	1030 - Out of Square/Level	Short wall right of closet not square.	0.25		
Garage	Doors	50000D - Damage	House entry door has damage cold side by top hinge.	0.25		
Kitchen/Dinette	Appliances	1805 - Missing Pieces	Filters under microwave missing.	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	3rd cabinet left of microwave top shelf is damaged.	0.25		
Kitchen/Dinette	Framing	1030 - Out of Square/Level	Bar side of island is not square with flooring.	0.25		
Kitchen/Dinette	Interior_Trim	1500D - Damage	Nail sticking out of baseboard at bar side of island at left comer.	0.25		
Kitchen/Dinette	Plumbing	700D - Damage	Scratches in bottom of sink.	0.25		
Stairs/Hall	Interior_Trim	1510 - Not Pieced Together Well	Baseboard mitre at right of hall bath not pieced together well.	0.25		
Stairs/Hall	Interior_Trim	1510 - Not Pieced Together Well	Inconsistent gap between right casing and wall at upstairs hall closet.	0.25		
Stairs/Hall	Interior_Trim	1500D - Damage	Nail sticking out at right side step before second landing.	0.25		
Stairs/Hall	Stairs_and_Rails	21000 - Miscellaneous	Nail heads visible at riser at first landing.	0.25		

Scored Photos



Bath - Hall
1400 - Miscellaneous
Comer above hinge side of door not plumb.



Bath - Owner's
1510 - Not Pieced Together Well
Right door jamb when in toilet room is cut short and filled with caulk.



Bath - Powder
720 - Sink/Tub Not Holding Water
Sink does not hold water.



Exterior
1915 - Exterior Presentation
House wrap visible above lower left window at rear patio.




Exterior
300 - Miscellaneous
Sod is displaced at right side of driveway.



Family Room
1730 - Item Not Painted
Base shoe not finished painted at rear entry door.




Family Room
50030 - Daylight Through Exterior Door Edge
Daylight visible at top left corner of rear entry door.



Foyer
1030 - Out of Square/Level
Short wall right of closet not square.



Garage
50000D - Damage
House entry door has damage cold side by top hinge.



Kitchen/Dinette
1030 - Out of Square/Level
Bar side of island is not square with flooring.



Kitchen/Dinette
1500D - Damage
Nail sticking out of baseboard at bar side of island at left corner.



Kitchen/Dinette
1600D - Damage
3rd cabinet left of microwave top shelf is damaged.



Kitchen/Dinette
1805 - Missing Pieces
Filters under microwave missing.



Kitchen/Dinette
700D - Damage
Scratches in bottom of sink.



Stairs/Hall
1500D - Damage
Nail, sticking out at right side step before second landing.



Stairs/Hall
1510 - Not Pieced Together Well
Baseboard mitre at right of hall bath not pieced together well.



Stairs/Hall
1510 - Not Pieced Together Well
Inconsistent gap between right casing and wall at upstairs hall closet.



Stairs/Hall
21000 - Miscellaneous
Nail heads visible at riser at first landing.

Check List Item and Other Photos



