



New Review - Home Quality Review

Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Provisions at Courtland SF (NC)(RAL)
Lot	00.0046
Street Address	331 Flourishing Street
Field Manager	Brad McLoud
	Eric Morphy
Reviewer	Joshua Chapman
Date	5/20/2026
Type	New Review
Product Type	Detached

Score	93.48%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	19
# of Items	22
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	3		0.25
Minor Paint	13		1.5
Minor Clean	3		0.25

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Owner's	Ceramic	1220 - Tile Installation Issue	Inconsistent drywall reveal at right side of shower tile, bathroom side	0.25		
Bath - Owner's	Closet_Shelving	17000D - Damage	Damage to shelf, far right end of middle long shelfe	0.25		
Bath - Owner's	Framing	1030 - Out of Square/Level	Out of square at bottom left of shower door	0.25		
Bath - Powder	Bath_Accessories	18040 - Mirror Crooked	Mirror is not centered with sink and light	0.25		
Exterior	Brick_Stone_Stucco	5000D - Damage	Damage to brick at right side of garage door	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Damage to driveway under overhead door	0.25		
Exterior	Concrete_Flatwork	520 - Stain	Stains on left side of driveway	0.25		
Exterior	Doors	50005 - Missing Pieces	Threshold not attached at SGD	0.25		
Exterior	Exterior_Trim	20060 - Ext. Trim Out of Plumb/Square	Kickboard not square/ plumb under SGD	0.25		
Exterior	Landscaping	330 - Dying Sod/Seed/Shrubs/Tree	Dying sod in front yard	0.25		
Exterior	Landscaping	330 - Dying Sod/Seed/Shrubs/Tree	Dying sod in backyard	0.25		
Exterior	Siding	4000D - Damage	Stains on siding by gas line , left side of house	0.25		
Garage	Doors	50000D - Damage	Dent in garage door	0.25		
Garage	Exterior_Trim	20060 - Ext. Trim Out of Plumb/Square	Kickboard not square/plumb under door to house	0.25		
Garage	Interior_Trim	1500D - Damage	Nail sharps at top strike side of garage door	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Damage to back of cabinet above microwave	0.25		
Kitchen/Dinette	Doors	50005 - Missing Pieces	Missing screw cap at top of SGD	0.25		
Kitchen/Dinette	Flooring	1300 - Miscellaneous	Soft spot in flooring, to left of dishwasher	0.25		
Kitchen/Dinette	Flooring	1360 - Item Under Flooring	Bump under flooring at right of island	0.25		
Living	Framing	1050 - Bowed Wall	Wall bows, under thermostat	0.25		
Living	Framing	1050 - Bowed Wall	Wall bows, wall to right of windows	0.25		
Stairs/Hall	Interior_Trim	1500D - Damage	Damage to baseboard at stairs landing	0.25		

Scored Photos




Bath - Owner's
1030 - Out of Square/Level
Out of square at bottom left of shower door



Bath - Owner's
1220 - Tile Installation Issue
Inconsistent drywall reveal at right side of shower tile, bathroom side



Bath - Owner's
17000D - Damage
Damage to shelf, far right end of middle long shelf



Bath - Powder
18040 - Mirror Crooked
Mirror is not centered with sink and light



Exterior
20060 - Ext. Trim Out of Plumb/Square
Kickboard not square/ plumb under SGD



Exterior
330 - Dying Sod/Seed/Shrubs/Tree
Dying sod in backyard



Exterior
330 - Dying Sod/Seed/Shrubs/Tree
Dying sod in front yard



Exterior
4000D - Damage
Stains on siding by gas line , left side of house



Exterior
50005 - Missing Pieces
Threshold not attached at SGD



Exterior
5000D - Damage
Damage to brick at right side of garage door



Exterior
500D - Damage
Damage to driveway under overhead door



Exterior
520 - Stain
Stains on left side of driveway



Garage
1500D - Damage
Nail sharps at top strike side of garage door



Garage
20060 - Ext. Trim Out of Plumb/Square
Kickboard not square/plumb under door to house




Garage
50000D - Damage
Dent in garage door



Kitchen/Dinette
1300 - Miscellaneous
Soft spot in flooring, to left of dishwasher




Kitchen/Dinette
1360 - Item Under Flooring
Bump under flooring at right of island



Kitchen/Dinette
1600D - Damage
Damage to back of cabinet above microwave



Kitchen/Dinette
50005 - Missing Pieces
Missing screw cap at top of SGD



Living
1050 - Bowed Wall
Wall bows, under thermostat



Living
1050 - Bowed Wall
Wall bows, wall to right of windows



Stairs/Hall
1500D - Damage
Damage to baseboard at stairs landing

Check List Item and Other Photos



