



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek SF 30's (NC)(RAL)
Lot	00.0517
Street Address	1577 Briar Brook Lane
Field Manager	Daniel Morris
	Eric Morphy
Reviewer	Jason Weaver
Date	5/12/2026
Type	New Review
Product Type	Detached

Score	90.43%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	21
# of Items	33
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

8 to 12

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	2		0.25
Minor Paint	11		1.5
Minor Clean	8		1

Items


Room	Trade	Item	Description	Points	Initials	
Attic	Doors	50000D - Damage	Weatherstripping on attic access door is partially painted in various areas	0.25		
Bath - Hall	Bath_Accessories	18050D - Damage	Toilet paper holder is scratched	0.25		
Bath - Hall	Framing	1030 - Out of Square/Level	Half wall with toilet paper holder on it is not square to floor	0.25		
Bath - Hall	Plumbing	700D - Damage	Scratches on inside top edge of tub across from toilet	0.25		
Bath - Hall	Windows	13010 - Difficult to Open	Window will not open	0.25		
Bath - Owner's	Electric	807 - Bulb Burned Out or Missing	Bulb out in vanity light over left sink	0.25		
Bath - Owner's	Framing	1030 - Out of Square/Level	Small pony wall left of glass door to shower is not square	0.25		
Bath - Owner's	Framing	1076 - Floor Squeak	Floor squeak in closet in front of switch	0.25		
Bedroom - Owner's	Windows	13010 - Difficult to Open	The left window on the back wall is very difficult to open/close	0.25		
Bedroom 1	Electric	810 - Crooked Outlet/Switch	Light switch is crooked in the back right bedroom	0.25		
Bedroom 1	Framing	1076 - Floor Squeak	Floor squeak in back left corner of room, left of window in back right bedroom	0.25		
Bedroom 1	Windows	13005 - Missing Pieces	The window in the back right bedroom is missing a screen	0.25		
Dining Room	Windows	13010 - Difficult to Open	Both windows in the dining room are very hard to open and close	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Hole in front porch stoop in the middle	0.25		
Exterior	Concrete_Flatwork	500D - Damage	Several holes in the lead walk on the left edge	0.25		
Exterior	Siding	4000D - Damage	Corner board right of garage door is dented on the edge	0.25		
Exterior	Windows	13005 - Missing Pieces	Window in the middle of the left side of the house about 8 feet off the ground is missing a screen	0.25		
Family Room	Windows	13010 - Difficult to Open	The left window on the back wall is very difficult to open and close	0.25		
Family Room	Windows	13010 - Difficult to Open	Both windows on the left wall are very hard to open and close	0.25		
Foyer	Doors	50000D - Damage	Interior door sweep to front door is partially painted	0.25		
Foyer	Doors	50020 - Weather Stripping Torn	Hole in weatherstripping near the top on the strike plate side	0.25		
Garage	Doors	50000D - Damage	Interior door sweep to fire door is partially painted	0.25		
Garage	Doors	50000D - Damage	Fire door is gouged on inside edge near the middle hinge	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Nail sticking out on back of cabinet over refrigerator area on the left side	0.25		
Kitchen/Dinette	Interior_Trim	1510 - Not Pieced Together Well	Inconsistent gap between shoe mold and bead board on left side at front of island	0.25		
Kitchen/Dinette	Interior_Trim	1510 - Not Pieced Together Well	Inconsistent gap between shoe mold and left panel of island facing family room or stairs	0.25		

Kitchen/Dinette	Plumbing	701 - Fixture Improperly Installed (ex: not square)	Water valve for refrigerator is crooked	0.25		
Kitchen/Dinette	Plumbing	700D - Damage	Scratches in the bottom of the sink, left of the drain	0.25		
Laundry Room	Windows	13010 - Difficult to Open	Window will not open	0.25		
Loft	Electric	810 - Crooked Outlet/Switch	Outlet is crooked under right window on long wall	0.25		
Loft	Windows	13010 - Difficult to Open	Small window in loft on front wall will not open	0.25		
Stairs/Hall	Electric	810 - Crooked Outlet/Switch	Outlet on angled hallway, right of coat closet is not flush with drywall	0.25		
Stairs/Hall	Interior_Trim	1500D - Damage	The right edge of the cap board going from the the landing to the second floor is gouged	0.25		

Scored Photos




Attic
50000D - Damage
Weatherstripping on attic access door is partially painted in various areas



Bath - Hall
1030 - Out of Square/Level
Half wall with toilet paper holder on it is not square to floor




Bath - Hall
13010 - Difficult to Open
Window will not open




Bath - Hall
18050D - Damage
Toilet paper holder is scratched




Bath - Hall
700D - Damage
Scratches on inside top edge of tub across from toilet



Bath - Owner's
1030 - Out of Square/Level
Small pony wall left of glass door to shower is not square




Bath - Owner's
1076 - Floor Squeak
Floor squeak in closet in front of switch




Bath - Owner's
807 - Bulb Burned Out or Missing
Bulb out in vanity light over left sink




Bedroom - Owner's
13010 - Difficult to Open
The left window on the back wall is very difficult to open/close




Bedroom 1
1076 - Floor Squeak
Floor squeak in back left corner of room, left of window in back right bedroom



Bedroom 1
13005 - Missing Pieces
The window in the back right bedroom is missing a screen



Bedroom 1
810 - Crooked Outlet/Switch
Light switch is crooked in the back right bedroom



Dining Room
13010 - Difficult to Open
Both windows in the dining room are very hard to open and close




Exterior
13005 - Missing Pieces
Window in the middle of the left side of the house about 8 feet off the ground is missing a screen



Exterior
4000D - Damage
Corner board right of garage door is dented on the edge




Exterior
500D - Damage
Hole in front porch stoop in the middle



Exterior
500D - Damage
Several holes in the lead walk on the left edge




Family Room
13010 - Difficult to Open
Both windows on the left wall are very hard to open and close



Family Room
13010 - Difficult to Open
The left window on the back wall is very difficult to open and close



Foyer
50000D - Damage
Interior door sweep to front door is partially painted



Foyer
50020 - Weather Stripping Torn
Hole in weatherstripping near the top on the strike plate side



Garage
50000D - Damage
Fire door is gouged on inside edge near the middle hinge



Garage
50000D - Damage
Interior door sweep to fire door is partially painted



Kitchen/Dinette
1510 - Not Pieced Together Well
Inconsistent gap between shoe mold and bead board on left side at front of island




Kitchen/Dinette
1510 - Not Pieced Together Well
Inconsistent gap between shoe mold and left panel of island facing family room or stairs




Kitchen/Dinette
1600D - Damage
Nail sticking out on back of cabinet over refrigerator area on the left side




Kitchen/Dinette
700D - Damage
Scratches in the bottom of the sink, left of the drain



Kitchen/Dinette
701 - Fixture Improperly Installed (ex: not square)
Water valve for refrigerator is crooked




Laundry Room
13010 - Difficult to Open
Window will not open



Loft
13010 - Difficult to Open
Small window in loft on front wall will not open



Loft
810 - Crooked Outlet/Switch
Outlet is crooked under right window on long wall



Stairs/Hall
1500D - Damage
The right edge of the cap board going from the the landing to the second floor is gouged



Stairs/Hall
810 - Crooked Outlet/Switch
Outlet on angled hallway, right of coat closet is not flush with drywall

Check List Item and Other Photos



