



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek SF 40's (NC)(RAL)
Lot	00.0493
Street Address	524 Hipwood Dr.
Field Manager	Daniel Morris
	Eric Morphy
Reviewer	Antonio Daniels
Date	5/1/2026
Type	New Review
Product Type	Detached

Score	96.80%
Second Look, Paint & Drywall?	No
Possible Points	125.00
Adj. Possible Points	125.00
Tic Marks	8
# of Items	13
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	1		
Minor Paint	6		0.5
Minor Clean	1		0.25

Check List

Item	Description
------	-------------

Items

Room	Trade	Item	Description	Points	Initials	
Bath - 1st Floor Full	Interior_Trim	1500D - Damage	Shoe molding damaged behind toilet on right side	0.25		
Bath - Owner's	Electric	810 - Crooked Outlet/Switch	Outlet crooked on right side of mirror	0.25		
Bath - Owner's	Framing	1030 - Out of Square/Level	Wall not squared on left side of base cabinet	0.25		
Bedroom 1	Drywall	1400 - Miscellaneous	Bow in ceiling board above bedroom door - front right bedroom	0.25		
Dining Room	Framing	1030 - Out of Square/Level	Short wall not squared on right on dining room	0.25		
Dining Room	Framing	1050 - Bowed Wall	Bow in wall right side of kitchen entrance	0.25		
Exterior	Cleaning	1920 - Trash and Debris	Debris left in backyard on left side	0.25		
Exterior	Electric	810 - Crooked Outlet/Switch	Outlet crooked on back left corner of house	0.25		
Exterior	Siding	4000 - Miscellaneous	Aluminum flashing bent at back right corner of house	0.25		
Exterior	Siding	4000 - Miscellaneous	Aluminum flashing bent at front right dormer	0.25		
Foyer	Electric	810 - Crooked Outlet/Switch	Outlet crooked on right side of bathroom door	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Scratches on bottom side of shelf inside corner wall cabinet	0.25		
Stairs/Hall	Drywall	1400 - Miscellaneous	Bow in ceiling board above bathroom door	0.25		

Scored Photos



Bath - 1st Floor Full
1500D - Damage
Shoe molding damaged behind toilet on right side




Bath - Owner's
1030 - Out of Square/Level
Wall not squared on left side of base cabinet




Bath - Owner's
810 - Crooked Outlet/Switch
Outlet crooked on right side of mirror



Bedroom 1
1400 - Miscellaneous
Bow in ceiling board above bedroom door - front right bedroom




Dining Room
1030 - Out of Square/Level
Short wall not squared on right on dining room




Dining Room
1050 - Bowed Wall
Bow in wall right side of kitchen entrance



Exterior
1920 - Trash and Debris
Debris left in backyard on left side




Exterior
4000 - Miscellaneous
Aluminum flashing bent at back right corner of house




Exterior
4000 - Miscellaneous
Aluminum flashing bent at front right dormer



Exterior
810 - Crooked Outlet/Switch
Outlet crooked on back left corner of house



Foyer
810 - Crooked Outlet/Switch
Outlet crooked on right side of bathroom door



Kitchen/Dinette
1600D - Damage
Scratches on bottom side of shelf inside corner wall cabinet



Stairs/Hall
1400 - Miscellaneous
Bow in ceiling board above bathroom door

Check List Item and Other Photos



