



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek TH (NC)(RAL)
Lot	00.0653
Street Address	672 Sefton Park Dr.
Field Manager	Gabriel Rounds
	Jovanny Mastromihalis
	Eric Morphy
Reviewer	Bill Beard
Date	5/11/2026
Type	New Review
Product Type	Townhouse

Score	94.25%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	12
# of Items	18
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

7 to 8 to 11

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	1		0.25
Minor Paint	6		0.5
Minor Clean	5		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Electric	810 - Crooked Outlet/Switch	Gap between wall and switch plate	0.25		
Bath - Hall	Interior_Trim	1560 - Out of plumb/square	Shoe mould right of vanity not square with floor	0.25		
Bedroom - Owner's	Flooring	1300D - Damage	Paint on carpet behind entry door	0.25		
Bedroom - Owner's	Framing	1050 - Bowed Wall	Right side wall near bathroom door bowed	0.25		
Bedroom 1	Windows	13010 - Difficult to Open	Right front bedroom, left front window hard to open	0.25		
Exterior	Concrete_Flatwork	520 - Stain	Paint stains on left side of driveway near CO	0.25		
Exterior	Concrete_Flatwork	520 - Stain	Patio stained in front of utility room	0.25		
Exterior	Exterior_Trim	20060 - Ext. Trim Out of Plumb/Square	Trim at outlet on utility room wall not square	0.25		
Exterior	Exterior_Trim	20040 - Ext. Trim Not Pieced Together Properly	Gap between trim at board on front porch ceiling	0.25		
Exterior	Siding	4020 - J Channel/Trim Not Square	Inconsistent reveal between siding and j channel above garage door	0.25		
Exterior	Siding	4030 - Soffit/Fascia Issues	Gap between trim and soffit in front of front porch	0.25		
Exterior	Siding	4030 - Soffit/Fascia Issues	Gap between soffit and metal trim at right side of front porch	0.25		
Exterior	Siding	4030 - Soffit/Fascia Issues	Gap between front porch soffit and metal trim	0.25		
Foyer	Interior_Trim	1560 - Out of plumb/square	Shoe mould right of closet bowed	0.25		
Foyer	Interior_Trim	1510 - Not Pieced Together Well	Top right casing at garage door not flush	0.25		
Garage	Garage_Doors	9005 - Missing Pieces	Sharp screws exposed	0.25		
Kitchen/Dinette	Appliances	1830 - Installed Incorrectly	Dishwasher not square with front edge of counter top and door rubs cabinet at top right	0.25		
Kitchen/Dinette	Interior_Trim	1560 - Out of plumb/square	Shoe mould left of pantry cabinet not square	0.25		
Utility Room	Cleaning	TIC	Floor not scraped	0		

Scored Photos



Bath - Hall
1560 - Out of plumb/square
Shoe mould right of vanity not square with floor



Bath - Hall
810 - Crooked Outlet/Switch
Gap between wall and switch plate




Bedroom - Owner's
1050 - Bowed Wall
Right side wall near bathroom door bowed



Bedroom - Owner's
1300D - Damage
Paint on carpet behind entry door



Bedroom 1
13010 - Difficult to Open
Right front bedroom, left front window hard to open




Exterior
20040 - Ext. Trim Not Pieced Together Properly
Gap between trim at board on front porch ceiling



Exterior
20060 - Ext. Trim Out of Plumb/Square
Trim at outlet on utility room wall not square




Exterior
4020 - J Channel/Trim Not Square
Inconsistent reveal between siding and j channel above garage door



Exterior
4030 - Soffit/Fascia Issues
Gap between front porch soffit and metal trim



Exterior
4030 - Soffit/Fascia Issues
Gap between soffit and metal trim at right side of front porch



Exterior
4030 - Soffit/Fascia Issues
Gap between trim and soffit in front of front porch



Exterior
520 - Stain
Paint stains on left side of driveway near CO



Exterior
520 - Stain
Patio stained in front of utility room




Foyer
1510 - Not Pieced Together Well
Top right casing at garage door not flush



Foyer
1560 - Out of plumb/square
Shoe mould right of closet bowed



Garage
9005 - Missing Pieces
Sharp screws exposed



Kitchen/Dinette
1560 - Out of plumb/square
Shoe mould left of pantry cabinet not square



Kitchen/Dinette
1830 - Installed Incorrectly
Dishwasher not square with front edge of counter top and door rubs cabinet at top right



Utility Room
TIC
Floor not scraped

Check List Item and Other Photos



