



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Sidney Creek TH (NC)(RAL)
Lot	00.0656
Street Address	678 Sefton Park Dr.
Field Manager	Gabriel Rounds
	Jovanny Mastromihalis
	Eric Morphy
Reviewer	Bill Beard
Date	5/11/2026
Type	New Review
Product Type	Townhouse

Score	94.00%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	11
# of Items	19
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Rescheduling Notes

7 to 8 to 11

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	1		0.25
Minor Paint	6		0.5
Minor Clean	4		0.5

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Owner's	Cabinets	1600D - Damage	Top drawer separating on left side	0.25		
Bath - Owner's	Cabinets	1600D - Damage	Middle drawer chipped on right side	0.25		
Bath - Owner's	Ceramic	1220 - Tile Installation Issue	Front weep hole in shower blocked	0.25		
Bath - Owner's	Counter_Tops	40000D - Damage	Red spot in front of right side sink	0.25		
Exterior	Cleaning	TIC	Patio slab dirty	0		
Exterior	Exterior_Trim	20060 - Ext. Trim Out of Plumb/Square	Inconsistent reveal between kick board and front door threshold	0.25		
Exterior	Exterior_Trim	20000 - Miscellaneous	Gap between front porch ceiling and metal trim at porch beam	0.25		
Exterior	Plumbing	700D - Damage	Vent pipe on rear roof not plumb	0.25		
Exterior	Siding	4020 - J Channel/Trim Not Square	J channel on left side of front porch beam at garage wall not square	0.25		
Exterior	Siding	4020 - J Channel/Trim Not Square	J channel at back left on rake crooked	0.25		
Family Room	Windows	13010 - Difficult to Open	Could not open middle window	0.25		
Garage	Doors	50020 - Weather Stripping Tom	Weather strip tom at bottom hinge	0.25		
Garage	Foundation	400D - Damage	Hole in foundation below CO	0.25		
Garage	Garage_Doors	9020 - Installation	Power cord at opener hanging down	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Bottom frame at front of sink base chipped near middle	0.25		
Kitchen/Dinette	Framing	1030 - Out of Square/Level	Wall on left side of pantry closet not square	0.25		
Laundry Room	Doors	50010 - Hinge Screw/Pin Issues	Screw at top hinge of right side door not matching other screws	0.25		
Stairs/Hall	Interior_Trim	1500D - Damage	Baseboard at bottom of stairs on left side at post chipped	0.25		
Stairs/Hall	Stairs_and_Rails	21000 - Miscellaneous	Plug in top of handrail left side bottom of stairs	0.25		
Stairs/Hall	Stairs_and_Rails	21000 - Miscellaneous	Plug in top of handrail on right side at curb wall	0.25		
Utility Room	Cleaning	TIC	Floor not scraped	0		

Scored Photos



Bath - Owner's
1220 - Tile Installation Issue
Front weep hole in shower blocked




Bath - Owner's
1600D - Damage
Middle drawer chipped on right side



Bath - Owner's
1600D - Damage
Top drawer separating on left side



Bath - Owner's
40000D - Damage
Red spot in front of right side sink



Exterior
20000 - Miscellaneous
Gap between front porch ceiling and metal trim at porch beam



Exterior
20060 - Ext. Trim Out of Plumb/Square
Inconsistent reveal between kick board and front door threshold



Exterior
4020 - J Channel/Trim Not Square
J channel at back left on rake crooked



Exterior
4020 - J Channel/Trim Not Square
J channel on left side of front porch beam at garage wall not square



Exterior
700D - Damage
Vent pipe on rear roof not plumb



Exterior
TIC
Patio slab dirty



Family Room
13010 - Difficult to Open
Could not open middle window



Garage
400D - Damage
Hole in foundation below CO



Garage
50020 - Weather Stripping Torn
Weather strip torn at bottom hinge



Garage
9020 - Installation
Power cord at opener hanging down



Kitchen/Dinette
1030 - Out of Square/Level
Wall on left side of pantry closet not square




Kitchen/Dinette
1600D - Damage
Bottom frame at front of sink base chipped near middle



Laundry Room
50010 - Hinge Screw/Pin Issues
Screw at top hinge of right side door not matching other screws




Stairs/Hall
1500D - Damage
Baseboard at bottom of stairs on left side at post chipped



Stairs/Hall
21000 - Miscellaneous
Plug in top of handrail left side bottom of stairs



Stairs/Hall
21000 - Miscellaneous
Plug in top of handrail on right side at curb wall



Utility Room
TIC
Floor not scraped

Check List Item and Other Photos



