



New Review - Home Quality Review

Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	Spring Village TH (NC)(RAL)
Lot	00.0151
Street Address	38 Anastasia Steet
Field Manager	Dustin Howard
	Eric Morphy
Reviewer	Terry Cureton
Date	6/5/2026
Type	New Review
Product Type	Townhouse

Score	93.50%
Second Look, Paint & Drywall?	No
Possible Points	100.00
Adj. Possible Points	100.00
Tic Marks	11
# of Items	22
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	0
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall	3		0.25
Minor Paint	5		0.5
Minor Clean	3		0.25

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Hall	Plumbing	701 - Fixture Improperly Installed	Hall bath shower faucet handle is loose	0.25		
Bath - Hall	Plumbing	700D - Damage	Hall bath tub pan is stained	0.25		
Bath - Hall	Plumbing	700D - Damage	Scuff marks top front edge of hall bath tub	0.25		
Bath - Owner's	Cabinets	1600D - Damage	Master vanity toekick has paint overspray	0.25		
Bath - Powder	Drywall	1400D -Damage	Drywall corner is wavy and out of square, inconsistent finish, right side of pedestal sink, powder bath	0.25		
Bedroom - Owner's	Drywall	1400D -Damage	Master bedroom ceiling edge is wavy, inconsistent finish, above entry door	0.25		
Bedroom - Owner's	Interior_Trim	1500D - Damage	Master bedroom entry door casing has nail sharp, right side, hallway side	0.25		
Bedroom 2	Flooring	1300D - Damage	Front left bedroom, hole in carpet, left front side of closet door	0.25		
Exterior	Doors	50000D - Damage	Water heater shed, entry door is dented, top left	0.25		
Exterior	Exterior_Trim	20040 - Ext. Trim Not Pieced Together Properly	Inconsistent gap, top edge of garage door top trim,	0.25		
Exterior	HVAC	600D - Damage	Ext hvac unit set crooked on pad	0.25		
Exterior	Siding	4000D - Damage	Siding has paint overspray, back patio, left of gas meter	0.25		
Foyer	Doors	50050 - Door/Lock Needs Adjustment	Front entry door lock needs adjustment	0.25		
Foyer	Drywall	1400D -Damage	Foyer bump out, has wavy drywall corner, left side	0.25		
Garage	Doors	50000D - Damage	Garage entry door sweep has peeling paint, garage side	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Inconsistent gap, back edge of kitchen cabinet, right side of fridge opening	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Back skin of upper cabinet is chipped, above microwave	0.25		
Kitchen/Dinette	Cleaning	1920 - Trash and Debris	Debris in top drawer, left of dishwasher	0.25		
Kitchen/Dinette	Flooring	1300D - Damage	Glue residue at edge of shoemold, front of back entry door threshold	0.25		
Kitchen/Dinette	Interior_Trim	1560 - Out of plumb/square	Baseboard out of square, bottom left of pantry door	0.25		
Stairs/Hall	Framing	1030 - Out of Square/Level	Baseboard is out of square, bottom left side of stair kneewall, top of stairs	0.25		
Stairs/Hall	Interior_Trim	1560 - Out of plumb/square	Kneewall top cap is crooked and out of square , left side of stairs	0.25		

Scored Photos



Bath - Hall
700D - Damage
Hall bath tub pan is stained



Bath - Hall
700D - Damage
Scuff marks top front edge of hall bath tub



Bath - Hall
701 - Fixture Improperly Installed
Hall bath shower faucet handle is loose




Bath - Owner's
1600D - Damage
Master vanity toe kick has paint overspray




Bath - Powder
1400D -Damage
Drywall corner is wavy and out of square, inconsistent finish, right side of pedestal sink, powder bath



Bedroom - Owner's
1400D -Damage
Master bedroom ceiling edge is wavy, inconsistent finish, above entry door



Bedroom - Owner's
1500D - Damage
Master bedroom entry door casing has nail sharp, right side, hallway side



Bedroom 2
1300D - Damage
Front left bedroom, hole in carpet, left front side of closet door



Exterior
2004D - Ext. Trim Not Pieced Together Properly
Inconsistent gap, top edge of garage door top trim,




Exterior
4000D - Damage
Siding has paint overspray, back patio, left of gas meter




Exterior
50000D - Damage
Water heater shed, entry door is dented, top left



Exterior
600D - Damage
Ext hvac unit set crooked on pad



Foyer
1400D -Damage
Foyer bump out, has wavy drywall corner, left side



Foyer
50050 - Door/Lock Needs Adjustment
Front entry door lock needs adjustment



Garage
50000D - Damage
Garage entry door sweep has peeling paint, garage side



Kitchen/Dinette
1300D - Damage
Glue residue at edge of shoemold, front of back entry door threshold




Kitchen/Dinette
1560 - Out of plumb/square
Baseboard out of square, bottom left of pantry door




Kitchen/Dinette
1600D - Damage
Back skin of upper cabinet is chipped, above microwave




Kitchen/Dinette
1600D - Damage
Inconsistent gap, back edge of kitchen cabinet, right side of fridge opening



Kitchen/Dinette
1920 - Trash and Debris
Debris in top drawer, left of dishwasher



Stairs/Hall
1030 - Out of Square/Level
Baseboard is out of square, bottom left side of stair kneewall, top of stairs



Stairs/Hall
1560 - Out of plumb/square
Kneewall top cap is crooked and out of square , left side of stairs

Check List Item and Other Photos



