



Builder	DRB Group
Region	North Carolina
Division	Raleigh
Community	The Farm at Neill's Creek (NC)(RAL)
Lot	00.0031
Street Address	352 Peach Grove Way
Field Manager	Brad McLoud
	Eric Morphy
Reviewer	Tony Walldroff
Date	5/15/2026
Type	New Review
Product Type	Detached

Score	94.13%
Second Look, Paint & Drywall?	No
Possible Points	115.00
Adj. Possible Points	115.00
Tic Marks	11
# of Items	22
Customer Exceptions	0
Weather Exceptions	0
Division Exceptions	1
Builder Items	0
No Action Items	0

Reschedules

Tic Mark Items

Item	Tic Marks	Description	Points
Minor Drywall			
Minor Paint	9		1
Minor Clean	2		0.25

Items

Room	Trade	Item	Description	Points	Initials	
Bath - Owner's	Bath_Accessories	18060 - Shower Enclosure Not Operating Properly	Glass shower door hits end of towel bar when opening	0.25		
Bath - Owner's	Bath_Accessories	18050D - Damage	Towel bar finish scratched	0.25		
Bath - Owner's	Ceramic	1200D - Damage	Tile edge strip scratched left of toilet facing bathroom	0.25		
Bath - Owner's	Ceramic	1200D - Damage	Chip in tile top right corner of niche	0.25		
Bath - Owner's	Ceramic	1210 - Grout Touchup	Grout touchup needed inside top of niche	0.25		
Bath - Owner's	Ceramic	1210 - Grout Touchup	Inconsistent grout line under shower controls	0.25		
Bedroom 2	Doors	50050 - Door/Lock Needs Adjustment	Middle right bedroom closet doors do not sit flush when closed	0.25		
Bedroom 3	Windows	13020 - Latch issues	Front right bedroom, right window, right latch sticks when engaged	0.25		
Exterior	Cleaning	1915 - Exterior Presentation	Excess shingle pieces and debris on roof over front porch, visible from loft	0.25		
Exterior	Electric	810 - Crooked Outlet/Switch	Receptacle and trim crooked at front porch	0.25		
Exterior	Siding	4000 - Miscellaneous	Bulge in siding at bath vent left front side	0.25		
Garage	Doors	50030 - Daylight Through Exterior Door Edge	Daylight visible top corner handle side at garage	0.25		
Garage	Electric	810 - Crooked Outlet/Switch	Switch at entry door crooked	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Penetration from inside cabinet visible next to outlet	0.25		
Kitchen/Dinette	Cabinets	1600D - Damage	Tall cabinet door in corner right of range scratched	0.25		
Kitchen/Dinette	Framing	1050 - Bowed Wall	Bow in wall between laundry and kitchen at bottom of stairs	0.25		
Kitchen/Dinette	Plumbing	700D - Damage	Sink scratched right of disposal	0.25		
Laundry Room	HVAC	660 - Ragged Drywall Visible Through Grate	Rough cut drywall visible from hall above laundry room	0.25		
Living	Drywall	1410 - Major Drywall Issue	Bow in drywall return at top left window	0.25		
Loft	Windows	13020 - Latch issues	Window next to stairs left side latch sticking, not operating smoothly	0.25		
Stairs/Hall	Framing	1030 - Out of Square/Level	Out of Square at floor left side bottom of stair	0.25		
Stairs/Hall	Stairs_and_Rails	21020 - Rails Loose/Not Secured	Handrail loose at top of stairs, rubbing wall	0.25		

Division Exceptions


Room	Trade	Item	Description	Adjustment	Initials	
Kitchen/Dinette	Cabinets	1600D - Damage	Grouped: Penetration visible from inside cabinet next to outlet, right side			

Photos

Scored Photos



Bath - Owner's
1200D - Damage
Chip in tile top right corner of niche



Bath - Owner's
1200D - Damage
Tile edge strip scratched left of toilet facing bathroom




Bath - Owner's
1210 - Grout Touchup
Grout touchup needed inside top of niche




Bath - Owner's
1210 - Grout Touchup
Inconsistent grout line under shower controls




Bath - Owner's
18050D - Damage
Towel bar finish scratched



Bath - Owner's
18060 - Shower Enclosure Not Operating Properly
Glass shower door hits end of towel bar when opening




Bedroom 2
50050 - Door/Lock Needs Adjustment
Middle right bedroom closet doors do not sit flush when closed



Bedroom 3
13020 - Latch issues
Front right bedroom, right window, right latch sticks when engaged




Exterior
1915 - Exterior Presentation
Excess shingle pieces and debris on roof over front porch, visible from loft



Exterior
4000 - Miscellaneous
Bulge in siding at bath vent left front side



Exterior
810 - Crooked Outlet/Switch
Receptacle and trim crooked at front porch



Garage
50030 - Daylight Through Exterior Door Edge
Daylight visible top corner handle side at garage



Garage
810 - Crooked Outlet/Switch
Switch at entry door crooked



Kitchen/Dinette
1050 - Bowed Wall
Bow in wall between laundry and kitchen at bottom of stairs




Kitchen/Dinette
1600D - Damage
Penetration from inside cabinet visible next to outlet




Kitchen/Dinette
1600D - Damage
Tall cabinet door in Corner right of range scratched




Kitchen/Dinette
700D - Damage
Sink scratched right of disposal



Laundry Room
660 - Ragged Drywall Visible Through Grate
Rough cut drywall visible from hall above laundry room



Living
1410 - Major Drywal Issue
Bow in drywall return at top , left window



Loft
13020 - Latch issues
Window next to stairs left side latch sticking, not operating smoothly



Stairs/Hall
1030 - Out of Square/Level
Out of Square at floor left side bottom of stair



Stairs/Hall
21020 - Rails Loose/Not Secured
Handrail loose at top of stairs, rubbing Wall

Division Exceptions Photos



Kitchen/Dinette

1600D - Damage

Grouped: Penetration visible from inside cabinet next to outlet, right side

Check List Item and Other Photos



