



## Notes:

1. Wire color is a recommendation
2. Label harnesses with text given in diagram
3. Label every connector to match the designation in the drawing
4. Zip tie entire harness at 1ft increments where required.
5. Cover all cables with 1/2" or 1/8" black sleeving as required.

| 5 | 0.30 | m    | Wire, 0.5 mm <sup>2</sup> , YE                     |
|---|------|------|--|
| 4 | 0.30 | m    | Wire, 0.5 mm <sup>2</sup> , RD                     |
| 3 | 0.60 | m    | Wire, 0.5 mm <sup>2</sup> , BK                     |
| 2 | 1    |      | Connector, Molex 8981, female, 4 pins              |
| 1 | 4    |      | Connector, Crimp ferrule, 0.5 mm <sup>2</sup> , OG |
| # | Qty  | Unit | Description  |

|     |            |          |                 |          |            |          |                        |              |
|-----|------------|----------|-----------------|----------|------------|----------|------------------------|--------------|
|     |            |          |                 |          | Date       | Name     | some company           |              |
|     |            |          |                 | created  | 2023-03-29 | bob ross |                        |              |
|     |            |          |                 | reviewed | n/a        | n/a      | 8888 fancy street west |              |
|     |            |          |                 |          |            |          | test                   |              |
| a   | 2023-03-29 | bob ross | initial release |          |            |          | test-01-TUTORIAL05     |              |
| Rev | Date       | Name     | Changelog       |          |            |          |                        | Sheet 1 of 1 |