RIDGELINE HEATING & AIR
412 Foundry Road, Alder Creek, OR
(SYNTHETIC TEST DOCUMENT)

INVOICE #RHA-20961
Service date: November 2, 2026
Customer: Erik Halvorsen, Juniper Lane, Alder Creek

Work performed:
  Annual furnace safety inspection and tune-up $149.00
  Hot surface igniter replaced (was cracked) $138.00
  Furnace filter 16x25x1 MERV 11 (customer supplied) $0.00
  Labor, igniter replacement (0.5 hr) ..... $ 0.00 (covered by service plan)
  Subtotal $287.00
  Tax $25.40
  TOTAL $312.40

Technician: Marco D.
Notes: Heat exchanger looks good. Blower motor bearings starting to get noisy; recommend replacement within 1-2 years (est. $650).

PAID — Visa ending 4417, auth code 08812B, 11/02/2026 3:47 PM
Thank you for your business!